0					
	, Tnp3				
S. RECEY: TEMPIN REF. NS	INC 2300/519/ TAP3				
	IGNMENT				
ь					
Promi: Date:	Veh No: SHD 73055 Yr Regn: 2018, Dec.				
Simulated lost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Text) / Prime Mover /				
OD / TE / WS ITP RES / OD RES / EVA / INV / MV	Truck / Trailer or				
To Irospecive hide No:	Make: Myunder lawing c.c 1580.				
at Workship mis	Colour Blace A/C: Insured / Std / Ni / NA				
of	Sp.Reading 408570 T/Radio: Insured / Std / NI / NA				
rsured:	Eng/No:				
Policy No	C/No: 164185 CUKU 12=2011				
Claims No. MT/1208457-003	Gen. Cond: God / Fair / Poor / Burní				
Sum insued: Excess:	Steering: inorder / Jammed / Leaked / Burnt or				
(CilentiRecord)	Brake: inorder / Jammed / Leaked / Burnt or				
Make of Veh:	Modi: Will / S/Rim / STD A/Rim or				
	Tyre Size: 40 CF: 1910 C P : 1910				
(Policy Condition)	R: 4 1				
Remark: The veh had commenced its N/S 0/S repair at the time of inspection,	BOY BON EAROYA FOT PROTEINS TO SELECT MILES OF THE COURT				
	TOAD I ADKO DI				
Bal. or Market Value: IDA.C Absident Rport: Consistent? : Yes or No					
GIA / PR Seen: Consistent? : Yes or No					
Est. Repairs: 2 days Res.: Yes or No	D.O.A. D.O.I. 6/2/23				
Lurn Sum: % 3 Val.: Yes or No	Survey held at Comfort layer				
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear) 1-0/9 N/8 / U/C Rooffop or				
Vehicle: IN / O					
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.				
Date / Time Action / Instruction	· · · · · · · · · · · · · · · · · · ·				
	1				
Taufikh confirmed lump sum \$130	00 and 2 days				
(red, \$2098.84, 62%)					
Date/Time, File Pass to? : Prell. Report	Days Of Repair: 2				
1) 05/05/23 : Final Report	Resurvey No. of Trip: 1 Survey Fee:				
Date/Time, File Return to?	Transportation:				
Add F	Fee: Site Insp (\$)_s+Rs_si				
Republicant for the second sec	: Interview (\$) Photos				
Lump Sture / LB. Jr. ()	F. Tech trive (*) Others				
· · · · · · · · · · · · · · · · · · ·	VVeelend (#				

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHD7305J

Make : HYUNDAI Model : IONIQ(G3) Date: 06.02.2023 Insurance: INCOME

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Туре	Unit Price	Amount
1	REAR BUMPER COVER			\$459.40
10	REAR BUMPER CLIPS			\$22.00
1	REAR BUMPER CENTRE MOULDING ASSY			\$451.25
1	REAR BUMPER REINFORCEMENT			\$394.80
1	REAR BUMPER REINFORCEMENT BRACKET LH RH		\$138.10	\$276.20
2	REAR BUMPER SIDE BRACKET LH RH		\$55.80	\$111.60
1	ANTENNA SMARTKEY			\$40.50
1	REAR BUMPER FOG LAMP			\$201.50
1	REAR PANEL GARNISH		6	\$346.80
1	REAR PANEL			\$532.00
	SUB TOTAL			\$2,836.05
	LESS 20%			\$567.21
	DISCOUNTED TOTAL			\$2,268.84
	REAR NUMBER PLATE WITH TRIM COVER			\$50.00
	REAR BUMPER REVERSE SENSOR			\$180.00
			NETT	\$230.00
	Labour Charge			6400.00
	PANEL BEATING			\$400.00 \$300.00
	SPRAY PAINTING CHARGE			\$60.00
	CHK ALL LIGHTING/ WIRING			\$60.00
	TUFF KOTE			\$80.00
	REMOVE/REFIX REVERSE SENSOR TOTAL LABOUR			\$900.00
	TOTAL LABOUR			φ900.00
	ESTIMATE TOTAL			\$3,398.84

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tantilin 97495749

WP 6/2/230 430pm

L/S Boung affer report

tentiling clubants com

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary 'tem(s) must be resurveyed and is subject to final corroval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755 Workshops 205 Braddell Road Singapore 579701 59 Loyang Drive Singapore 508969 383 Sin Ming Drive Singapore 575717

Date/Time: 06.02.2023 14:20

Page: 1

ARC Repair TP(CLSO)1 eam:

JOB CARD Sales Order: 5812122 JC NO.305544766

OMER

IS

COMFORT TRANSPORTATION PTE LTD

7010045

OMER NO 383 SIN MING DRIVE

Singapore SINGAPORE 575717

65508755 (R)

(P)

DUNT CARD NO.

ĝis rei	REGN NO.: SHD7305J	MILEAGE	
	MAKE: HYUNDAI	FUEL E1/2F	
	MODELIONIQ(G2) 0	04.02.2023 19:10	
	YR OF MANU. 04.12.2018	TARGET DATE	
	CHASSIS CODE KMHC851CVKU122011	COMPLETION DATE/TIME:	


JOB DESCRIPTION

ccident Date: 04.02.2023 ATURE: 3P 04.02.2023 '

/NO

LABOR CODE

DESCRIPTION



KED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

10:

SHD7305J

YY

Exit Pass

Vehicle No.:

SHD7305J

Service Advisor

Signature/Date

Name of Service Advisor

1

urned to Service Reception upon collection

To be kept by Security Guard

SJ0G2326000E / JP Knights Pte Ltd ENTRY DATE & TIME: 06/02/2023 10:11 (SGT) SUBMITTED BY: Weine Chieng VERSION: 1 (06/02/2023 10:11 (SGT))



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

06/02/2023 10:11 (SGT) Date of Submission Reported by Driver Date of Accident 04/02/2023 14:30 (SGT) Exact Location of Accident Hougang Ave 6, Singapore SLIP ROAD BUANGKOK DRIVE Additional Location Information Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHD7305J

INSURED/POLICYHOLDER

Is company? Yes COMFORT TRANSPORTATION PTE LTD Name Of Registered Owner Company Reg No 1XXXXX821R Email Address fleetsafety@cdgtaxi.com.sg Mobile Phone No (Phone) +65-87907305 Alternative Phone No (Office) +65-65508768

VEHICLE PARTICULARS

Manufacturer Hyundai Model Ae ioniq Variant Exact purpose for which vehicle was being used at time of Private hire accident Are you claiming under your own insurance policy for repair to No - Claiming third party your vehicle?

Vehicle Category Taxi Transmission Auto CC 1580

INSURANCE COMPANY

Name of Insurance Company HSBC Life (Singapore) Pte. Ltd Policy Number / Cover Note Number VFX/P2419138

DRIVER

Name of Driver **NEO SOON KEONG** NRIC No SXXXX970C Date Of Birth 12/08/1969 Occupation Outdoor

Date Of Driving Pass 07/0
Driving experience 31 1
Gender Mal

Mobile Number
Alt. Phone Number

Email Address
Address

Address complement

Postcode

Is the driver the policyholder?

If No, Relationship of the Driver with the Insured

Does Driver Own Other Vehicles?

Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

07/03/1991

31 YEARS AND 11 MONTHS

Male

(Phone) +65-87907305

fleetsafety@cdgtaxi.com.sg

BLK 134 ANG MO KIO AVENUE 3 #03-1679

560134

No

Hirer

nirei

No

-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident
Weather Conditions
Road Surface

Collision - Head to Rear

Raining Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?

No Number of vehicles involved in the accident

Was anybody injured in the Accident?

No Was any injured conveyed to hospital by ambulance?

Was any other vehicle or property damaged?

Number of Passengers (Including Driver)

Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?

No Translator's name

Translator's name
Translator's Phone number
Translator's email
Original language used in the statement

DETAILS OF POLICE ACTION

Was the accident reported to the police?

Was notice of intended Prosecution given?

No
If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

ON 04/02/2023 AT ABOUT 1430HRS, I WAS STATIONARY IN VEHICLE A BEARING VEHICLE REGISTRATION PLATE, SHD7305J, ALONG SLIP ROAD OF HOUGANG AVENUE 6 TO BUANGKOK DRIVE. AS I WAS LOOKING AND WAITING FOR TRAFFIC ON MAJOR ROAD TO CLEAR, I FELT AN IMPACT FROM THE REAR AND REALISED VEHICLE B BEARING VEHICLE REGISTRATION PLATE, SKU8396P, HAD COLLIDED ONTO MY VEHICLE REAR BUMPER. NOBODY WAS INJURED AT THE TIME OF ACCIDENT.

ATTACHMENT(S)

Are accident photos available for attachment?

Was there any video captured by Car Camera?


Yes

Yes

Reasons for not uploading a video of the accident FILE IS NOT SUITABLE

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKU8396P
Vehicle Manufacturer Mazda
Vehicle Model Vehicle Variant Vehicle Colour -



Vehicle Category	Private car
Name of Driver	CHEN HANGYUAN
Passport No/FIN	GXXXX588X
Contact Number	(Phone) +65-87817777
Address	-
Address complement	_
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	_
No. Of Passenger (Including Driver)	1
	-

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please correctly report the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorized Driver.
- Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the center and to copies of the report being made available aforesald.
- 8. Consent under the Personal Data Protection Act (PDPA)

lunderstand, acknowledge, agree and consent that:

- (a) My insurer , my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims.
- (ii) investigating the accident and/or my claims.
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me.
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(Collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

FLASH ACCIDENT


FRO LATIFF

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time 04/02/2023 1730hrs

Witnessed by Reporting Centre

Sketch Plan



Describe Circumstances of the Accident

ON 04/02/2023 AT ABOUT 1430HRS, I WAS STATIONARY IN VEHICLE A BEARING VEHICLE REGISTRATION PLATE, SHD7305J, ALONG SLIP ROAD OF HOUGANG AVENUE 6 TO BUANGKOK DRIVE. AS I WAS LOOKING AND WAITING FOR TRAFFIC ON MAJOR ROAD TO CLEAR, I FELT AN IMPACT FROM THE REAR AND REALISED VEHICLE B BEARING VEHICLE REGISTRATION PLATE, SKU8396P, HAD COLLIDED ONTO MY VEHICLE REAR BUMPER. NOBODY WAS INJURED AT THE TIME OF ACCIDENT.

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time 04/02/2023 1730hrs

FLASH ACCIDENT Coldent REPORTING OFFICER

Witnessed by Reporting Centre Personnel