

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

income (Ushun)

Date: 06.02.2023

Time: 15:32:07

Page: 1

Jumari

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305544791
 REGN NO : SHA3833T
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 26.05.2016
 DATE/TIME IN : 06.02.2023 12:15
 ACCIDENT DATE : 06.02.2023

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-2322-A	BUMPER FRT COVER+	1	1,052.20	20.00	841.76	dl
0002 04-01-0103-0782-A	LAMP ASSY-HEAD RH#	1	1,388.00	20.00	1,110.40	cur
0003 04-01-0103-0640-G	BRACKET-FR BUMPER SIDE RH	1	44.80	20.00	35.84	dl
0004 04-01-0103-0573-A	PANEL-FENDER RH+	1	663.00	20.00	530.40	ht
0005 04-01-0103-0658-G	CAP ASSY-WHEEL HUB	1	217.20	20.00	173.76	ant
0006 03-01-0103-0098-G	WHEEL ASSY-STEEL	1	650.60	20.00	520.48	?
0007 04-01-0103-2934-G	GUARD ASSY-FRONT WHEEL R	1	174.90	20.00	139.92	dl

SUB-TOTAL : 3,352.56

JOB NATURE

0000 L	PANEL BEAT	600.00	525
0001 SP	SPRAYPAINT CHARGE	600.00	500
0002 17-01	CHECK ALL LIGHTING	50.00	30
0003 20-00	TUFF COAT ON AFFECTED PARTS.	50.00	30

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305544791
REGN NO : SHA3833T
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 26.05.2016
DATE/TIME IN : 06.02.2023 12:1
ACCIDENT DATE : 06.02.2023

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

SUB-TOTAL : 1,300.00

TOTAL : 4,652.56

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Tanphin 97495719
WP 6/2/23 2430pm
L/S Resurvey after repair
Tanphin C/kk auto.wm
2-3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Date/Time: 06.02.2023 15:23

Page : 1

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5812146

JC NO.305544791

OMER
IS COMFORT TRANSPORTATION PTE LTD
OMER NO 7010045
ESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)
(P)

REGN NO:
SHA3833T

MILEAGE

MAKE:
HYUNDAI

FUEL

E.....1/2.....F

MODEL
I-40

DATE/TIME IN
06.02.2023 12:15

YR OF MANU
26.05.2016

TARGET DATE

CHASSIS CODE
KMHLB41UMGU089988


COMPLETION DATE/TIME:

DUNT CARD NO.

JOB DESCRIPTION

Accident Date: 06.02.2023
ATURE: 3P.06.02.23/C

NO LABOR CODE DESCRIPTION



ED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

o.: **SHA3833T**

JU INCOME

Vehicle No.:

SHA3833T

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard