

Our Job Ref No : 305543327

Date 01.02.23

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156**FINALIZATION FORM**

To : LKK

Fax :

Attn : Mr IRFAN

Vehicle Reg No. SH 7841B

Date of Accident : 20.01.23

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill 703A **CHINA** --- **GBC4318T**
2. The finalized amount shall be:
 - (a) Spare Parts after List discount
 - (b) Labour Charges
 - Total for Part-By-Part Repair Cost**
 - (c.) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20% **\$3,500.00**
Final Lumpsum Repair cost
3. Estimated normal period for repairs: 4 working days.
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance. We confirm the estimates and finalized amount

Signature : 

Name : JUMANI

Tel : 62148315

Fax : 65468156

Signature : _____

Name : IRFAN

Date : _____

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
LTA Search Fee	26.75/2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks: