

ASS. REC. BY: Smg REF:

ASSIGNMENT

From: Date:
Estimated Cost:
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspoct Vehicle No:
at Workshop m/s
ol
Insured: CTI
Policy No.
Claims No.
Sum Insured: Excess:
(Client's Record)
Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:
IDAC Accident Rpt: Consistent? Yes or No
GIA / PR Scen: Consistent? Yes or No
Est. Repairs: 4 days Res: Yes or No
Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: Sh 78413 Yr Regn: 03/5/19
Type: M.Gar / M.Cycle / Bus / Van / Lorry / Tractor / Prime Mover /
Truck / Tractor or
Make: Hyundai Lonig
Colour: Blue AC: Insured / Std / NI / NA
Sp. Reading: T/Radio: Insured / Std / NI / NA
Eng/No:
C/No: Kmh CBSI CUKU 141862
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modl: NII / S/Rim / STD / Rim; or

Tyre Size: F: 195 / 65 R15
R: 195 / 65 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Westlane

Front	Rear
R/Bal. <u>6</u> mm	R/Bal. <u>5</u> mm
L/Bal. <u>6</u> mm	L/Bal. <u>5</u> mm
D.O.I. <u>20/1/23</u>	D.O.I. <u>25/1/23 330pm</u>

Survey held at Comfort

Des. of Damages: Fit / Keat / O/S / N/S / U/C / Reeltop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

1)
Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I: (\$)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation:

\$ + RS. \$1

Photos

Others

TOTAL

Date/Time: 25.01.2023 10:02

Page : 1

nam: ARC Repair TP(CLS0)1

JOB CARD Sales Order: 5727416

JC NO 305543327

OMER

S COMFORT TRANSPORTATION PTE LTD
OMER NO. 7010045
ESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)
(P)

REGN NO. SH 7841B

MILEAGE

MAKE: HYUNDAI

FUEL

MODEL IONIQ(G2)

DATE/TIME IN 25.01.2023 09:30

YR OF MANU 03.05.2019

TARGET DATE

CHASSIS CODE KMHC851CVKU141862

COMPLETION DATE/TIME

JUNT CARD NO.


JOB DESCRIPTION

Accident Date: 20.01.2023
ATURE: 3P.20.01.23

'NO

LABOR CODE

DESCRIPTION



KED & PASSED OUT BY:

CUSTOMER'S SIGNATURE

SERVICE ADVISOR

edgement Slip

Exit Pass

to:

SH 7841B

JU CHINA

Vehicle No.:

SH 7841B

Service Advisor

Signature/Date

Name of Service Advisor

Date

umed to Service Reception upon collection

To be kept by Security Guard