

Chana (Ysum)

Date: 25.01.2023

Time: 10:15:53

Page: 1

Jumani

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305543327
 REGN NO : SH 7841B
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G2)
 DATE OF REGN : 03.05.2019
 DATE/TIME IN : 25.01.2023 09:30
 ACCIDENT DATE : 20.01.2023

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2534-G	COVER-FR BUMPER#	1	481.10	20.00	384.88	Scr ✓
0002	04-01-0104-2361-G	MOULDING-FRONT BUMPER CTR	1	368.50	20.00	294.80	Scr ✓
0003	04-01-0104-2164-A	GRILLE ASSY-RADIATOR+#	1	1,409.10	20.00	1,127.28	Br ✓
0004	04-01-0104-2815-A	LAMP ASSY-HEAD LH#	1	2,110.30	20.00	1,688.24	Scr ✓
0005	04-01-0104-2282-G	COVER-RR BUMPER#	1	459.40	20.00	367.52	Scr R
0006	04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1	451.25	20.00	361.00	Cut ✓
0007	04-01-0104-2288-G	BEAM-RR BUMPER	1	394.80	20.00	315.84	X NN
0008	04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60	me ✓
0009	04-01-0104-2544-G	CAP-RR HOOK	1	98.80	20.00	79.04	? X NN
0010	09-01-0104-2132-G	UNIT ASSY-SMART CRUISE CO	1	3,061.40	20.00	2,449.12	? X NN

SUB-TOTAL 7,085.32

FT = 5103.80

20% = 1020.76

= 4083.04

24100%

SUB-TOTAL 0.00

5571.32

24100%

JOB NATURE

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour = 700

Paint = 500

check wire = 30

4 days

L/S

1 item 330pm

25/1/23