



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI23001616/Kqy3e2 Date: 16/03/2023	Code: AGI
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLP 1867H	Veh. Inspected	GBG 5942M	
Policy No.	P10815714R00	Coverage (\$)	0.00	
Claim No.	C10020491 /JT	Excess (\$)	0.00	
Assign From	FRAULEINE KHOO	Assign Date	14/02/2023	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	NISSAN NV200 (M)	c.c	1461	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	VSKYBAM20Z0146885	Colour	SILVER	
Odometer	202329 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	MICHELIN	9 mm	
L/H Front Tyre	195/65 R15	MICHELIN	9 mm	
R/H Rear Tyre	195/65 R15	MICHELIN	9 mm	
L/H Rear Tyre	195/65 R15	MICHELIN	9 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	13/02/2023	Inspection Date	14/02/2023	
Survey held at	EM SOLUTION PTE LTD 160 SIN MING DRIVE #03-18/19 SIN MING AUTOCITY SINGAPORE 575722			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	