

ASS. REC. BY: Smg REF: Q57

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspcd Vehicle No: _____
at Workshop m/s _____
of _____
Insured: II
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? Yes or No
GIA / PR Seen: _____ Consistent? Yes or No
Est. Repairs: 2 days Res: Yes or No
Lump Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: Shd 3537H Yr Reg: 28/09/21
Type: M/Car / M/Cycle / Bus / Van / Lorry / Trailer / Prime Mover /
Truck / Trailer or
Make: hyundai / only cc 1580
Colour Blue AC: Insured / Std / NI / NA
Sp. Reading 102407 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/Nr: KMH 6851 CVLV 194622
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Ind / Jammed / Leaked / Burnt or
Brake: Ind / Jammed / Leaked / Burnt or
Mod: NI / S/Rlm / STD / Rlm, or
Tyre Size: F: 195/65R15
R: 195/65R15
BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Westlake
Front Rear
R/Bal. 5 mm R/Bal. 5 mm
L/Bal. 5 mm L/Bal. 5 mm
D.O.A. 12/2/23 D.O.I. 14/2/23 2pm
Survey held at Conifort
Des. of Damages: Frt / Rear / O/S / M/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

1) _____
Date/Time, File Return to?

2) _____

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

\$ + RS. \$

Photos: _____

Others: _____

TOTAL

Job: ARC Repair TP(CLS0)1

JOB CARD Sales Order: 5852958

JG NC305545405

OWNER
IS COMFORT TRANSPORTATION PTE LTD
OWNER NO. 7010045
LESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)
(P)


REGN NO SHD3537H	MILEAGE
MAKE HYUNDAI	FUEL E 1/2 F
MODEL IONIQ(G3)	DATE/TIME IN 12.02.2023 22:20
YR OF MANU 28.09.2021	TARGET DATE
CHASSIS CODE KMHC851CVLU194622	COMPLETION DATE/TIME

DUNT CARD NO.

JOB DESCRIPTION

Accident Date: 12.02.2023
NATURE: 3P.12.02.23

'NO LABOR CODE DESCRIPTION



WORKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Check-out Slip

Exit Pass

No.: SHD3537H JU INDIA

Vehicle No.: SHD3537H

Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard