

A.S.S. REC. BY: Paul

REF:

CS3/HSB23001637/Rvp3

2431

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMR 8398Bat Workshop m/s ALPHA PERFORMANCEof 48, TAYLOR RD GLEN HOP-130Insured: HSBC

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 78K

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMR 8398B Yr Regn: 2020 JanType: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: HONDA FIT 1.34F CVT c.c. 1317Colour: GREEN A/C: Insured / Std / NI / NASp. Reading: 045119 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GK 33422578Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orMod: Nil / SRim / STD A/Rim orTyre Size: F: 195/55R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 13/02/23 D.O.I. 14/02/23Survey held at ALPHA PERFORMANCEDes. of Damages: FR / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	REPAIR LIMIT - 49K
	ESTIMATE RANGE OF REPAIR / no. of days - (3K-4K) / 7 days

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Workshop (\$

Survey Fee:

Transportation:

S + RS SI

Photos

Others

Repair Formed:

Lump Sum / L.E.H. (\$

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type: Singapore NRIC

Owner ID: 243I

Vehicle No.: SMR8398B

Vehicle to be Exported: No

Intended Deregistration Date: 15 Feb 2023

Vehicle Make: HONDA

Vehicle Model: FIT 1.3GF CVT

Primary Colour: Grey

Manufacturing Year: 2019

Engine No.: L13B3937066

Chassis No.: GK33422578

Maximum Power Output: 73.0 kW (97 bhp)

Open Market Value: \$15,655.00

Original Registration Date: 23 Jan 2020

First Registration Date: 23 Jan 2020

Transfer Count: 0

Actual ARF Paid: \$5,655.00

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 22 Jan 2030

PARF Rebate Amount: \$4,241.00

COE Expiry Date: 22 Jan 2030

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$35,010.00

COE Rebate Amount: \$24,281.00

Total Rebate Amount: \$28,522.00

The information contained herein is correct as at 15 Feb 2023

OK

Honda Fit 1.3A GF

Overview

Financial

Accessories

Similar

Research

Photos

Map

Price	\$79,800		
Depreciation [?]	\$10,990 /yr View models with similar depre	Reg Date	12-Feb-2020 (6yrs 11mths 27days COE left)
Mileage	44,388 km (14.7k /yr)	Manufactured [?]	2019
Road Tax [?]	\$578 /yr	Transmission	Auto
Dereg Value [?]	\$29,092 as of today (change)	OMV [?]	\$15,850
COE [?]	\$35,320	ARF [?]	\$5,850
Engine Cap	1,317 cc	Power	73.0 kW (97 bhp)
Curb Weight [?]	1,030 kg	No. of Owners [?]	1
Type of Vehicle	Hatchback		