

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS6/A 15 23001643/4943

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SNH 5016P

at Workshop m/s Sme 9-30

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: 20k

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$40k.

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 1.3.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: 27A 23900

Veh No: SNH 5016P

Yr Regn: 18/12/15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make: Mazda 3 hatchback

Colour: white

Sp. Reading: 83044

Eng/No: _____

C/No: JM 6BM 44A 860 323417

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 8 mm

R/Bal. 8 mm

L/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 10/2/23

D.O.I. 16/2/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

8/3/23 No second hand parts please want repair r/p
 7/7/23 2213.20 in hand AH ying checked \$612.60, 20%

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair: 3

1)

☐

Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

2)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

Photos

Others

Report Format: MERON

Lump Sum / I.B.I. (\$

2213.20

TOTAL

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, Singapore 417883

Tel: 6747 6106 (6 Lines) Fax: 6744 2368

Email: service@smemotor.com.sg Website: www.smemotor.com.sg

Co. & GST Reg. No: 201119451E

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	23/AL/OD-072 (02)
Policy No:	SP2004367750-01	Date of Loss:	10/02/2023
Vehicle Reg. No.:	SNH5016P	Driveable?	
Driver Age/Info:	57 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	NICOLE TAN KIM ENG	Contact No:	+6596229422
Driver:	NICOLE TAN KIM ENG		
Make/Model:	MAZDA 3, 1.5 (A)	Vehicle Reg. Date:	18/12/2015
Vehicle Colour:	WHITE		
Engine No:	P520328386	Chassis No:	JM6BM44A8G0323417
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Remarks:	VEHICLE NOT IN.		
Present Location:	SME MOTOR PTE LTD (KAKI BUKIT)		

Not Allowed
16/2/23
EXCESS NIL
by H/S
3 days.

COST OF CLAIMS

Parts	1,955.80
Miscellaneous Items	40.00
Labour	830.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$)	2,825.80
+ GST 8.00% (\$)	226.06
Nett Amount (\$)	3,051.86

2/28 22/3.20

This claim is handled by: CHIA PEI YING

LKK Auto Consultants hereby certify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 14 Feb 2023)

Parts: 144

MAZDA 3 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: SME Motor Pte Ltd/SNH5016P/14/02/2023 12:42

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT GRILLE <i>one</i>	0.00	0.00	*380.00 F
2	1		*FRT GRILLE CENTER LOGO <i>scr</i>	0.00	0.00	*35.00 F
3	2		*FRT GRILLE CHROME <i>one/scr</i>	0.00	0.00	*250.00 F
4	2		*GRILLE REAR BRACKET <i>711 X</i>	0.00	0.00	*56.00 F
5	6		*GRILLE CLIP <i>scr</i>	0.00	0.00	*15.00 F
6	1		*GRILLE TOP GARNISH <i>72/ae</i>	0.00	0.00	*195.00 F
7	6		*GRILLE TOP GARNISH RIVETS <i>scr</i>	0.00	0.00	*33.00 F
8	1		*FRT BUMPER <i>2e/1012</i>	0.00	0.00	*490.00 F
9	10		*FRT BUMPER CLIP <i>scr</i>	0.00	0.00	*20.00 F
10	1		*FRT BUMPER REINFORCEMENT <i>ex</i>	0.00	0.00	*260.00 F
11	2		*FRT BUMPER SCREW COVER <i>ms</i>	0.00	0.00	*44.00 F

F=Franchise part.

Sub Total (S\$)

1,778.00

+ Margin on L,N Items 10.00% (S\$)

177.80

Total Parts (S\$)

1,955.80

SME Motor Pte Ltd/SNH5016P/14/02/2023 12:42. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

P-1462
102
1608.20

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	NUMBER PLATE <i>surf</i>	35 40.00
Sub Total (S\$)			40.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	WIRE CHECKING	New	20 30.00
2	LABOUR CHARGE	New	250 400.00
3	SPRAY PAINTING (PEARL)	New	300 400.00
Gross Labour Cost (S\$)			830.00

SME Motor Pte Ltd/SNH5016P/14/02/2023 12:42. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

CHIN HON MOTOR & TRADING PTE. LTD.

定貨單
ORDER No

SNH 5016P

蒙採定下列各貨

Date. 17/2/2023

Issued by
經手人