Adjuster Report 3/30/23, 3:20 PM

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/III23001647/ANY3E2

Date:

30/03/2023

REFERENCE

Handling Insurer:

India International Insurance Pte Ltd

Policy No:

Claimant Vehicle No:

SMK7532Z

Insured Vehicle No:

SMM1381X

Claim No:

Date of Loss:

10/02/2023

Nature of Claim:

TP

N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

HONDA JAZZ, 1.5 VTIR CVT ABS D/AIRBAG

Engine No:

Yes

L15B31000443

Make & Model:

2WD (A)

SMK7532Z

30/03/2015 (Man. Year: 2015) Chassis No: JHMGK5850FX202718

Reg. Date: Colour:

Red

Odometer:

132278 km

Engine Capacity:

1498 cc Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes

Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: Front Left Side: Front Right Side: 185/55 R16 Yokohama 6 mm

Yokohama 6 mm

Rear Tyre Size: Rear Left Side: Rear Right Side:

Yokohama 6 mm Yokohama 6 mm

185/55 R16

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		0.00	0.00	0.00	
Miscellaneous Items		0.00	0.00	0.00	
Labour		0.00	0.00	0.00	
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	0.00	0.00	0.00	
	Approved Total (Overridden) (S\$)		4,600.00		
	Nett Amount (S\$)	0.00	4,600.00	-4,600.00	

INSPECTION

Date Inspected:

Date of Assignment:

14/02/2023

14/02/2023

Inspected At:

YSK Auto Workshop (HQ)

1 Kaki Bukit Avenue 6 @ AutoBay, #01-71

Singapore 417883

Estimated Period of Repair:

6.0 days

ADRIAN LING Adjuster:

Manager:

HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 30 Mar 2023)

Parts: 144 HONDA JAZZ 1.5 VTIR CVT ABS D/AIRBAG 2WD (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMK7532Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

3/30/23, 3:20 PM Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >