

A&S, PLO. BY:

REF:

CS3/SPF23001664/Dwy³

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 2 days Res.: Yes or NoLum Sum: P/P % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLH 6444D Yr Regn: - /

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel c.c. 1496Colour: Brown A/C: Insured / Std / NI / NASp. Reading: 176438 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RU31213729

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60 R16R: —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Towrador

Front _____ Rear _____

R/Bal. S mm R/Bal. S mmL/Bal. S mm L/Bal. S mmD.O.A. 08/02/2023 D.O.I. 15/02/2023Survey held at LKK office Paya Ubi

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SPF PLS <u>Just bump - low</u> <u>Just grille top garnish</u> <u>Just bonnet - low</u> <u>\$578.00</u>
	<u>Front bumper, just bonnet and just grille top garnish found</u> <u>with scratch & marks. Cannot polish off.</u> <u>\$732.00</u>
	<u>Spray Painting of damaged parts</u> <u>\$400.00</u> <u>with 2 days.</u>
	Repair Range = 400 - 500

Date/Time, File Pass to?

02/03/2023

1) Typist

Date/Time, File Return to?

2)



: Prel. Report



: Final Report

Days Of Repair: 02

Resurvey No. of Trip: _____

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Invs (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

Report Formset: DAR

I certify I am a P.P. in the

\$203.00