

(08/11/13) wef

ASS. REC. BY: Conn

REF:

CS/HLA 23001671/Rcny3

2804

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SML 5514Rat Workshop m/s WAH HONG MOTORSof 38, TONG LUN RD EAST #01-57Insured: HLA

Policy No.

Claims No.

Sum Insured:

Excess:

300

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: 58K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SML 5514RYr Regn: 2017 / MARType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: NISSAN QASHQAI 1.2 DIG-T cc 1197Colour: BROWNA/C: Insured / Std / NI / NASp. Reading: 72970T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: SJN PEA J1141788100Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

215/60R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 11/02/23D.O.I. 16/02/23

Survey held at

WAH HONGDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 27K26/7/23 Repair finalised LS \$4700; 6 days with repainer. (Red 4918.25, 51%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☒

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

Report Format: ODLump Sum / I.B.I: (\$ 4700)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	250G
Vehicle Details	
Vehicle No.:	SLM5514R
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Feb 2023
Vehicle Make:	NISSAN
Vehicle Model:	QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR
Primary Colour:	Brown
Manufacturing Year:	2016
Engine No.:	HRA2337835A
Chassis No.:	SJNFEAJ11U1788100
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$18,725.00
Original Registration Date:	31 Mar 2017
First Registration Date:	31 Mar 2017
Transfer Count:	0
Actual ARF Paid:	\$13,725.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Mar 2027
PARF Rebate Amount:	\$9,607.00
Intended COE Rebate Details	
COE Expiry Date:	30 Mar 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,765.00
COE Rebate Amount:	\$21,373.00
Total Rebate Amount:	\$30,980.00

The information contained herein is correct as at 13 Feb 2023

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	13/02/2023 10:22 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	11/02/2023 16:05 (SGT)
Exact Location of Accident	270 Upper Bukit Timah Rd, Singapore 588211
Additional Location Information	270 UPPER BUKIT TIMAH RD, TRAFFIC JUNCTION
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLM5514R
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	LIM JUNWEN, LESLIE
NRIC No	SXXXX250G
Email Address	EILSEL_MIL@HOTMAIL.COM
Mobile Phone No	(Phone) +65-81137178
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Nissan
Model	Qashqai
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1197

INSURANCE COMPANY

Name of Insurance Company	HL Assurance Pte Ltd
Policy Number / Cover Note Number	MP309471

DRIVER

Name of Driver	LIM JUNWEN, LESLIE
NRIC No	SXXXX250G
Date Of Birth	06/07/1985
Occupation	Indoor

Date Of Driving Pass	17/08/2005
Driving experience	17 YEARS AND 6 MONTHS
Gender	Male
Mobile Number	(Phone) +65-81137178
Alt. Phone Number	-
Email Address	EILSEL_MIL@HOTMAIL.COM
Address	BLK 487C CHOA CHU KANG AVE 5
Address complement	#11-113
Postcode	683487
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	5
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

PASSENGER 1

Name	NATALIE
Gender	Female

PASSENGER 2

Name	CALISTA
Gender	Female

PASSENGER 3

Name	POH LIAN
Gender	Female

PASSENGER 4

Name	RICHARD
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN & SUMMARY

Are accident photos available for attachment? Yes
Was there any video captured by Car Camera? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKM6868Y
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

Describe Circumstance of the Accident

On 11/02/2023 (Sat) around 4.05pm, I was driving my Vehicle SLM5514R along Upper Bukit Timah Road toward Beauty World. When my vehicle SLM5514R was near the traffic junction, vehicle SKM6886Y did a jam brake when the traffic light turn amber. The vehicle SKM6886Y was over the traffic line at the point of accident.

Declaration

I/We declare the foregoing particulars are true in every respect.

Subs 13/02/23
Policyholder's Signature / Date & Time
9:20am

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

TEO SEK LAM

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

[Signature]

Policyholder's Signature / Date & Time


Driver's Signature (if driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

TEO SECK LAM

Sketch Plan



2ND UPPER BUDIT TIMUKH RD.

Wah Hong Motors & Credit Pte Ltd (Co.Reg.No:199806235M)38 Toh Guan Road East, #01-57, Enterprise Hub
Singapore 608581

Tel: +65 6773 7377 Email: motor@wahhong.sg

INSURER: **HL Assurance Pte Ltd (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	WH1707
Policy No:	MP309471	Date of Loss:	11/02/2023
Vehicle Reg. No.:	SLM5514R	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LIM JUNWEN, LESLIE	Contact No:	+6581137178
Make/Model:	NISSAN QASHQAI, 1.2 DIG-T CVT ABS 2WD 5DR (A)	Vehicle Reg. Date:	31/03/2017
Vehicle Colour:	BROWN	Chassis No:	SJNFEAJ11U1788100
Engine No:	HRA2337835A		
Odometer:	72792 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Present Location:	WAH HONG MOTORS & CREDIT PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	6,683.25
Miscellaneous Items	145.00
Labour	2,160.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	9618.25 8,988.25
+ GST 8.00% (S\$)	719.06
Nett Amount (S\$)	9,707.31

This claim is handled by: CHAN PEI PEI

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 14 Feb 2023)

Parts: M1-SUV NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Wah Hong Motors & Credit Pte Ltd/SLM5514R/14/02/2023 16:50

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Bonnet <i>ht</i>	0.00	0.00	*700.00 F
2	1		*Bonnet hinge RH/LH@2*\$50 <i>Xnn</i>	0.00	0.00	*100.00 F
3	1		*Headlamp RH/LH@2*\$450 <i>cm</i>	0.00	0.00	*900.00 F
4	1		*Front bumper <i>cut</i>	0.00	0.00	*450.00 F
5	1		*Front bumper side retainer RH/LH@2*\$35 <i>Xnn</i>	0.00	0.00	*70.00 F
6	1		*Front bumper towing cover <i>cut</i>	0.00	0.00	*25.00 F
7	1		*Center grille <i>cm</i>	0.00	0.00	*350.00 F
8	1		*Center grille logo badge <i>cm</i>	0.00	0.00	*60.00 F
9	1		*Front bumper sponge <i>cm</i>	0.00	0.00	*150.00 F
10	1		*Front reinforcement <i>? Xnn</i>	0.00	0.00	*450.00 F
11	1		*Front lower reinforcement <i>Xnn</i>	0.00	0.00	*250.00 F
12	1		*Front bumper lower sponge RH/LH@2*\$50 <i>Xnn</i>	0.00	0.00	*100.00 F
13	1		*Front chassis member bracket RH/LH@2*\$100 <i>Xnn</i>	0.00	0.00	*200.00 F
14	1		*Horn - high pitch <i>cm</i>	0.00	0.00	*90.00 F
15	1		*Condenser <i>ht</i>	0.00	0.00	*650.00 F
16	1		*Radiator <i>? Xnn</i>	0.00	0.00	*650.00 F
17	1		*Fan cowling set <i>? Xnn</i>	0.00	0.00	*550.00 F
18	1		*Radiator air guide RH/LH@2*\$85 <i>LH-cm / RH-? Xnn</i>	0.00	0.00	*170.00 F
19	1		*Front fender LH <i>repair</i>	0.00	0.00	*450.00 F
20	1		*Front fender RH (Repair refer to labour) <i>R</i>	0.00	0.00	*- F

F=Franchise part.

Sub Total (\$)	<i>3460</i>	6,365.00
+ Margin on L,N Items 5.00% (\$)	<i>52+</i>	318.25
Total Parts (\$)	<i>3633</i>	6,683.25

Wah Hong Motors & Credit Pte Ltd/SLM5514R/14/02/2023 16:50. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	Center grille clips <i>ne</i>	25.00
2	1	Coolant <i>no? m</i>	50.00
3	1	Front bumper clips <i>m</i>	35.00
4	1	Front car plate with holder <i>sun</i>	35.00
Sub Total (S\$)			145.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	New	1,000.00
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	New	1,000.00
3	To remove and refix wiring system at accident damaged area and check for all electrical proper function	New	60.00
4	To remove and refit aircon condenser, radiator, related pipes and hoses, vaccum and refill aircon gas	New	100.00
Gross Labour Cost (S\$)			2,160.00

Wah Hong Motors & Credit Pte Ltd/SLM5514R/14/02/2023 16:50. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3633

115

1510

630

5888

206

4710

Ram

Hp 900/100 G8

6 days

4s

16/02/23 @ 1435

EXCESS: 300

Revert

Resy after repair

4s - \$4,700/6 days

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Mar 2023)

Parts: M1-SUV NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Wah Hong Motors & Credit Pte Ltd/SLM5514R/02/03/2023 18:54

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front wheel arch garnish RH/LH@2*\$300 <i>cm</i>	0.00	0.00	*600.00 F
F=Franchise part.						
Sub Total (\$\$)						600.00
+ Margin on L,N Items 5.00% (\$\$)						30.00
Total Parts (\$\$)						630.00 ✓

Wah Hong Motors & Credit Pte Ltd/SLM5514R/02/03/2023 18:54. Not valid without Reference section.
Generated using Merimen e-Claims IEAS