

PG 11/11

Sm 8

REF:

ASS. REC. BY:

091

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspcd Vehicle No: _____

at Workshop m/s _____

of _____

Insured: INC

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Est. or Market Value: _____

IDAC Accident Report: _____ Consistent? Yes or No

GIA / PR Seen: _____ Consistent? Yes or No

Est. Repairs: 3 days Rep: Yes or No

Lump Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SH4662m Yr Reg: 30/05/2017

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius cc 1798

Colour: Blue AC: Insured / Std / Nil / NA

Sp. Reading: 675951 T/Radio: Insured / Std / Nil / NA

Eng No: _____

CN: JD K B 3 F U 70355-7417

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / Rim, or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LZA / WIC / OHTSU / PR / SUMI /

TOYO / YOKO or Westlake

Front

Rear

R/Bal: 5 mm R/Bal: 5 mm

L/Bal: 5 mm L/Bal: 5 mm

D.O.A: 13/2/23

D.O.I: 14/2/23 2.30pm

Survey held at Comfort

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee:

Transportation

\$ + RS: \$

Photos

Others

TOTAL

COMFORTDELGRO ENGINEERING

A member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Bras Basah Road Singapore 179571

Mainline + 65 6380 0000 Facsimile + 65 6380 0100

Workshops

59 Loring Drive Singapore 600045

383 Sin Ming Drive Singapore 570717

45 Pandan Road Singapore 600096

222 Loo Joo Road Singapore 600045

24 Serangoon Road Singapore 758108

7 Sungei Road Singapore 700071

101 Hutan Industrial Park A Singapore 75

Date/Time: 14.02.2023 12:36

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5867792

JC NO305545585

CUSTOMER

MR/MS COMFORT TRANSPORTATION PTE LTD
CUSTOMER NO. 7010045
ADDRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
TEL (R) 65508755 (O)
(P)

DISCOUNT CARD NO.

REGN NO.

SHA4662M

MILEAGE

MAKE

TOYOTA

FUEL

E 1/2

MODEL

PRIUS HYBRID(G4)14.02.2023 08:20

DATE/TIME IN

YR OF MANU.

30.05.2017

TARGET DATE

CHASSIS CODE

JTDKB3FU703557419

COMPLETION DATE/TIME

JOB DESCRIPTION


Accident Date: 13.02.2023

NATURE: 3P 13.02.2023

S/O

LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Name:

I/C No.:

Vehicle No.: SHA4662M

YY

Exit Pass

Vehicle No.:

SHA4662M

Name of Service Advisor

Signature/Date

Name of Service Advisor

Date

To be returned to Service Reception upon collection

To be kept by Security Guard