

(08/16/13) wsf

ASS. REC. BY Permu

REF:

CS/FCI 23 001682/RUG3

9517

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SMP 5710Mat Workshop m/s PERFORMANCEof ALEXANDRA RDInsured: FCI

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 116K

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMP 5710M Yr Regn: 2019 1 SEPType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: B-M-W 216 I G.T c.c. 1499Colour: GREY A/C: Insured / Std / NI / NASp. Reading: 21342 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBA6V12040SN97622Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt or _____Brake: Inorder / Jammed / Leaked / Burnt or _____Modi: Nil / S/Rim / STD A/Rim or _____Tyre Size: F: 205/55R17R: 36BE / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 19/01/23 D.O.I. 21/03/23Survey held at PERFORMANCEDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 65K

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

S + RS ___ \$

Photos

Others

Report Format : _____

Lump Sum / I.B.I: (\$)

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

16 Feb 2023

Estimate No. : b1 64902
Date Estimated : 06/02/2023
Prepared By : Jack Ng Guo Ming

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -

Ang Kirk Gine
79, Pasir Ris Grove#03-42

Singapore 518209

ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMP5710M	WBA6V120405N97622	30/09/2019	216i Gran Tourer	17506

DESCRIPTION

To replace rear bumper and all damage parts.

To respray rear bumper

To check electrical wiring

Sundries.

VALUE

850 1,700.00

986 1,038.00

168 17.00

? 150.00

Total Labour 1: 3,065.00

DESCRIPTION

REAR BUMPER PANEL PRIMED (LINES PDC) *de*
REAR BUMPER TRIM STRIP CHROM ?

QTY

PRIC

VALUE

1 1,088.30

1,088.30

1 97.90

97.90

Total Parts : 1,186.20

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:



Rasue
Hp 9000068
3 days
21/03/23 @ 1520
Resy before paint

Labour 1	:	3,065.00
Parts	:	1,186.20
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 8%	:	340.10
Grand Total	:	4,591.30

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **
** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 951D

Vehicle Details

Vehicle No.: SMP5710M

Vehicle to be Exported: No

Intended Deregistration Date: 21 Mar 2023

Vehicle Make: B.M.W.

Vehicle Model: 216i GRAN TOURER NAV

Primary Colour: Silver

Manufacturing Year: 2019

Engine No.: 41145740B38A15A

Chassis No.: WBA6V120405N97622

Maximum Power Output: 80.0 kW (107 bhp)

Open Market Value: \$34,427.00

Original Registration Date: 30 Sep 2019

First Registration Date: 30 Sep 2019

Transfer Count: 0

Actual ARF Paid: \$40,198.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 29 Sep 2029

PARF Rebate Amount: \$30,148.00

Intended COE Rebate Details

COE Expiry Date: 29 Sep 2029

COE Category: E - Open - all except motorcycle

COE Period(Years): 10

QP Paid: \$37,912.00

COE Rebate Amount: \$20,729.00

Total Rebate Amount: \$50,877.00

BMW 2 Series 216i Gran Tourer

Overview

Insurance

Financial

Accessories

Similar

Research

Photos



Our Accreditations



Singapore
Vehicle
Traders
Association

Price **\$116,800**

Depreciation  \$15,950 /yr
[View models with similar depre](#)

Reg Date 23-Sep-2019
(6yrs 6mths 1day COE left)

Mileage 70,146 km (20.1k /yr)

Manufactured  2019

Road Tax  \$684 /yr

Transmission Auto

Dereg Value  \$40,108 as of today ([change](#))

OMV  \$24,215

COE  \$31,759

ARF  \$25,901

Engine Cap 1,499 cc

Power 80.0 kW (107 bhp)

Curb Weight  1,490 kg

No. of Owners  1