

(08/16/13) wbf

ASS. REC. BY: Permu

REF:

C/FU23001682/RUG3m4

9517

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SMP 5710Mat Workshop m/s PERFORMANCEof ALEXANDRA RDInsured: SMG 904B FCI

Policy No.

Claims No. D23000499MVQC


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

116K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMP 5710M

Yr Regn:

2019 1 SEPType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

B-M-W 216I G.Tc.c 1499

Colour

GREY

A/C:

Insured / Std / NI / NA

Sp. Reading

21342

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WBA6V12040SN97622Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R17

R:

44BE / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

19/01/23

D.O.I.

21/03/23

Survey held at

PERFORMANCEDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LIMIT - 65K

2/5/23

Final fig \$3270.20 confirmed by email (Red 981, 23%)

Date/Time, File Pass to?



Prel. Report

1)



Final Report

Date/Time, File Return to?

2) 2/5/23-typist

Days Of Repair: 3Resurvey No. of Trip: 1

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

135

Transportation:

50

S + RS SI

50

Photos

23

Others

Total:

258Report Format : TP

Lump Sum / I.B.I: (\$ 3270.20)