

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



AUTOMOBILE INSPECTION REPORT					
INCOME INSURANCE LTD			Ref:	NS/INC23001684/Swp3m4	
75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557			Date:	25-05-2023 INC4	
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SKP 8838H	Veh. Ir	spected	SHD 3584X
	Policy No.		Covera	age (\$)	0.00
	Claim No.	MT/1213527-001	Exces	s (\$)	0.00
	Assign From		Assigr	n Date	14/02/2023
2. Vehicle Particulars & Condition					
	Make & Model	HYUNDAI I40	c.c		1685
	Engine No.	HIDDEN	Year o	f Reg.	2016
	Chassis No.	KMHLB41UMGU093689	Colou	•	BLUE
	Odometer	1171258	Steerin	ng	IN ORDER
	Brakes	IN ORDER	Modifi	cation	STANDARD ALLOY RIM
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	195/65 R15	WEST		5 mm
	L/H Front Tyre	195/65 R15	WEST	_AKE	5 mm
	R/H Rear Tyre	195/65 R15	WEST	_AKE	5 mm
	L/H Rear Tyre	195/65 R15	WEST	_AKE	5 mm
4.					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S AND REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	10/02/2023	Inspection Date 14/02/2023		
	Survey held at	COMFORTDELGRO ENGINEERING PTE LTD			
		59 LOYANG DRIVE SINGAPORE 508969			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	c. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				