

PG1117

Sm

REF:

ASS. REC. BY:

est

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspcd Vehicle No: _____

at Workshop m/s _____

of _____

Insured: INC

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
X	X

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: Shd 3584X Yr Reg: 8/9/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: hyundai 140 cc 1798

Colour Blue AC: Insured / Std / NI / NA

Sp. Reading 1171258 T/Radio: Insured / Std / NI / NA

Eng No: _____

C No: KMBL041UMGV093689

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD / Rlm, or

Tyre Size: F: 175/65R15
R: _____

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PRI / SUMI /

TOYO / YOKO or West Lake

Front _____ Rear _____

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 10/2/23 D.O.L. 14/2/23 9am

Survey held at Comfort

Des. of Damages: Fit / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

1) _____
Date/Time, File Return to?

2) _____

Report Format :

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:

Transport: _____

3 + RS : \$ _____

Photos : _____

Others : _____

TOTAL

Date/Time: 13.02.2023 08:29 Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5852890

JC NO:05545394

STOMER

MS COMFORT TRANSPORTATION PTE LTD

STOMER NO. 7010045

DRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717

(R) 65508755 (O)

(P)

COUNT CARD NO.

REGN NO. SHD3584X	MILEAGE
MAKE HYUNDAI	FUEL E 1/2 F
MODEL I-40	DATE/TIME IN 11.02.2023 06:00
YR OF MANU 08.09.2016	TARGET DATE
CHASSIS CODE KMHLE41UMGU093689	COMPLETION DATE/TIME

JOB DESCRIPTION


Accident Date: 10.02.2023

NATURE: 3P 10.02.2023

I/NO LABOR CODE
000010 PB

DESCRIPTION

LUMPSUM REPAIR-SHD3584X-TP



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Wedge Slip

Exit Pass

No.: SHD3584X LIMITS

Vehicle No.: SHD3584X

of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard