

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315



AUTOMOBILE INSPECTION REPORT



		AUTOMOBILE INSI	LCII	ON KLFOKT		
INCC	ME INSURANCE	LTD	Ref:	NS/INC23001686/Snp3e2		
75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557			Date:	05-04-2023		
			Code:	INC4		
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SML 6920M	Veh. lı	nspected	SHB 412P	
	Policy No.		Cover	age (\$)	0.00	
	Claim No.	MT/1204172-002	Exces	s (\$)	0.00	
	Assign From		Assig	n Date	09/01/2023	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA PRIUS	c.c		1798	
	Engine No.	HIDDEN	Year o	f Reg.	2017	
	Chassis No.	JTDKB3FU403572797	Colou	r	MAROON	
	Odometer	-	Steeri	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	STANDARD ALLOY RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	TOURI	NG	6 mm	
	L/H Front Tyre	195/65 R15	TOURI	NG	6 mm	
	R/H Rear Tyre	195/65 R15	TOURI	NG	6 mm	
	L/H Rear Tyre	195/65 R15	TOURI	NG	6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	06/01/2023	Inspec	ction Date	09/01/2023	
	Survey held at COMFORTDELGRO ENGINEERING PTE LTD					
		59 LOYANG DRIVE SINGAPORE 508969				
5a.	Remarks					
		A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair					
	ESTIMATED NOR	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				
$\overline{}$	•					