



## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



### AUTOMOBILE INSPECTION REPORT

INCOME INSURANCE LTD

Ref: NS/INC23001691/Snp3e2

75 BRAS BASAH ROAD  
INCOME CENTRESINGAPORE 189557

Date: 18-04-2023

Code: INC4

#### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YN 5703C	Veh. Inspected	SH 6232R
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1209361-002	Excess (\$)	0.00
Assign From		Assign Date	13/02/2023

#### 2. Vehicle Particulars & Condition

Make & Model	BYD E6 (ME-2)	c.c	0
Engine No.	HIDDEN	Year of Reg.	2022
Chassis No.	LC0CE4DC0N0040215	Colour	BLUE
Odometer	45168	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55 R17	CHAO YANG	6 mm
L/H Front Tyre	215/55 R17	CHAO YANG	6 mm
R/H Rear Tyre	215/55 R17	CHAO YANG	6 mm
L/H Rear Tyre	215/55 R17	CHAO YANG	6 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

#### 5. General Information

Accident Date	10/02/2023	Inspection Date	13/02/2023
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

#### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------