

(P&T) 1-1

ASS. REC. BY:

REF:

NS/INC23001691/Snp3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspcd Vehicle No: _____

at Workshop m/s _____

of _____

Insured: INC

Policy No. _____

Claims No. MT/1209361-002

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res: Yes or NoLump Sum: 1 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: Sh 6232R Yr Regn: 25/08/22

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BYD New E6 cc 70kwhColour Blue

A/C: Insured / Std / Nil / NA

Sp. Reading 45168

T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: LC0LE40C0N0040215

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / A/Rim, or

Tyre Size: F: 215/55r17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or chao yang

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 10/2/23D.O.L. 13/2/23 4:10pmSurvey held at Comfort

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

P/PIrfan confirmed fonal fig \$1520.60 ans 2 days
(red. \$5182.49. 77%)

Date/Time, File Pass to?

☐ : Prel. Report

1) 17/04/23

☐ : Final Report

Date/Time, File Return to?

2) _____

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: 2Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5851663

JC NO305545338

STOMER /MS COMFORT TRANSPORTATION PTE LTD STOMER NO. 7010045 DRESS 383 SIN MING DRIVE Singapore SINGAPORE 575717 - (R) 65508755 (O) (P)	REGN NO.: SH 6232R	MILEAGE
	MAKE: BYD	FUEL E 1/2 F
	MODEL: NEW E6	DATE/TIME IN 10.02.2023 14:50
	YR OF MANU: 25.08.2022	TARGET DATE
	CHASSIS CODE: LC0CE4DCON0040215	COMPLETION DATE/TIME:

COUNT CARD NO.


JOB DESCRIPTION

Accident Date: 10.02.2023
NATURE: 3P 10.02.2023

3/NO

LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: SH 6232R CHIANG

Vehicle No.: SH 6232R

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard