

ASS. REC. BY: Smy REF: _____

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspcd Vehicle No: _____

at Workshop m/s _____

of _____

Insured: INC

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res: Yes or No

Lump Sum: 1 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: Sh 6232R Yr Regn: 25/08/22

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BYD New E6 'cc 70kwh

Colour Blue

A/C: Insured / Sd / NI / NA

Sp. Reading 45168

T/Radio: Insured / Sd / NI / NA

Eng/No: _____

C/No: LC0LE40C0N0040215

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD / A/Rlm, or

Tyre Size: F: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 10/2/23

D.O.L. 13/2/23 4:10pm

Survey held at

Comfort

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

P/P

Date/Time, File Pass to?

☐ : Prell. Report

1) Date/Time, File Return to?

☐ : Final Report

2) _____

Report Format :

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5851663

JC NO305545338

CUSTOMER /MS COMFORT TRANSPORTATION PTE LTD STOMER NO. 7010045 DRESS 383 SIN MING DRIVE Singapore SINGAPORE 575717 - (R) 65508755 (O) (P)	REGN NO.: SH 6232R	MILEAGE
	MAKE: BYD	FUEL E 1/2 F
	MODEL: NEW E6	DATE/TIME IN 10.02.2023 14:50
	YR OF MANU: 25.08.2022	TARGET DATE
	CHASSIS CODE: LC0CE4DCON0040215	COMPLETION DATE/TIME:

COUNT CARD NO.


JOB DESCRIPTION

Accident Date: 10.02.2023
NATURE: 3P 10.02.2023

3/NO

LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.:

SH 6232R

CHIANG

Vehicle No.:

SH 6232R

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard