

(P6711)

ASS. REG. BY:

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspcd Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2

days

Res: Yes or No

Lump Sum:

20

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Shd 3223m

Yr Regn:

30/6/2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

hyundai t40

cc 1685

Colour

Blue

A/C: Insured / Std / NI / NA

Sp. Reading

870483

T/Radio: Insured / Std / NI / NA

Eng No:

C/Nr:

Kmh LB41UN90091001

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / Rim or

Tyre Size:

F:

R:

195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / WIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

west Lake

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

14/2/23

D.O.I.

15/2/23 4.30pm

Survey held at

Comfort

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

: Prel. Report

1)

: Final Report

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.J: (\$

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

: Site Insp (\$

: Interview (\$

: Tech. Invs (\$

: Weekend (\$

Survey Fee:

Transportation:

S + RS: \$

Photos

Others

TOTAL

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5866556

JC NO305545611

OMER

IS COMFORT TRANSPORTATION PTE LTD

OMER NO. 7010045

ESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717

(R) 65508755

(O)

(P)

JUNT CARD NO.

REGN NO.:

SHD3223M

MILEAGE

MAKE:

HYUNDAI

FUEL

E.....1/2.....F

MODEL

I-40

DATE/TIME IN
14.02.2023 08:25

YR OF MANU.

30.06.2016

TARGET DATE

CHASSIS CODE

KMHLB41UMGU091601

COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 14.02.2023


ATURE: 3P.14.02.23

'NO

LABOR CODE

DESCRIPTION

FRONT



REAR

LEFT SIDE

RIGHT SIDE

To

KED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

No.: SHD3223M

JU TOKIO

Vehicle No.:

SHD3223M

Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard