

06/11/23

Smg

REF:

ASS. REC. BY:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspcd Vehicle No: _____

at Workshop m/s _____

of _____

Insured: INC

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vehc _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res: Yes or No

Lump Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: Sh4372A Yr Regn: 27/12/19

Type: MCar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota prius cc 1798

Colour Blue

AC: Insured / Std / Nil / NA

Sp. Reading 307281

T/Radio: Insured / Std / Nil / NA

Eng No: _____

C/Nr: 5TD1C33F0X03090562

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD / A/Rlm, or

Tyre Size: F: 195/65 R15

R: _____

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or web + LAKL

Front _____ Rear _____

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 11/2/23 D.O.L. 13/2/23 4pm

Survey held at Comfort

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐ : Prell. Report

☐ : Final Report

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

COMFORTDELGRO ENGINEERING

member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701

Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

60 Loyang Drive Singapore 508989

383 Sin Ming Drive Singapore 575717

45 Pandan Road Singapore 609289

329 Ubi Road Singapore 408649

24 Serangoon Loop Singapore 758156

7 Sungai Kadut Way Singapore 728791

501 Yehun Industrial Park A Singapore 768732

Date/Time: 13.02.2023 14:26

Page : 1

Job: ARC Repair TP(CLS0)1

JOB CARD Sales Order: 5853497

JC NO305545567

Customer

IS COMFORT TRANSPORTATION PTE LTD
Customer NO. 7010045
ADDRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)
(P)

REGN NO.

SHA4372A

MILEAGE

MAKE

TOYOTA

FUEL

E 1/2 F

MODEL

PRIUS HYBRID(G4A11.02.2023 15:00

DATE/TIME IN

YR OF MANU.

27.12.2019

TARGET DATE

CHASSIS CODE

JTDKB3FUX03090562

COMPLETION DATE/TIME:

Job Card NO.


JOB DESCRIPTION

Accident Date: 11.02.2023
Accident Time: 3P 11.02.2023

Job NO

LABOR CODE

DESCRIPTION



Job Card & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Job Card

Exit Pass

Job No.: SHA4372A

CHIANG

Vehicle No.:

SHA4372A

Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard