

ASS. REC. BY:

REF: Tb /

## ASSIGNMENT

Kenneth

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s Cam

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: £127k

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 1.81% 3 Val.: Yes or NoCA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: Smw9733J Yr Regn: 12, 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Tucson S.c.c 1591Colour: N. Black A/C: Insured / Std / NI / NASp. Reading: 20979 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KM14J3812V2U390641

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / RIM or

Tyre Size: F: \_\_\_\_\_

R: 225/60R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or  Hankook

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 26/10/22

Survey held at \_\_\_\_\_

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 16/2/2023

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

M N/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Prell. Report☐ : Final Report

Date/Time, File Return to?

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:

Transportation

S - RS. SI

F. m/s

Others

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Report Format :

Lump Sum / I.B.I. (\$) \_\_\_\_\_

# ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

205 Braddell Road  
Singapore 579701

Tel: 63837613 Fax: 62815767/65462533 Email: teokeejin@cdge.com.sg; samuelxie@cdge.com.sg

INSURER: **India International Insurance Pte Ltd (HQ)**

## PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	D20MFL0000326_02	Date of Loss:	26/10/2022
Vehicle Reg. No.:	SMW9733J	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES

Insured/Claimant: COMFORTDELGRO RENT-A-CAR PTE LTD

Make/Model:	HYUNDAI TUCSON, 1.6 GLS T-GDI DCT 2WD (A)	Vehicle Reg. Date:	21/12/2020
Vehicle Colour:	BLACK	Chassis No:	KMHJ3812VLU390641
Engine No:	G4FJLH805669		
Odometer:	0 KM		

Paint Type:  
List Item Discount: 20.00 %  
Total Loss? NO  
Est. Duration of Repair (day) 8 days

*Not Authorize  
Repair B&P only*

Present Location: COMFORTDELGRO ENGINEERING PTE LTD (BRADDELL)

COST OF CLAIMS	Amount
Parts	2,934.96
Miscellaneous Items	61.00
Labour	1,450.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (\$\$)</b>	<b>4,445.96</b>
<b>+ GST 8.00% (\$\$)</b>	<b>355.68</b>
<b>Nett Amount (\$\$)</b>	<b>4,801.64</b>

This claim is handled by: OI SUN PIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System



## R DETAILS

### Reference

Source: MRM-SG Version: 1.0 (Last Synchronised: 16 Feb 2023)

Parts: M1-SUV HYUNDAI TUCSON 1.6 GLS T-GDI DCT 2WD (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SMW9733J/16/02/2023 08:56

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BONNET	20.00	0.00	*1,617.80 FL ✓
2	1		*FRONT BUMPER	20.00	0.00	*554.00 FL ✓
3	1		*FRONT GRILLE	20.00	0.00	*1,087.00 FL ✓
4	1		*FRONT BUMPER LOWER GARNISH	20.00	0.00	*389.00 FL ✓
5	1		*FRONT NUMBER PLATE GARNISH	20.00	0.00	*20.90 FL ✓
Sub Total (\$\$)						3,668.70
- List Item Discount on L Items (\$\$)						733.74
Total Parts (\$\$)						2,934.96

F=Franchise part. L=ListItemDisc.

ComfortDelGro Engineering Pte Ltd/SMW9733J/16/02/2023 08:56. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

### LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## Estimates on Miscellaneous Items

Qty	Particulars	Amount
<u>Miscellaneous Items</u>		
1	1 FRONT BUMPER CLIPS	50.00
2	1 OD/TP Case (Insurer)	11.00
Sub Total (S\$)		61.00

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	To knock & straighten on accident area, to remove & refit Front damage parts.	New	800.00
2	To putty & respray on Front damage parts.	New	600.00
3	To check wiring & focus headlamp.	New	50.00
Gross Labour Cost (S\$)			1,450.00

ComfortDelGro Engineering Pte Ltd/SMW9733J/16/02/2023 08:56. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	03/11/2022 16:16 (SGT)
Reported by	Driver
Date of Accident	26/10/2022 21:30 (SGT)
Exact Location of Accident	1 Jurong Lake Link, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number SMW9733J

#### INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	COMFORTDELGRO RENT-A-CAR PTE LTD
Company Reg No	1XXXXX775H
Email Address	dannyng@cdgrentacar.com.sg
Mobile Phone No	(Phone) +65-91544311
Alternative Phone No	(Office) +65-68820888

#### VEHICLE PARTICULARS

Manufacturer	Hyundai
Model	TL TUCSON FL 1.6 GLS T-GDI DCT 2WD
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Reporting only
Vehicle Category	Private car
Transmission	Auto
CC	1591

#### INSURANCE COMPANY

Name of Insurance Company	India International Insurance Pte Ltd
Policy Number / Cover Note Number	D20MFL0000326_02

#### DRIVER

Name of Driver	KIM JEONGHO
Passport No/FIN	GXXXX952J
Date Of Birth	08/08/1971
Occupation	Outdoor



## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



↑ BULIM AVENUE

A - SMW9733J

B - WALL

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	775H

### Vehicle Details

Vehicle No.:	SMW9733J
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Feb 2023
Vehicle Make:	HYUNDAI
Vehicle Model:	TL TUCSON FL 1.6 GLS T-GDI DCT 2WD
Primary Colour:	Black
Manufacturing Year:	2020
Engine No.:	G4FJLH805669
Chassis No.:	KMHJ3812VLU390641
Maximum Power Output:	130.0 kW (174 bhp)
Open Market Value:	\$19,173.00
Original Registration Date:	21 Dec 2020
First Registration Date:	21 Dec 2020
Transfer Count:	0
Actual ARF Paid:	\$19,173.00

### Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Dec 2030
PARF Rebate Amount:	\$14,379.00

### Intended COE Rebate Details

COE Expiry Date:	20 Dec 2030
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$39,000.00
COE Rebate Amount:	\$30,686.00
<b>Total Rebate Amount:</b>	<b>\$45,065.00</b>

The information contained herein is correct as at 07 Feb 2023

OK