



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

Ref: CS/INC23001754/Sny3m4

75 BRAS BASAH ROAD  
INCOME CENTRESINGAPORE 189557

Date: 21/03/2023

ATTN: YEE PEI LI

Code: INC

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SNF 346E	Veh. Inspected	SMY 5821D
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1209601-001	Excess (\$)	0.00
Assign From	HAZALYSA BINTE IBRAHIM	Assign Date	16/02/2023

### 2. Vehicle Particulars & Condition

Make & Model	NISSAN X-TRAIL	c.c	1997
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JN1JANT32Z0001444	Colour	RED
Odometer	175471 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/60 R18	MICHELIN	5 mm
L/H Front Tyre	235/60 R18	MICHELIN	5 mm
R/H Rear Tyre	235/60 R18	MICHELIN	5 mm
L/H Rear Tyre	235/60 R18	MICHELIN	5 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	09/02/2023	Inspect Date / Time	16/02/2023 ( 01:30 PM )
Survey held at	JSSM AUTOSOLUTIONS PTE LTD 8 KAKI BUKIT AVENUE 4 #02-13 PREMIER @ KAKI BUKIT SINGAPORE 415875		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**