

(08/11/13) Wef

ASS. REC. BY: JSU

REF:

CS/CTI 2300 1759/R9P3

(OPC) 383B

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SM2 1897Gat Workshop m/s PERFOR MARKof 303, ALUMINUM RDInsured: CTI

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

130k

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

REPAIR LIFT - 20K

Veh No:

SM2 1897G

Yr Regn:

2021 APRType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

B-M-W X1 DRIVE 18I HL c.c 1499

Colour:

BLUG

A/C: Insured / Std / NI / NA

Sp. Reading

23073

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBA 32A A0605T10519Gen. Cond: Good / Fair / Poor / BurntSteering: Order / Jammed / Leaked / Burnt orBrake: Order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/55R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

11/02/23

D.O.I.

14/03/23

Survey held at

PERFORMANCEDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?



: Prel. Report

1)

Date/Time, File Return to?



: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Photos

Others

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$))

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

15 FEB 2023

Estimate No. : b1 65015
Date Estimated : 14/02/2023
Prepared By : Foong Shiuh Jye

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -

Valerie Sheila Manlalu
351D Anchorvale Road
#14-221

Singapore 544351

- ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMZ1897G	WBA32AA0605T10519	15/04/2021	X1 sDrive18i	16750

DESCRIPTION

To replace bumper rear panel and attachments

850 1275.00

To spray paint bumper rear panel

986 1,088.00

To remove old PDC assembly, replace damaged parts and
reconnect to new bumper including conduct check for
proper function.

168 171.00

To check electrical wiring system and lighting at the
rear section for proper function.

168 171.00

Sundries.

? 80.00

Total Labour 1: 2,747.00

DESCRIPTION

RR BUMPER LH CORNER MOUNTING

QTY	PRIC	VALUE
1	151.90	151.90

RR BUMPER RH CORNER MOUNTING

1	151.90	151.90
---	--------	--------

REAR BUMPER PANEL PRIMED

1	926.75	926.75
---	--------	--------

REAR BUMPER MIDDLE TRIM PANEL (PDC)

1	272.45	272.45
---	--------	--------

Total Parts : 1,503.00

Claims OD (3rd Party) / Uninsured losses / Direct Settlement

Regn No. Claim No.

Date & Time Excess \$

Surveyor's Name Sign

Surveyor's Tel 90010068 Authorised Yes / No

Authorised Date Time

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail

No. of Working Days Recommend 3 days

Labour 1 : 2,747.00

Parts : 1,503.00

Labour 2 : 0.00

Excess : 0.00

Total GST @ 8% : 340.00

Grand Total : 4,590.00



** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **
** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	383B
Vehicle Details	
Vehicle No.:	SMZ1897G
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Mar 2023
Vehicle Make:	B.M.W.
Vehicle Model:	X1 SDRIVE 18I LED HL
Primary Colour:	Blue
Manufacturing Year:	2021
Engine No.:	37166316B38A15F
Chassis No.:	WBA32AA0605T10519
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$35,606.00
Original Registration Date:	15 Apr 2021
First Registration Date:	15 Apr 2021
Transfer Count:	0
Actual ARF Paid:	\$41,849.00
OPC Cash Rebate Details	
OPC Cash Rebate Eligibility:	No
OPC Cash Rebate Eligibility Expiry Date:	-
OPC Cash Rebate Amount:	-
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Apr 2031
PARF Rebate Amount:	\$31,386.00
Intended COE Rebate Details	
COE Expiry Date:	14 Apr 2031
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$35,309.00
COE Rebate Amount:	\$28,541.00
Total Rebate Amount:	\$59,927.00