

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 19960/198R GST Reg. No. 19-960/198-R				
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERAL	INSURANCE (S) PL	Ref	: CS/AGI23001760/Kvy3e2	
	(BUDGET DIRECT 190 CLEMENCEAU SINGAPORE SHO 239924	INSURANCE) J AVENUE #03-01 PPING CENTRESINGAPORE	Dat	te: 14/03/2023	
			Cod	de: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SML 5511S	Veh. Inspected	SJN 379R	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10020514 /CH	Excess (\$)	0.00	
	Assign From	FRAULEINE KHOO	Assign Date	16/02/2023	
2. Vehicle Particulars & Condition					
	Make & Model	HONDA FIT (A)	c.c	1339	
	Engine No.	HIDDEN	Year of Reg.	2009	
	Chassis No.	GE61149092	Colour	METALLIC BLUE	
	Odometer	221566 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	195/50 R15	TOURADOR	7 mm	
	L/H Front Tyre	195/50 R15	TOURADOR	7 mm	
	R/H Rear Tyre	195/50 R15	TOURADOR	7 mm	
	L/H Rear Tyre	195/50 R15	TOURADOR	7 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	13/02/2023	Inspection Date	16/02/2023	
	Survey held at	THIAM HENG HUAT PTE LTD			
		176 SIN MING DRIVE #05-14 SINGAPORE 575721			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				

6 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: