



# N-51 AUTOMOTIVE PTE LTD

**Company & GST Registration No. 200616038C**

2 Kaki Bukit Avenue 2 #01-17/#01-18 /Heavy Vehicle #01-08/Spray Painting #02-27

Kaki Bukit Autohub Singapore 417921

Tel: 68420051

Fax: 67410510

Email: sales@n51.com.sg

Our Ref:

**SMA 4987 S**

Your ref:

**XD 5155 Z**

16 February 2023

**ERGO INSURANCE PTE. LTD.**

8 TEMASEK BOULEVARD,

#04-01 SUNTEC TOWER 3

SINGAPORE 038988

Attn: Motor Claims Department

Dear Sir/Madam,

**NAME OF CLAIMANT : TEH LI HAR**

**VEHICLE NUMBER : SMA 4987 S**

**YOUR INSURED VEHICLE NUMBER : XD 5155 Z**

**ACCIDENT ON 15 FEB 2023 AT ABOUT 07:45 HOURS**

**ALONG PIE(TUAS) AFTER BAHAR FLYOVER**

We refer to your email/fax dated **16 Feb 2023** informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment **LKK** as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

**N-51 AUTOMOTIVE PTE LTD**

Kaki Bukit Autohub

2 Kaki Bukit Avenue 2

#01-18

Singapore 417921

Contact Person:

**6842 0051 / 6744 0510 (Melody)**

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,



.....  
**N-51 AUTOMOTIVE PTE LTD**

**FOR SURVEYOR:**

Please initial here after completion of pre-repair inspection. Thank you!

Appointed surveyor :

(Name & Signature) :

Date & Time of Inspection: