

Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

## **ESTIMATE FOR EH95A**

Mr Loong

18 Hillview Drive Singapore 669380

Mobile: +6583396396

Vehicle & Document Information

63011

/ 01/04/2021 EH95A

/ 0 Date In/Mileage

WIP No

Reg No/Reg Date

W1K2130802A9407381 Chassis No 26492030381400

Engine No MB/E 200 SEDAN Make/Model

029 992 Selenite Gr/ 042 201 Leather Bla Colour/Trim

ccount No	Terms	Date/Time Printed	CSE	Operator			
TP00001	Cash	15/02/2023/ 14:00	K0	301 / Kerlyn On		Unit Price Disc%	Amount
		Description of Good	ls / Services		Qty	Unit Price Disc%	Amount
A RPNSIIN	Request	<b>NOT</b> A E: 7210032741 // 14/	02/2023	FFICIA	AL TA	X INVO	ICE
DRIVE IN	ID/ACC DAT I/TP VEHIC 'DATE SURV	LE NO : 15/02/2023	// GBG658	4L - SCDF		3	
BY/AUTHF	RIZED ON	:			C-17 1/2		1920.00
DISASSEM	MBLE AND R	REPLACE ATTACHED DAMAG	ED PARTS &	REFINISH.	/ // /,	and the second second	1200.00
A DOTLAD	REAR BUMP		4	21 Mm.		0.10	380.00
USING XI IDENTIF	ICATION ST	GNOSTIC TO CHECK ON CC	15-11	11112			120.00
A BPILAB CHECK R	EAR LIGHT	ING SYSTEM AND WATER 1	EST FOR AN	Y LEAKAGE. NETT	1.00	2171.46 00.00	2171.46
M REAR BU	MPER	The state of the s			1.00	389.53 00.00	389.53
M REAR BU	MPER LOWER	R CHROME MOULDING	material de la constitución de l		1.00	402.10 00.00	402.10 613.90
M REAR BU	STANCE SE	NSOR			2.00	306.95 00.00	13.44
M DECOUPL	ING RING	And the second			2.00	6.72 00.00 199.16 00.00	199.10
M RH/ EXH	UAST PIPE	CHROME			1.00 1.00	64.34 00.00	64.3
M RH/ EXH	UAST PIPE	CHROME BRACKET			1.00	89.31 00.00	89.3
M LH/ REA	R BUMPER	LATERAL SUPPORT			1.00	89.31 00.00	89.3
M RH/ REA	R BUMPER	LATERAL SUPPORT			1.00	113.78 00.00	113.7
M CTR/ BA M REAR CR	SIC CARRI OSS MEMBE	ER FOR BUMPER R			1.00	1039.80 00.00	1039.8
			DID :	Kerlyn Ong Kai Li : 6771 4420 HP : 9186 5	5113		
			Cycle &	rlyn.ong@cyclecarriag c Carriage Industries I Service Centre - Panc	Pte Ltd		
Confirmed	& accepted	by			00/	Nett GST on 8806.13	8,806.1 704.4
					8% (	331 011 0000.13	, , , , ,
						Total Payable	9,510.6
		and company stamp					

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg



SC20232F0002 / CYCLE & CARRIAGE INDUSTRIES PTE LTD ENTRY DATE & TIME: 15/02/2023 09:59 (SGT) SUBMITTED BY: Courtney Ang Peck Yen VERSION: 1 (15/02/2023 09:59 (SGT))



# SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver
  3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### **ACCIDENT STATEMENT**

Date of Submission 15/02/2023 09:59 (SGT) Reported by Both Policyholder and Actual Driver Date of Accident 14/02/2023 12:45 (SGT) Exact Location of Accident Singapore Additional Location Information HILLVIEW AVENUE Country/State of Loss Singapore

### **DETAILS OF OWN VEHICLE**

Vehicle Registration Number EH95A INSURED/POLICYHOLDER Is company? No Name Of Registered Owner LOONG CHOE YUEN NRIC No SXXXX897F Email Address LOONGCHOEYUEN@GMAIL.COM Mobile Phone No ..... (Phone) +65-83396396 Alternative Phone No VEHICLE PARTICULARS Manufacturer Mercedes Model E200 Variant Exact purpose for which vehicle was being used at time of Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party Vehicle Category Private car Transmission Auto CC 1991 INSURANCE COMPANY Name of Insurance Company AIG Asia Pacific Insurance Pte. Ltd. Policy Number / Cover Note Number 7210032741

Name of Driver LOONG CHOE YUEN NRIC No SXXXX897F Date Of Birth 23/05/1955 Occupation Indoor

Date Of Driving Pass 18/04/1981 Driving experience 41 YEARS AND 10 MONTHS Gender Male Mobile Number (Phone) +65-83396396 Alt. Phone Number Email Address LOONGCHOEYUEN@GMAIL.COM Address 18 HILLVIEW DRIVE Address complement Postcode 669380 Is the driver the policyholder? Yes If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Collision - Head to Rear Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) 2 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement PASSENGER 1 Name LIM BEE LIAN Gender Female **DETAILS OF POLICE ACTION** Was the accident reported to the police? Police Station Name Jurong East Neighbourhood Police Centre Police Station Phone No (Phone) +65-18008999999 Alt. Police Station Phone No (Fax) +65-66655791 Police Station Address No. 92 Boon Lay Way Singapore 609962 Was notice of intended Prosecution given? If yes, against whom? CIRCUMSTANCES OF ACCIDENT REFER TO POLICE REPORT NO.:T/20230214/2108 ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? Yes Reasons for not uploading a video of the accident KINDLY REFER TO CSE KO.

### **DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number	GBG6584L
Vehicle Manufacturer	SCDF
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	RAMDZAN
Contact Number	(Phone) +65-90615073
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

#### SKETCH PLAN

### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association
- of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer , my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes. Kerlyn Ong Kai Li

DID: 6771 4420 HP: 9186 5113 Email: kerlyn.ong@cyclecarriage.com.sg Cycle & Carriage Industries Pte Ltd Customer Service Centre - Pandan Loop

Policyholder's Signature / Date & Time 15/02/2023 0858

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel KERLYN

Skatch Plan

Sketch Plan	
	10 - martin comment of martin

Describe Circumstances of the Accident		
REFER TO POLICE REPORT NO.T/2023	0214/2108	
2		

### Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time 15/02/2023 0858

Driver's Signature (If driver is not the policyholder) / Date & Time

Email: kerlyn.ong@cyclecarriage.com Cycle & Carriage Industries Pte Locustomer Service Centre - Pandan Loo.

**Kerlyn Ong Kai Li** DID: 6771 4420 HP: 9186 5113

> Witnessed by Reporting Centre Personnel KERLYN





T/20230214/2108

1 of 3

Report No. T/20230214/2108

Police Station Of Origin: Jurong East N.P.C 92 Boon Lay Way SINGAPORE 609962 Tel No: 1800-8999999

### REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 14/02/2023 22:12			Vide Report No.:		Station Diary No.: 78	
Informant'	s Particul	ars				
Name of Informant:			Address:			
LOONG CHOE YUEN			18 HILLVIEW DRIVE SINGAPORE 669380			
ID Type / ID No.:			Contact No.:			
NRIC NO / S2538897F			Home/Office: Mobile: 83396396			
Nationality:			Email:			
SINGAPOR	RE CITIZE	N	LOONGCHOEYUEN@GMAIL.COM			
Sex:	Age:	Date of Birth:	Type of Informant:			
Male	67	23/05/1955	Driver			
Race:			Language:	Institution	/ School Name:	
Chinese					-	
Occupation	1:		Driving Licence Information:			
Retiree			Class: 3	Date of Ex	piry:	

General Informa	tion of the Accident				
Type of Accident:	Non-Injury Government Vehicle	Drink Drive: No	Date/Time of Accident: 14/02/2023 12:45	Type of Location: Straight Road	
Location:					
HILLVIEW AVE	NUE				
Weather:		Road Surface:	Road Speed Limit:		
Traffic Flow:		Traffic Control:		Traffic Volume:	
Type of Collision	n:			Anyone conveyed by ambulance:	

Vehicle No.	Type	Make	Model	Calor	Condition	No of Passenger
EH95A		MERCEDES	E200	Grey	Slightly	0
		BENZ	SEDAN AVG	-	Damaged	
GBF6584L						0

Details of Vehicle Insurance						
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date		
EH95A	AIG ASIA PACIFIC INSURANCE PTE.	7210032741-01	01/04/2022	31/03/2023		
	LTD.					





2 of 3

Report No. T/20230214/2108

Police Station Of Origin: Jurong East N.P.C 92 Boon Lay Way SINGAPORE 609962 Tel No: 1800-8999999

#### CONTINUATION OF REPORT

Details of Perso	n Involved			ī.		
Any Pedestrian Ir						
No. of Pedestrian		Use of Pec	<u>destrian</u>	Cross	ing: NA	
Driver		-			T	005000075
Name	LOONG CHOE YUEN			ID No.		S2538897F
Related Vehicle	EH95A		Contact No.		83396396	
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date		Class: 3 Date of Expiry: NIL	
Date Treatment NIL			Date Discharge NIL			
No. of Days granted Medical Leave NIL Degree of Injury NIL						
Driver			100			
Name	RAMDZAN			ID No.		NIL
Related Vehicle	GBF6584L	4444		Conta	ct No.	90615073
Hospital/Clinic	NIL			Class of Driving Licence & Expiry Date		Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Disc		NIL	
No. of Days gran	ted Medical Leave	NIL	Degree of	Injury	NIL	

### **Brief Details.**

On 14/02/2023 at about 1245hrs, I was driving my vehicle (EH95A) along Hillview Ave, on the second lane. I checked my right-side mirror and saw that on the first lane, there was an SCDF red rhino, with flashing light and siren. In front of the SCDF red rhino was vehicle A that was travelling parallel to me. In addition, I observed road works ahead of me on the first lane. Hence, I slowed down my vehicle to allow both vehicles on my right to overtake me. While I was allowing vehicle A to overtake me, I felt a collision in the rear. I realised that the SCDF red rhino's front bumper had collided against the rear bumper of my vehicle, while it was trying to change lane from the first to second lane. Both the SCDF red rhino driver and I proceeded to the side road at Hillview Terrace to avoid road congestion. I observed that the rear bumper of my vehicle has dents, and the paint was chipped off. I was provided with an SCDF correspondence notice - accident involving SCDF vehicle. I wish to state that there is an in-car camera installed in my vehicle and both the SCDF driver and I were not injured. However, I am unsure if the in-car camera is functioning well.





· 3 of 3

Report No. T/20230214/2108

Police Station Of Origin: Jurong East N.P.C 92 Boon Lay Way SINGAPORE 609962 Tel No: 1800-8999999

### CONTINUATION OF REPORT

### Sketch Plan

NP168

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature of Officer Recording The Report: D / SGT 2 SAIYIDAH BINTE ABDUL WAHID	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 14/02/2023 22:12
Officer In Charge Of Case: TP / GIA / SI MOHAMAD ZULFAZDLI BIN ABDULLAH Contact No.: 65476204	Classification Of Case:



B L Lim < limbeelian@gmail.com>

### Car accident 230214

1 message

Choe Yuen Loong <loongchoeyuen@gmail.com>

To: B L Lim <a href="mailto:limbeelian@gmail.com">, Choe Yuen Loong <a href="mailto:loongchoeyuen@gmail.com">, Choe Yuen Loong <a href="mailto:loongchoeyuen@gmailto:loongchoeyu

Tue, Feb 14, 2023 at 8:39 PM

At about 12.45pm, while I was driving my car EH95A in the second lane along Hillview Ave, I saw, from my right side mirror, a SCDF red rhino (small fire engine vehicle) with flashing light and siren, driving in the first lane, traveling behind vehicle "A" which was traveling parallel to mine. Ahead of the road, I noticed there is road work blocking in the first lane.

So I slow down my vehicle so as to allow vehicle A and the red rhino to over take me.

While I was still driving slowly forward, allowing car A to overtake me, the red rhino changed from first lane to the second lane and hit the back of my car.

To avoid road congestion, both my car and the red rhino drove about 200m and turned into the side road, Hillview Terrace and parked there to deal with the accident.

I noticed my car back bumper is dented, and paint came off.

The red rhino driver told me his name was Ramdzan and he exchanged mobile number with me.

His mobile number is 90615073.

He noted down my name from my NRIC, but on my request, he said he didn't carry with him his IC nor driving licence. Instead, he gave me a SCDF correspondence notice - accident involving SCDF vehicle.

I took photos of my car and the red rhino and the road work block at Hillview Ave for records.







