

REF: CS1/SCD23001779/Dqy3

Special Instruction:

ASSIGNMENT (Office)

\$4869.36

From (Person): RALF TAY of SCD Date/Time: 16/02/2023

Estimated Cost: _____ Bill to: _____

Third Parties:

Claimant:

Surveyor: AIG in house surveyor

Workshop: CYCLE & CARRIAGE
INDUSTRIES PL

OD/TP Re-inspection	Evaluation
1.0	1.0
2.0	2.0
3.0	3.0
4.0	4.0
5.0	5.0
6.0	6.0
7.0	7.0
8.0	8.0
9.0	9.0
10.0	10.0

To Inspect Vehicle No: EH 95A Insured: GBG 6584L

at Workshop m/ CYCLE & CARRIAGE INDUSTRIES PL Tel:

of 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)

Policy No: _____ Claim No: 2023 - 18

Sum Insured: _____ Excess: _____

Make of Veh: _____
(Client's Record) _____ D.O.A. 14/02/2023

H.O.D. Endorsement/Date:

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: _____ Confirmed with _____ Final Fig _____, ____ days (Red \$____/____%; Original 3 days)

Date/Time: 01/06/23 Submit Final Fig \$4869.36, 3 days (Red \$ 0 / 0 %; Original 3 days)

[illegible]

Para(1) : Parts found not replaced (To highlight *R* or *UB*, *LR*, *Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)	

Para(3) : Nett Value

Market Value :

Salvage Value : _____

Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:

Basic & Add

Transport

Photos

Others

Total

Date: _____

1) Date/Time 01/06/23 File Pass to Typist

2) Date/Time _____ File Return to _____

3) Date/Time _____ File Pass to _____

4) Date/Time _____ File Return to _____

5) Date/Time _____ File Pass to _____

6) Date/Time _____ File Return to _____