



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                                      |                 |                                                         |  |
|----------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|-----------------|---------------------------------------------------------|--|
| CHINA TAIPING INSURANCE (S) PTE LTD<br>3 ANSON ROAD #16-00<br>SPRINGLEAF TOWERSINGAPORE 079909                                         |                                                                                      |                 | Ref: CS/CTI23001799/p3<br>Date: 17/02/2023<br>Code: CTI |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                                      |                 |                                                         |  |
| Insured Veh.                                                                                                                           | GBL 9494L                                                                            | Veh. Inspected  | SMN 485G                                                |  |
| Policy No.                                                                                                                             | DMCVSNW00034462201                                                                   | Coverage (\$)   | 0.00                                                    |  |
| Claim No.                                                                                                                              | SNM23D201128/C02                                                                     | Excess (\$)     | 0.00                                                    |  |
| Assign From                                                                                                                            | CECILIA LEE                                                                          | Assign Date     | 17/02/2023                                              |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                                      |                 |                                                         |  |
| Make & Model                                                                                                                           |                                                                                      | c.c             | 0                                                       |  |
| Engine No.                                                                                                                             | HIDDEN                                                                               | Year of Reg.    |                                                         |  |
| Chassis No.                                                                                                                            |                                                                                      | Colour          |                                                         |  |
| Odometer                                                                                                                               | -                                                                                    | Steering        |                                                         |  |
| Brakes                                                                                                                                 |                                                                                      | Modification    |                                                         |  |
| General                                                                                                                                |                                                                                      |                 |                                                         |  |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                                      |                 |                                                         |  |
|                                                                                                                                        | Size                                                                                 | Make            | Balance                                                 |  |
| R/H Front Tyre                                                                                                                         |                                                                                      |                 | mm                                                      |  |
| L/H Front Tyre                                                                                                                         |                                                                                      |                 | mm                                                      |  |
| R/H Rear Tyre                                                                                                                          |                                                                                      |                 | mm                                                      |  |
| L/H Rear Tyre                                                                                                                          |                                                                                      |                 | mm                                                      |  |
| <b>4. Description of Damages</b>                                                                                                       |                                                                                      |                 |                                                         |  |
|                                                                                                                                        |                                                                                      |                 |                                                         |  |
| <b>5. General Information</b>                                                                                                          |                                                                                      |                 |                                                         |  |
| Accident Date                                                                                                                          | 12/02/2023                                                                           | Inspection Date |                                                         |  |
| Survey held at                                                                                                                         | AUTOSPRINT PTE LTD<br>24 LENG KEE ROAD #07-01/02 LENG KEE AUTOPOINT SINGAPORE 159096 |                 |                                                         |  |
| <b>5a. Remarks</b>                                                                                                                     |                                                                                      |                 |                                                         |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                      |                 |                                                         |  |