



**KOMODO MOTORS PTE. LTD.**  
 257, Avenue 10, Singapore 730257  
 Tel: 65 6472 3888 Fax: 65 6472 1613  
 012 815 1766/538

( GST REGISTRATION NO: MR-8500364-4 )

Date : 17/02/2023

**LONPAC INSURANCE BHD**

Attn: Motor Claims Department

Vehicle number : **SMN7728K**  
 Make and model : AVANTE 1.6 4DR AUTO "S"  
 Registration Date : 28/08/2019  
 Chassis number : KMHD841CMKU934887  
 Engine number : G4FGKU171365

Job No. :  
 Owner name : MISLIMAYA  
 BTE ISMAIL  
 Date of Acc : 14/02/2023  
 Policy number : A300658552AH  
 Claim Type : 3rd Party Claim

Items :	Estimate
1 BUMPER CLIP X10	865952T500 \$ 12.00
2 COVER ASSY-RR BUMPER UPR	86611F2AA1 \$ 500.10
3 COVER-RR BUMPER LWR	86612F2AG0 \$ 353.50
4 MOULDING-L/PLATE REAR BUMPER	86619F2AA0 \$ 27.80
5 REFLECTOR/REFLEX ASSY-RR RH	92406F2500 \$ 221.60
6 REFLECTOR/REFLEX ASSY-RR LH	92405F2500 \$ 221.60
7 BEAM-RR BUMPER	86631F2AB0 \$ 294.80
8 LAMP ASSY-LICENSE PLATE,LH	92501F6000 \$ 32.30
9 LAMP ASSY-LICENSE PLATE,RH	92502F6000 \$ 32.30
10 STAY-RR BUMPER RH	86642F2AB0 \$ 78.60
11 STAY-RR BUMPER LH	86641F2AB0 \$ 78.60
12 BRACKET-RR BUMPER SIDE MTG,RH	86614F2AA0 \$ 29.40
13 BRACKET-RR BUMPER SIDE MTG,LH	86613F2AA0 \$ 29.40
14 PANEL ASSY-TRUNK LID	69200F2530 \$ 2,096.90
15 EMBLEM-AVANTE	86310F2AA0 \$ 31.20
16 WEATHER STRIP-TRUNK LID	87321F2000 \$ 92.50
	\$ 4,132.60
Less 20% Discount	\$ 826.52
Material total	\$ 3,306.08

Body,Paint & Labour Items :	Estimate
1 To carry out accident body repair	\$ 2,100.00
2 Complete putty and spray paint all affected areas	\$ 1,710.00
Labour Charges:	Estimate
3 To realign both Rear Tail lamp (S.NETT)	\$ 40.00
4 To supply trunk sealant (S.NETT)	\$ 100.00
5 To transfer trunk mechanism (S.NETT)	\$ 250.00
6 To supply & install RR number plate (S.NETT)	\$ 40.00
7 To carry-out body cavity preservation (S.NETT) (INCLUDING NEW PARTS AND CAOUTCHOUC)	\$ 280.00
8 To check electrical system for proper functioning (S.NETT)	\$ 280.00
9 Sundries (S.NETT)	\$ 40.00
10 To supply & install 'S' Logo	\$ 35.00
Total	\$ 8,181.08
Excess	
Add GST 8%	\$ 654.49
<b>Grand Total</b>	<b>\$ 8,835.57</b>

\*\*\* Estimation are base on visual inspection, should there be furthur damages found during process of repair, you will be inform prior before carry out\*\*\*