
SN0723280008 / Income Insurance Limited ENTRY DATE & TIME: 08/02/2023 19:13 (SGT) SUBMITTED BY: Lim Pusy Kiat, Ignatius VERSION: 1 (08/02/2023 19:13 (SGT))



IMPORTANT NOTICE

- Please report corractly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Actual Driver
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate.
- 4 The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies. 5. Any false reporting may be referred to the Police for Investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving
- and that copies of this report will, for a fee, be made available open application by interested parties.

 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission Reported by Date of Accident Exact Location of Accident Additional Location Information Country/State of Loss

08/02/2023 19:13 (SGT) Both Policyholder and Actual Driver 07/02/2023 14:45 (SGT) Singapore PUNGGOL REGIONAL SPORTS CENTRE Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SLT7956Z

INSURED/POLICYHOLDER

is company?

Name Of Registered Owner

NRIC No

Email Address

Mobile Phone No.

Alternative Phone No.

LIN JINHUI

AIL COM

VEHICLE PARTICULARS

Manufacturer

Model Variant

Exact purpose for which vehicle was being used at time of

Are you claiming under your own insurance policy for repair to your vehicle?

Vehicle Category

Transmission

CC

Mercedes Glc250

Yes

Private car

Auto 2000

INSURANCE COMPANY

Name of Insurance Company

Policy Number / Cover Note Number

Income Insurance Limited

HS

OF THE COM

5131687481

DRIVER

Name of Driver NRIC No

Date Of Birth

Occupation

Accident report SN0723280008

LIN JINHUI

magar

Male.

Yes

Nα

(Phone)

Date Of Driving Pass Driving experience Gender Mobile Number Alt. Phone Number

Email Address Address

Address complement

Postcode.

is the driver the policyholder?

if No. Relationship of the Driver with the Insured

Does Driver Own Other Vehicles?

Vehicle Registration Number of Other Vehicle Owned by Driver

此受保护的P

Insurance Company of Other Vehicle Owned by Driver

malerous decreased their on the homeson





Page 1 of 15

Date Of Driving Pass Driving experience Gender Mobile Number Alt. Phone Number Email Address

Address complement

Postcode

Is the driver the policyholder?

If No. Relationship of the Driver with the Insured.

Does Driver Own Other Vehicles?

Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Weather Conditions Road Surface

Collided Into Property

Clear

No

Nα

Na

Nα

1

Yes

No.

OTHER INFORMATION

Was any foreign vehicle involved in the accident?

Number of vehicles involved in the accident

Was anybody injured in the Accident?

Was any injured conveyed to hospital by ambulance?

Was any other vehicle or property damaged?

Number of Passengers (Including Driver)

Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?

Translator's name

Translator's ID

Translator's phone number

Translator's email
Original language used in the statement

DETAILS OF POLICE ACTION

Was the accident reported to the police?
Police Station Name
Police Station Phone No
Alt. Police Station Phone No
Police Station Address
Was notice of intended Presentation given.

Was notice of Intended Prosecution given?

If yes, against whom?

Yes

Ang Mo Kio Division Headquarters (Phone) +65-18002180000 (Fax) +65-64814246

51 Ang Mo Kio Avenue 9 Singapore 569784 No

-

CIRCUMSTANCES OF ACCIDENT

REFER TO POLICE REPORT

ATTACHMENT(S)

Are accident photos available for attachment? Was there any video captured by Car Camera? Reasons for not uploading a video of the accident Yes

Yes

ADV TO SUBMIT TO MOTORVIDEO@INCOME.COM.SG



Page 2 of 15

SKETCH PLAN

SKETCH PLAN

IMPORTANT NOTICE

- * Please report <u>optractly</u> the details of the accident to speed up the claims process.
- This Form must be completed by the Policyhnitet and/or the Ad^{*}
 Information provided must be an included and missister and an included and are included an included and are included an included an
- Information provided must be as trottleful and assurable as pose insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance compani.
- reventation of witholding of national facts may allow
 - ion of policy lacitity on the part of the insurance companies.
- Any false reporting may be referred to the Traffic epartment for investigation.
- This report will be forwarded by the insulant to the GIA Records Management Certiff entablished by the General Immunice Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
 By the lodgement of this report to the immunity, you hereby consent to the archiving of this report at the centre and to copies of the







SKETCH FLAN

SKETCH PLAN

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver
- Information provided must be an truthful and accurate as possible. Any willul misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Traffic Police Department for investigation.
- 6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 6. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") mayrare permitted to collect, use, disclaims and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

processing, flanding and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to.
 the claims.

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administrating my claims (including the mailing of correspondence, statements, trivoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")


(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be seed outside of Singapore, for one or more of the above Purposes.

G

08/02/2023, 1400 Sketch Plan Oriver's Signature (if driver is not the policyholder) / Dute: & Time Ignatius Lim

Witnessed by Reporting Centre Personnel (Name as in NRICAD card)



-



Page 3 of 15 3/15

SKETCH PLAN #2

escribe Circumstance of the Accident		
	_	
	Refer to GEARs	







SKETCH PLAN#2

Describe Circumstance of the Accident	
Refer to GEARs	
Refer to GEARS	

Declaration

I/We declare the foregoing particulars are true in every respect.



Driver's Signature (if driver is not the policyholder) / Date & Time Ignatius Lim


Wheesaed by Reporting Centre Personnel (Name as in NRIC/ID card)

2



Page 4 of 15 4/15


IMAGES















Page 6 of 15 6/15

IMAGES #3












Page 7 of 15 7/15

IMAGES #4








IMAGES





Page 5 of 15 5/15

IMAGES #2









1 of 2

Report No. F/20230208/7029

POLICE REPORT (NP299)

Police Station Of Origin
Ang Mo Kio Division HQ
51 Ang Mo Kio Avenue 9 SINGAPORE
569784

Tel No:1800-2180000

Date/Time Report Made 08/02/2023 10:23	Vide Report No.	Station Diary No.
Name Of Informant LIN JINHUI	Address	5 SINGAPORE:
ID Type / ID No. NRIC NO / S^ -	Contact No. Home/Office: Mobile:	
Nationality SINGAPORE CITIZEN	Email Address tianbaobuilders@gmail.com	
Occupation Construction manager	Sex Age Date of Birth	Race Chinese
Institution/School Name	Language English	
Date/Time Of Incident 07/02/2023 14:45 - 08/02/2023 08:00	Location Of Incident 205C COMPASSVALE LANE #10-3 543205	5 SINGAPORE
Priof details		

When my vehicle (SLT7956Z) drive in to the punggol construction site, one excavator is doing the excavation works, the excavator was stop by the signal man when signal man saw my vehicle is driving in, when i follow the signal man instruction to drive in, the excavator suddenly turn over his body which cause my vehicle rear view mirror,rear door mirror broken and rear part of the vehicle body is damaged.

	4
Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 08/02/2023 10:23
Officer In-Charge Of Case:	Classification Of Case:





2 of 2

) CONTINUATION OF REPORT

Report No. F/20230208/7029

	A SECTION OF THE PARTY OF THE P	
LIN JINHUI		1
NRIC NO	ID No	
Male	Age	
	Language	English
Construction manager	Address	¢.
1	Is informant A Victim?	Yes
6		
LIN JINHUI (Informant)		
	Male Chinese Construction manager	NRIC NO Male Chinese Construction manager Address Is informant A Victim?

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Sing No signature is required.	pass
Signature Of Interpreter: Not applicable	Date/Time: 08/02/2023 10:23	b
Officer In-Charge Of Case:	Classification Of Case:	



INVOICE

CAR HUB HOLDINGS PRIVATE LIMITED | BOSS GARAGE

143 Bukit Timah Road Shell Petrol Station (Shell Autoserv) Singapore, 229843 Singapore

> Phone: 87778055 Mobile: 86848055

BILL TO LIN JINHUI

S2750998C

Invoice Number: CH-2023-3010

Invoice Date: March 1, 2023

Payment Due: March 1, 2023

Amount Due (SGD): \$10,100.00

Items	Quantity	Price	Amount
LUMP SUM REPAIR AS PER SURVEY REPORT	1	\$10,100.00	\$10,100.00
		Total:	\$10,100.00
		Amount Due (SGD):	\$10,100.00

Notes / Terms

SLT7956Z MERCEDES BENZ GLC250 CHASSIS NO. WDC2533462F313141

INVOICE

To: Lin Jin Hui Date: 16 May 2023

c/o : Car Hub Holdings Pte Ltd

143 Bukit Timah Road Invoice No. : 8094516

Shell Petrol Station (Shell Autoserv)

Singapore 229843

DESCRIPTION	AMOUNT
Service rendered for appraisal / inspection report :	
Professional inspection fees	SGD 733.00
Photographs 63 pcs	
Transport fees	
Re-inspection fees (work in progress, post repair inspection)	
Total	SGD 733.00
Singapore dollar : SEVEN HUNDRED THIRTY THREE ON	LY.
Registration no. : SLT7956Z	
Make/Model : Mercedes Benz GLC250 4matic Coupe	
Our reference : UAM23.02.16-AK-STP-CHH-SLT7956Z	



Our ref.: UAM23.02.16-AK-STP-CHH-SLT7956Z

Date : 16 May 2023

Lin Jin Hui

WITHOUT PREJUDICE

Ъ	α.
Dear	Sir

Re: Third Party Claim For Vehicle Registration No. SLT7956Z

We refer to your instruction to appraise the above-mentioned vehicle of 21 February 2023

A static inspection was carried out and our report is enclosed for your perusal. The estimated cost of repair submitted by Messrs. Car Hub Holdings Pte Ltd for SGD 15,685.93 as per our attached schedule has been inspected thoroughly by us against the actual damages sustained on the above-mentioned vehicle and we recommend the replacement and rectification accordingly.

Our revised quotation for the repair is SGD 12,636.06. In our opinion, it to be excessive. Therefore, we recommend a contract lump-sum repair cost. This is more economical than to have the above-mentioned vehicle repaired on parts by/for parts basis. Invariably, the repairer has the prerogative/option for the recommended replacement parts to either be repaired or be replaced.

We have negotiated with the repairer and they have agreed to repair the above-mentioned vehicle for **SGD 10,100.00** NETT. Which, in our opinion is fair and reasonable.

The repairer has agreed to undertake the repairs to your requirement at the recommended contract lump-sum. However, we have not given any instruction and authorisation to the repairer to proceed with the repairs.

Under normal circumstances, the entire repair of the damaged vehicle should be completed within a reasonable period of **6 (Six)** days.

We are reverting the matter to you for a decision, and enclosed is our vehicle inspection report, appraisement schedule and invoice for services rendered.

Please do not hesitate to contact us if you have any queries on this matter.

Yours faithfully, United Appraisal & Management Pte Ltd



Ananda K. Biswas Marc Motor Vehicle Appraiser

Encls.:

The information contained in these document may be privileged and confidential, and is intended for the exclusive use of the addressee designation. If you are not the addressee, any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you received this document by error, please contact us immediately to arrange for its return.

Motor Vehicle Appraiser and Insurance Loss Adjuster No. 10 Kaki Bukit Ave 4 #06-75 Premier @ Kaki Bukit Singaore 415874 Handphone No.: +65 9146 1186 Email: united.appraisal@live.com.sg Business Registration Nos.: 200817301N

VEHICLE INSPECTION REPORT

To: Lin Jin Hui

Our ref.: UAM23.02.16-AK-STP-CHH-SLT7956Z

Date : 16 May 2023

REFERENCE

Assign by	:	Lin Jin Hui	Insured	:	To be advice
Assign on	:	21 Feb 2023	Policy no.	:	To be advice
Inspection on	:	21 Feb 2023	Claim no.	:	To be advice
Accident on	:	07 Feb 2023	Sum insured	:	To be advice
Workshop name	:	Car Hub Holdings Pte Ltd	Excess	:	Not applicable
Inspection at	:	143 Bukit Timah Road	3rd party Veh.	:	To be advice
		Shell Petrol Station (Shell Autoserv)	3rd party ins.	:	To be advice

Singapore 229843

PARTICULARS OF DAMAGED VEHICLE

Registration no. : SLT7956Z Odometer : 139629 km

Make / Model : Mercedes Benz GLC250 4matic Coupe Chassis no. : WDC2533462F313141 Regn. date : 13 Nov 2017 Engine no. **:** 27492031169655

: 1991 cc : Black

Body colour Engine cap.

PRE-ACCIDENT CONDITION OF VEHICLE (STATIC CHECK ONLY)

: In order Paintwork : Good Steering Footbrake : In order Undercarriage : Serviceable Handbrake : In order Gen. condition : Good


TYRE CONDITION ON VEHICLE

		Make	Size	Tread depth	Type of road wheel
Front N/S	:	Michelin	235/55R19	70%	Alloy
Front O/S	:	Michelin	235/55R19	70%	Alloy
Rear N/S	:	Michelin	255/50R19	70%	Alloy
Rear O/S	:	Michelin	255/50R19	70%	Alloy

NOTE: The above percentages represent the estimated remaining life of tyre threads.

^{*} Denotes damaged component/s

POINT OF IMPACT



SYNOPSIS OF DAMAGES RESULTANT FROM THE ACCIDENT

The impact of the collision has damaged / affected the n/s front fender, front door, wing mirror, rear door, rear fender and etc...

Please refer to Annex A (Appraisement Schedule) for a detailed account of the damages and photographs taken.

Note: Reinspection vehicle on 22 Feb 2023 for repair in progress.

RECOMMENDATION

The estimate cost of repair submitted by Messrs Car Hub Holdings Pte Ltd as per schedule attached has been revised and scrutinised, and in our opinion, we consider it to be fair and reasonable. The repairers have agreed to undertake the repairs to the owner's satisfaction at our revision. We have not authorised the repairs.

Our adjusted cost of repair is SGD 10,100.00 to carry out the repairs. Please refer to Annex A (Appraisement Schedule) for a detailed account of the cost estimates.

REMARKS

We have not authorised the repair. However, for information, under normal circumstances, the repair would takes approximately **6** (Six) working days to complete.

In accordance to your instruction, we have **NOT AUTHORISED** the repair to the damaged vehicle and the survey was conducted strictly on a "**WITHOUT PREJUDICE**" basis.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Appraisal Report, which includes evidence photographs.

Yours faithfully, United Appraisal & Management Pte Ltd



Ananda K. Biswas Marc Motor Vehicle Appraiser

APPRAISEMENT SCHEDULE

Annex A

Registration no.
Our reference : SLT7956Z

: UAM23.02.16-AK-STP-CHH-SLT7956Z

CAL	04	Down to divin	Condition /	Estimate by	Adjusted
S/N	Qty	Description	Remarks	Wshop SGD	Amt SGD
		LIST ITEMS			
			~	007.00	0.00
1	1	Front fender n/s	Serviceable	895.20	0.00
2	1	Front door n/s	Refer To Labour	0.00	0.00
3	1	Front door outer trim moulding upper n/s	Serviceable	274.00	0.00
4	1	Front door outer trim moulding lower n/s	Distorted	251.80	251.80
5	1	Wing mirror assy n/s	Damaged	1895.30	1895.30
6	1	Wing mirror outer cover n/s	Deep Grazed	320.00	320.00
7	1	Rear door n/s	Dented	2165.00	2165.00
8	1	Rear door applique trim n/s (black)	Bent	310.86	310.86
9	1	Rear door outer trim moulding lower n/s	Cut/Snapped	236.00	236.00
10	1	Rear door quarter glass n/s	Shattered	534.10	534.10
11	1	Rear door quarter glass trim moulding n/s	Deep Grazed	233.92	233.92
12	1	Rear fender n/s	Dented	3238.00	3238.00
13	1	Rear fender quarter glass n/s	Shattered	605.00	605.00
14	1	Rear fender quarter glass trim moulding n/s	Distorted	316.75	316.75
				11275.93	10106.73
			Less 0% / 10%	0.00	1010.67
				11275.93	9096.06
		SPECIAL NETT ITEMS			
1	1	Sundries	Nagaggawy	50.00	30.00
1	1		Necessary	45.00	45.00
2 3	1set	Front fender wheel arch garnish clips n/s	Necessary	65.00	65.00
	1set	Rear door trimboard clips n/s Rear door sealant n/s	Necessary	120.00	100.00
4 5	1		Necessary Necessary	45.00	45.00
	1	Rear fender wheel arch garnish clips n/s Rear fender inner trim clips n/s	Necessary	75.00	75.00
6 7	1 1	Rear fender quarter glass primer & cleaner n/s	Necessary	100.00	80.00
8	1	Rear fender quarter glass inner seal n/s	Necessary	100.00	80.00
9	1	Rear fender quarter glass sealant n/s	Necessary	80.00	60.00
9	1	Real lender quarter glass seafailt ii/s	recessary	680.00	580.00
		TOTAL		11955.93	9676.06
		TOTAL		11755.75	7070.00
		LABOUR & MISC CHARGES			
1		To dismantle / renew the accident damaged portion. To panel beating, reshape, straighten orientate and align repair / replacement parts.	SGD350.00/day	1400.00	1050.00
2		To disconnect rear wire harness of electrical component to facilitate repairs, reconnect and check functions including taillamp lighting.	I	100.00	80.00
3		To remove and refit interior upholstery to facilitate the repair.		200.00	180.00

APPRAISEMENT SCHEDULE

Annex A

Registration no.
Our reference : SLT7956Z


: UAM23.02.16-AK-STP-CHH-SLT7956Z

S/N	Qty	Description	Condition / Remarks	Estimate by Wshop SGD	Adjusted Amt SGD
4		To remove and refit n/s rear door component to repair n/s rear door, check and alignment.		180.00	150.00
5		To remove and refit n/s rear fender glass for replacement.		150.00	120.00
6		To apply undercoating on the accident repair and replaced panel for rust protection.		200.00	180.00
7		Supply spray paint material and necessary items to respray n/s front fender, front door, rear door, rear fender and other affected area / panel.	SGD300.00/pnl	1500.00	1200.00
		TOTAL		3730.00	2960.00
		Total Parts and Labour Cost of Repair Less (Lumpsum repair adjustment)		15685.93	12636.06 2536.06
Adjustment Parts and Labour Cost of Repair				10100.00	













































































































































SW - 1st Notice to Conduct Pre-Repair Survey - Your insured Policy number: SD22E00620/EPM/R2/E0; Our Ref: JP/SW/23/SLT 7956Z/CHH - Accident involving SLT 7956Z and an Excavator at Punggol Regional Sports Centre (construction site) on 07 February 2023

Motor Claims <motorclaims@kscgp.com>

Fri 10/02/2023 12:50

 $\label{thm:com.sg} \mbox{To: Work Shop Estimate (SG) $$<$workshopestimate@libertyinsurance.com.sg>$$$

Cc: jiapei < jiapei@kscgp.com>

Dear Sirs,

Please find enclosed the 1st Notice to Conduct Pre-Repair Survey for your attention/action.

Best Regards,
Sharon
For and on behalf of Ms Hue Jiapei
KSCGP Juris LLP
133 New Bridge Road
#17-03 Chinatown Point

Singapore 059413

Tel: 6538 3611 / DID: 3152 0985 / Fax: 6538 3708

Email: motorclaims@kscgp.com

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

RE: SW - 1st Notice to Conduct Pre-Repair Survey - Your insured Policy number: SD22E00620/EPM/R2/E0; Our Ref: JP/SW/23/SLT 7956Z/CHH - Accident involving SLT 7956Z and an Excavator at Punggol Regional Sports Centre (construction site) on 07 Febr...

Sahadevan, Thayalan <sahadevan.thayalan@libertyinsurance.com.sg>

Tue 14/02/2023 08:06

To: Work Shop Estimate (SG) <workshopestimate@libertyinsurance.com.sq>;Claims Admin (SG) <claims admin@libertyinsurance.com.sg>

Cc: jiapei <jiapei@kscgp.com>;Motor Claims <motorclaims@kscgp.com>

Hi

Thank you for your email.

Please take note this policy SD22E00620 is not extended to covers such incident.

Please inform TP's vehicle to liaise with the machine/excavator owner directly for further action.

Thank you

Thayalan Sahadevan

Claims

Liberty Insurance Pte Ltd 51 Club Street #03-00 Liberty House Singapore 069428 DID: (65) 6328 0775





PROUD PARTNER

From: Work Shop Estimate (SG) <workshopestimate@libertyinsurance.com.sg>

Sent: Monday, 13 February 2023 5:15 PM

To: Sahadevan, Thayalan <sahadevan.thayalan@libertyinsurance.com.sg>; Claims Admin (SG) <claims_admin@libertyinsurance.com.sg>

Cc: jiapei <jiapei@kscgp.com>; Motor Claims <motorclaims@kscgp.com>; Work Shop Estimate (SG)

<workshopestimate@libertyinsurance.com.sg>

Subject: RE: SW - 1st Notice to Conduct Pre-Repair Survey - Your insured Policy number: SD22E00620/EPM/R2/E0; Our Ref: JP/SW/23/SLT 7956Z/CHH - Accident involving SLT 7956Z and an Excavator at Punggol Regional Sports Centre (construction site) on 07 Febr...

Hi Thayalan

TP SLT7956Z claim against us Excavator - Policy No. SD22E00620 - kindly advise

Aside > Admin Team

No info in Workflow

Please register / upload & forward to the respective OIC.

Regards Workshop Estimate

From: Work Shop Estimate (SG) < <u>workshopestimate@libertyinsurance.com.sg</u>>

Sent: Friday, 10 February 2023 3:36 PM

To: Claims_Admin (SG) < claims_admin@libertyinsurance.com.sg>

Cc: Sahadevan, Thayalan <<u>sahadevan.thayalan@libertyinsurance.com.sg</u>>; Work Shop Estimate (SG)

<workshopestimate@libertyinsurance.com.sg>

Subject: RE: SW - 1st Notice to Conduct Pre-Repair Survey - Your insured Policy number:

SD22E00620/EPM/R2/E0; Our Ref: JP/SW/23/SLT 7956Z/CHH - Accident involving SLT 7956Z and an Excavator

at Punggol Regional Sports Centre (construction site) on 07 Febr...

Hi Jess

TP SLT7956Z claim against us Excavator - Policy No. SD22E00620

Regards

Workshop Estimate

From: Claims_Admin (SG) < claims_admin@libertyinsurance.com.sg>

Sent: Friday, 10 February 2023 3:23 PM

To: Work Shop Estimate (SG) < <u>workshopestimate@libertyinsurance.com.sg</u>>


Subject: FW: SW - 1st Notice to Conduct Pre-Repair Survey - Your insured Policy number:

SD22E00620/EPM/R2/E0; Our Ref: JP/SW/23/SLT 7956Z/CHH - Accident involving SLT 7956Z and an Excavator

at Punggol Regional Sports Centre (construction site) on 07 Febr...

Hi,

Please re-confirm as vehicle no. SLT 7956Z is not insured with Liberty. Under the attached GIA report shown as Income Insurance.



Liberty Insurance Pte Ltd

Registration no. 199002791D

51 Club Street #03-00 Liberty House Singapore 069428 Tel: (65) 6221 8611

The Schedule website: http://www.libertyinsurance.com.sg

				age	1 / 15
Class of Policy	CONTRACTOR'S PLANT & MACHIN	ERY	and the transfer of the		
Policy No.	SD22E00620 / EPM / R2 / E0	Account	TAN INSURANCE BE	ROKERS	S PTE LTC
Insured	KOH KOCK LEONG CONSTRUCTIO	N PTE. LTD.			
Address	24 TUAS AVENUE 2 SINGAPORE 639455				
Business/Occp	BUILDING MATERIAL SUPPLIER, MIXED CONSTRUCTION ACTIVITIES, GENERAL CONTRACTOR, IMPORTER & EXPORTER & SAND, MECHANICAL ENGINEERING WORKS, RENTAL & LEASING OF MACHINERIES / HEAVY MACHINERIES AND ALL OTHER BUSINESS RELATED				
Period of Insurance	From 01-MAY-2022 To 30-APR-2028 Any subsequent period for which the It and the Company shall agree to accep	nsured shall pay			
Gross Premium	SGD *******1,402.50				
Situation of Risks	ANYWHERE IN SINGAPORE INCLUDING OFFSHORE ISLAND, BUT EXCLUDING WATERBORNE RISKS AND ON BOARD VESSEL RISKS UNLESS STATED OTHERWISE OR INDICATED UNDER LIST ATTACHED			SE OR	

CONTRACTORS' PLANT & MACHINERY

LTD AS OWNER FTRR&I

ITEM	DESCRIPTION OF PROPERTY	SUM INSURED			
1	MACHINERIES - AS PER LIST ATTACHED	SGD *****510,000.00			
	INSURED; KOH KOCK LEONG CONSTRUCTION PTE LTD AS HIRER &/OR DBS BANK				

TOTAL SUM INSURED

SGD *****510,000.00

Excess

IT IS HEREBY DECLARED AND AGREED THAT THE INSURED SHALL BE RESPONSIBLE FOR THE FOLLOWING EXCESSES:

A) 5% OF LOSS, MINIMUM \$\$750.00 EACH & EVERY LOSS IN RESPECT OF ALL OTHER CLAIMS PER UNIT

B) 10% OF LOSS, MINIMUM S\$2,500.00 EACH & EVERY LOSS IN RESPECT OF FLOOD/WATER DAMAGE PER UNIT

SUBJECT TO THE FOLLOWING ENDORSEMENTS, WARRANTIES AND/OR CLAUSES PRINTED IN THIS POLICY OR ATTACHED HERETO:

AUTOMATIC REINSTATEMENT OF LOSS

In the event of loss the sum insured by this Policy will be automatically reinstated from the date of loss unless written notice is given to the contrary either by the Company or by the Insured and the Insured undertake to pay such necessary premiums as may be required for such reinstatement from that date.

COVER FOR EXTRA CHARGES FOR OVERTIME, NIGHT WORK, WORK ON PUBLIC HOLIDAYS, EXPRESS FREIGHT