

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
SOMPO INSURAN	CE SINGAPORE PL		Ref:	CS/SMO23001816/Kvy3e2	
50 RAFFLES PLAC SINGAPORE LANI	CE #03-03 D TOWERSINGAPORE 048623	J	Date:	22/03/2023	
		(Code:	SMO	
1. Policy Particulars :- THIRD PARTY CLAIM					
Insured Veh.	SJH 9707A	Veh. Inspected		SHD 6368J	
Policy No.		Coverage (\$)		0.00	
Claim No.	CMTD2300700/RUC	Excess (\$)		0.00	
Assign From	GRACE TEO	Assign Date		17/02/2023	
2. Vehicle Particulars & Condition					
Make & Model	TOYOTA PRIUS (A)	c.c		1798	
Engine No.	HIDDEN	Year of Reg.		2019	
Chassis No.	JTDKB3FU203089373	Colour		METALLIC BROWN	
Odometer	274470 KM	Steering		IN ORDER	
Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
General	GOOD				
3. Conditions of Tyres					
	Size	Make		Balance	
R/H Front Tyre	195/65 R15	FALKEN		5 mm	
L/H Front Tyre	195/65 R15	FALKEN		5 mm	
R/H Rear Tyre	195/65 R15	FALKEN		7 mm	
L/H Rear Tyre	195/65 R15	FALKEN		7 mm	
4. Description of Damages					
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
DAMAGES SEE DETAILS.					
5. General Information					
Accident Date	16/02/2023	Inspection Date)	17/02/2023	
Survey held at	strides automotive services pl.				
	60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705				
5a. Remarks					
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair					
ESTIMATED NOR	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. General Information Accident Date 16/02/2023 Inspection Date 17/02/2023 Survey held at STRIDES AUTOMOTIVE SERVICES PL. 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705 Ta. Remarks A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. B. Estimate Days of Repair					