



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	17/02/2023 11:15 (SGT)
Reported by	Driver
Date of Accident	16/02/2023 14:00 (SGT)
Exact Location of Accident	PIE, Singapore
Additional Location Information	PIE TOWARDS CHANGI AIRPORT , AFTER KIM KEAT EXIT
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD6368J
-----------------------------	----------

#### INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	Strides Taxi Pte Ltd
Company Reg No	1XXXXX369K
Email Address	AUTO-SVCS-TARC@SMRT.COM.SG
Mobile Phone No	(Phone) +65-68662671
Alternative Phone No	-

#### VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Prius
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1800

#### INSURANCE COMPANY

Name of Insurance Company	MS First Capital Insurance Ltd
Policy Number / Cover Note Number	D-22099115MFSH

#### DRIVER

Name of Driver	SIN WAI MENG
NRIC No	SXXXX991F
Date Of Birth	14/01/1960
Occupation	Outdoor



Date Of Driving Pass	19/07/1984
Driving experience	38 YEARS AND 7 MONTHS
Gender	Male
Mobile Number	(Phone) +65-68662672
Alt. Phone Number	-
Email Address	AUTO-SVCS-TARC@SMRT.COM.SG
Address	11
Address complement	-
Postcode	-
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	4
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	Yes
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

#### PASSENGER 1

Name	SUE
Gender	Female

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Woodlands East Neighbourhood Police Centre
Police Station Phone No	(Phone) +65-18007679999
Police Station Address	3 Woodlands Drive 63 Singapore 737890
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

REFER TO POLICE REPORT - T/20230216/2070

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJH9707A
-----------------------------	----------

Vehicle Manufacturer	Toyota
Vehicle Model	Prius
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	JENNIFER
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SBN9800B
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	WONG
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

#### DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	SLR9782E
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

#### INJURED PERSONS DETAILS

##### INJURED 1

Name of injured person	UNKNOWN
Gender	-
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SLR9782E
Were seat belts worn?	-



Was this injured conveyed to hospital by ambulance? Yes

INJURED 2

Name of injured person -  
Gender -  
Phone No -  
Address -  
Address Complement -  
Post Code -  
Approximate Age Years Old -  
Injuries Sustained -  
Injured person in which vehicle? -  
Were seat belts worn? -  
Was this injured conveyed to hospital by ambulance? No

INJURED 3

Name of injured person SIN WAI MENG  
Gender -  
Phone No -  
Address -  
Address Complement -  
Post Code -  
Approximate Age Years Old -  
Injuries Sustained -  
Injured person in which vehicle? SHD6368J  
Were seat belts worn? -  
Was this injured conveyed to hospital by ambulance? No

WITNESS DETAILS

WITNESS 1

Name SUE  
Phone -  
Email -

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reputate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

6. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the availing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

Actual Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

Sketch Plan

Taxi  
SHD 6348T

Honda  
SJH 9207A

Grab Car  
SLR 9702E

Re toward airport after exit km knot to payh

vJun2022

Describe Circumstance of the Accident

### Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Actual Driver's Signature (if driver is not the policyholder)  
/ Date & Time

Witnessed by Reporting Centre Personnel  
(Name as in NRIC/ID card)

229704

1



**SMRT Accident Vehicle Repair Estimates**

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63655592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 17/02/2023

User ID : BoonChewTay

**Section A - Accident Details**

Registration Number	SHD6368J
Case Reference Number	TAX/02/23/2033
Registration Date	26/12/2019
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	SIN WAI MENG
Type of Accident	Head to Rear
Accident Date and Time	16/2/2023 2:00 PM
Accident Reported Date and Time	16/2/2023 4:18 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24117650
Special Instruction to ARC, if any	TP/ REAR PORTION
Prepared Date and Time	17/2/2023 10:43 AM
Chassis Number	
Allegae	
Work Shop	
Repair Completion Date and Time	

**Section B - Summary of Repair Estimates**

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$0.00
Total Spray Cost	\$1,296.00	\$0.00
Total Spare Part Cost	\$5,184.70	\$0.00
Total Other Cost	\$500.00	\$0.00
<b>TOTAL COST</b>	<b>\$8,994.70</b>	<b>\$0.00</b>
Lump Sum Total	\$9,000.00	\$0.00
Number of Repair Days	6.0	2 days
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	17/02/2023 11:07 AM	
Signature	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Remarks		

**Section C - Quotation and Accident Invoice Details**

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

*Kenneth (LKK)*  
*LI Pump Repair*

*Not Authorised*

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



**SMRT Accident Vehicle Repair Estimates**

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated : 17/02/2023

User ID : BoonChewTay

**Section D - Details of Repair Estimates**

**Part 1 - Labour Works**

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
O REPAIR REAR PORTION	\$1,014.00 <i>200L</i>	
<b>total Labour</b>	<b>\$1,014.00</b>	

**Part 2 - Spray Painting & Panel Beating Related Works**


Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
O RESPRAY REAR BUMPER	\$378.00 <i>200L</i>	
O RESPRAY REAR PANEL	\$180.00 <i>X</i>	
O RESPRAY TAIL GATE	\$378.00 <i>X</i>	
O RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00 <i>150L</i>	
O RESPRAY REAR SPOILER	\$180.00 <i>X</i>	
<b>total Spray Painting &amp; Panel Beating</b>	<b>\$1,296.00</b>	

**Part 3 - Other Costs - Accident and Accident Repair Related Expense**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
O WASH AND VACUUM	\$60.00 <i>X</i>	
O CHECK WIRING AND SYSTEM FUNCTION	\$120.00 <i>20L</i>	
O APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00 <i>X</i>	
O TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00 <i>30L</i>	
O REPLACE SUNDRY PARTS	\$100.00 <i>X</i>	
<b>total Other Costs</b>	<b>\$500.00</b>	

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52023-47030	REAR BUMPER REINFORCEMENT	1.00	\$360.10	25.00	\$270.08	Replace	<i>By 2</i>
		52159-47927	COVER, RR BUMPER ASSY	1.00	\$525.40	25.00	\$394.05	Replace	<i>RI R X</i>
		52462-47130	PAD, RR BUMPER, RH & LH, 3	2.00	\$12.00	25.00	\$18.00	Replace	<i>nn X</i>
		52462-47030	PAD, RR BUMPER, RH & LH, 2	2.00	\$4.30	25.00	\$6.45	Replace	<i>nn X</i>
		52462-47020	PAD, RR BUMPER, RH & LH, 1	2.00	\$4.30	25.00	\$6.45	Replace	<i>nn X</i>
		52461-47070	PAD, RR BUMPER, CTR	3.00	\$12.00	25.00	\$27.00	Replace	<i>nn X</i>
		52191-47030	SEAL, RR BUMPER ARM, RH & LH	2.00	\$12.30	25.00	\$18.45	Replace	<i>nn X</i>
		52599-68030	STOPPER, RR BUMPER, RH & LH	2.00	\$4.80	25.00	\$7.20	Replace	<i>nn X</i>
		52575-47060	RETAINER, RR BUMPER, RH	1.00	\$143.60	25.00	\$107.70	Replace	<i>nn X</i>
		52576-47060	RETAINER, RR BUMPER, LH	1.00	\$143.60	25.00	\$107.70	Replace	<i>nn X</i>
		52591-47080	SEAL, RR BUMPER, RH	1.00	\$128.00	25.00	\$96.00	Replace	<i>nn X</i>
		52592-47080	SEAL, RR BUMPER, LH	1.00	\$128.00	25.00	\$96.00	Replace	<i>nn X</i>
		52161-16010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.80	25.00	\$36.00	Replace	<i>nn X</i>
		52453-47900	GUARD, RR BUMPER, LOWER	1.00	\$405.00	25.00	\$303.75	Replace	<i>nn/nn ✓</i>
		52169-47070	COVER, GUARD RR BUMPER LOWER	1.00	\$23.90	25.00	\$17.92	Replace	<i>nn X</i>
		81910-47030	REAR BUMPER REFLECTOR ASSY, REFLEX, RH	1.00	\$42.20	25.00	\$31.65	Replace	<i>nn X</i>
		81920-47030	REAR BUMPER REFLECTOR ASSY, REFLEX, LH	1.00	\$42.20	25.00	\$31.65	Replace	<i>nn X</i>





**SMRT Accident Vehicle Repair Estimates**

<b>SMRT Automotive Services Pte Ltd</b>	
60 Woodlands Industrial Park E4, Singapore 757705	
FAX Number : 6385592	
Estimator Telephone Number : 68662623	
Accident Reporting Number : 68662672	

Date Generated : 17/02/2023

User ID : BoonChewTay

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		9018906029	REAR BUMPER GROMMET SCREW	1.00	\$2.20	25.00	\$1.65	Replace	Sm X
		58398-47050	COVER, REAR FLOOR UNDER, RH	1.00	\$189.20	25.00	\$141.90	Replace	Sm X
		58399-47030	COVER, REAR FLOOR UNDER, LH	1.00	\$261.60	25.00	\$196.20	Replace	Sm X
		66259-47010	COVER, REAR FLOOR UNDER CENTER	1.00	\$249.10	25.00	\$186.83	Replace	Sm X
		81551-47481	LENS & BODY, REAR COMBINATION LAMP, RH	1.00	\$367.30	10.00	\$330.57	Replace	Sm X
		81561-47471	LENS & BODY, REAR COMBINATION LAMP, LH	1.00	\$367.30	10.00	\$330.57	Replace	Sm X
		81457-47020	LENS & BODY, REAR COMBINATION LAMP, NO.2 RH	1.00	\$282.70	10.00	\$254.43	Replace	Sm X
		81458-47020	LENS & BODY, REAR COMBINATION LAMP, NO.2 LH	1.00	\$282.70	10.00	\$254.43	Replace	Sm X
		81580-47070	LAMP ASSY, REAR, RH	1.00	\$317.80	10.00	\$286.02	Replace	Sm X
		81590-47070	LAMP ASSY, REAR, LH	1.00	\$317.80	10.00	\$286.02	Replace	Sm X
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Sm X
		89997-30100	ANTENNA, ELECTRICAL KEY	1.00	\$78.00	10.00	\$70.20	Replace	Sm X
		58307-47100	END PANEL SUB-ASSY, BODY LOWER BACK	1.00	\$707.10	25.00	\$530.33	Replace	Sm X
		67005-47530	TAIL GATE PANEL SUB-ASSY, BACK DOOR	1.00	\$1,238.40	25.00	\$928.80	Replace	Sm X
		76801-47170-A1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1.00	\$992.30	25.00	\$744.22	Replace	Sm X Repair
		75403-48010	EMBLEM SUB-ASSY REAR	1.00	\$77.40	25.00	\$58.05	Replace	Sm ✓
		75441-47220	NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR	1.00	\$59.10	25.00	\$44.33	Replace	Sm ✓
		75442-47200	NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR	1.00	\$59.10	25.00	\$44.33	Replace	Sm ✓
		76085-47916	SPOILER SUB-ASSY, REAR	1.00	\$1,704.20	25.00	\$1,278.15	Replace	Sm X
			STRIDES LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Sm ✓
			STICKER DECAL 65558888	1.00	\$21.60	0.00	\$21.60	Replace	Sm ✓
total					\$9,759.20		\$7,752.48		

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
total									