Our Job Ref No :			305541080 03.01.2023	_	ENGINEERING  ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969		
FIN	IALIZA	TION FORM				8546 8156	
То	: _		LKK		Fax	:	
Attn	1 7	G	UO QIANG				
Veh	nicle Re	g No. : SHI	D4266H		Date of Accident	27.12.2022	
The	survey	and estimates of	f the repairs of the a	above-mention	ed vehicle are a	s follows:-	
1.	The repair job shall bill to:		II to:	INCOME		PC7494G	
2.	The finalized amount shall be:						
	(a)	Spare Parts aft	er List discount				
	(b)	(b) Labour Charges (include advertisement stickers etc,if any)					
	Total for Part-By-Part Repair Cost						
	(c.)	Lumpsum Repa Total for Lumps Final Lumpsur	nir (if applicable) num repair cost after Less: 20% n Repair cost			\$800.00 \$800.00	
3. 4. 5.	We si withir	ated normal perional treat the about 17 working days	ove amount as Co s	rrect and Con	working days.  Firmed if there if  Ve confirm the elimination amount		
	Signat Name Tel Fax	: <u>LIM T S</u> : <u>6214839</u> : 6546815		_	signature :	GUO DIANG NAZ LKU 21(0212023	
				_			
For U		Jse Only tem	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks	
1. Rei	ntal Rat	te P/Day		YES			
		ome Paid	•••	N			
3. Sur	vey Fe	es		-			
5. Med	er, if ap	h Fee es (on behalf of oplicable)	\$7.49 /\$2.00	Y			
Remark	ks:						