| Date | _ | ef No : : | 305541080 03.01.2023 | _ | COMPORIDELGRO ENGINEERING ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969 Fax: 6546 6156 | | | | |
|--|-------------------------------------|---|-------------------------|-----------------------------------|--|---------------------------------|--|--|--|
| То | | | LKK | | | | | | |
| Attn | · - | | UO QIANG | | Fax | (; | | | |
| | | | 04266H | | loto of Assidas | . 07 40 0000 | | | |
| | | | | | Date of Acciden | | | | |
| The | survey | and estimates of | f the repairs of the a | above-mention | ed vehicle are a | as follows:- | | | |
| 1. | The | repair job shall bi | II to: | INCOME | *** | PC7494G | | | |
| 2. | The | finalized amount | shall be: | | | | | | |
| | (a) Spare Parts after List discount | | | | | | | | |
| | (b) | Labour Charge | s (include advertis | etc.if anv) | | | | | |
| | | Total for Part-By-Part Repair Cost | | | | | | | |
| | | | | | | | | | |
| | (c.) | Lumpsum Repa Total for Lumps | \$800.00 | | | | | | |
| | | Final Lumpsur | \$800.00 | | | | | | |
| 4 . 5 . | withi | hall treat the about 7 working day | S | , | firmed if there Ve confirm the inalized amoun | | | | |
| | Signat Name Tel Fax | *************************************** | | _ | ignature : lame : late : | GUO GIANG NAZ LKY 21(0212023 | | | |
| For Of | ficial (| Jse Only | | | | | | | |
| | *** | tem | Amount | Document Attached Yes or No | Confirm By (Signature) | Remarks | | | |
| 1. Rental Rate P/Day | | | | YES | | | | | |
| 2. Loss of Income Paid | | | > | N | | | | | |
| 3. Survey Fees | | | - | - | | | | | |
| LTA Search Fee Medical Fees (on behalf of driver, if applicable) Overrun | | | \$7.49 /\$2.00 | Y | | | | | |
| Remark | s: | | | | | | | | |

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

DATE:

29.12.2022

MODEL:

Hyundai loniq

VEHICLE NO .: SHD4266H

LKK-Guo Qiano

Effective Date: 1 Nov 2020

INSURANCE: INCOME

MVA: LIMTS

| 1 1 10 1 | \$ | 2.20 | \$ \$. \$ \$ \$ | 459.40 451.25 22.00 41.45 |
|-------------------|--------|------|--------------------|------------------------------------|
| 10 | \$ | 2.20 | \$ | 22.00 41.45 |
| | \$ | 2.20 | \$ | 41.45 |
| 1 | | | * | |
| | | | \$ | 974 10 |
| | l | | - | 017.10 |
| | 1 | | \$ | 194.82 |
| | | | \$ | 779.28 |
| 1 | | | \$ | 50.00 |
| | | | • | 400.00 |
| | | | | 300.00 |
| , | , | | | 120.00 |
| 1 | i i | | \ | 120.00 |
| | | | \$ | 820.00 |
| | | | \$ | 1,649.28 |
| | | | | \$ \$ \$ |

his is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Ways.

is hance notify

the Repairs of the toflowing:

- To resurvey before offer spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: