

(08/11/13) wef

ASS. REC. BY: *Marcus*

REF:

CS/EG1230182/493

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SMC 1625X*

at Workshop m/s *convergence*

of *6131622A*

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☐
N/S	O/S
☐	☐

Bal. or Market Value: *85k*

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: *3* days Res.: Yes or No

Lum Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

3186
Vehicle: IN / OUT

Date: _____ Person Contacted: *LTN 41930*

Veh No: *SMC 1625X* Yr Regn: *27/06/8*

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or *CA*

Make: *VOLVO S60 T2* c.c. *1498*

Colour: *Grey* A/C: Insured / Std / NI / NA

Sp. Reading: *103480* T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *YV1FS28LOJ 246893*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: *235-15-24*
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

62 TOYO / YOKO or

Front

R/Bal. *7* mm R/Bal. *7* mm

L/Bal. *7* mm L/Bal. *7* mm

D.O.A. *12/02/23* D.O.I. *22/02/23*

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt n/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1/3/23 1/5 @ 4600 in brand Jeremy (red @ 4126-70, 47%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: *3*

Resurvey No. of Trip: *1*

Survey Fee:

Transportation:

) \$ + RS, SI

) Photos

) Others

TOTAL

Report Format : *MEP-TP*

Lump Sum / I.B.I. (\$) *4600*

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

CONVERGENCE AUTOMOTIVE
39 WOODLANDS CLOSE, MEGA@WOODLANDS
#01-24 SINGAPORE 737856
TEL :69932080
ATT : JEREMY HP : 98888119

Estimate for SMC 1625X (VOLVO S60)

Not Authorised
22/2/23
4/54 4600/
3 days
Wuphi After up -

1PC	BONNET	<i>20/3uf</i>	\$2,480.00	
1PC	FRONT BUMPER	<i>Rept Cn7</i>	\$1,685.00	
1PC	FRONT BUMPER SIDE RETAINER N/S	<i>11</i>	\$145.00	X
1PC	FRONT BUMPER BEAM	<i>11</i>	\$980.00	X
1SET	FRONT BUMPER CLIPS	<i>11</i>	\$50.00	X
1PC	HEADLAMP N/S	<i>320</i>	\$1,473.00	
1PC	FRONT FENDER N/S	<i>R</i>	\$1,150.00	X
			\$7,963.00	
			LESS 10%	\$7,166.70

TO CHECK WIRING	\$50.00	<i>20</i>
TO SPRAY RUST PROOFING	<i>11</i>	\$50.00 X
TO REFILL AIR CON GAS	<i>11</i>	\$100.00 X
TO CONDUCT WHEEL ALIGNMENT	<i>11</i>	\$100.00 X
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$580.00	<i>280</i>
TO PUTTY & SPRAY PAINTING	\$680.00	<i>500</i>
TOTAL	\$8,726.70	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: