

REF: Smg

ASS. REC. BY:

REF:

CS/TMI23001854/Sqy3

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD/TP/WS/TP RES/OD RES/EVA/INV/INV  
 To Inspcd Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: TMI  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bol. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent? Yes or No  
 GIA / PR Sect: \_\_\_\_\_ Consistent? Yes or No  
 Est. Repairs: 3 days Res: Yes or No  
 Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN/OUT

Veh No: Shc 11975 Yr Regt: 07/01/2019  
 Type: M.Cur / M.Cycle / Bus / Van / Lorry / Truck / Prime Mover /  
 Truck / Trailer or  
 Make: Toyota Prius cc: 1798  
 Colour: Blue AC: Insured / Std / NA  
 Sp. Reading: 528493 T/Radio: Insured / Std / NA  
 Eng No: \_\_\_\_\_  
 C/Nr: 5TDK33FV 603077808  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Ins / Jer / Jammed / Leaked / Burnt or  
 Brake: Ins / Jer / Jammed / Leaked / Burnt or  
 Mod: Nil / S/Rim / STD / R/Rim, or

Tyre Size: F: 195/65R15  
 R: \_\_\_\_\_

BS / DUN / EDNOVA / GY / FS / LZA / M/C / OHTSU / PRI / SUMI /  
 TOYO / YOKO or WetLure

Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R/Bal: 5 mm R/Bal: 5 mm  
 L/Bal: 5 mm L/Bal: 5 mm  
 D.O.A. 17/2/23 D.O.I. 20/2/23 230

Survey held at Comfort

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Roof/Top or  
Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>L/S = 3350</u>
	<u>IREAN finalised LS \$3350, 3 days. (Red \$2142.16, 39%)</u>

Date/Time, File Pass to? ☐: Prell. Report

27/03 Typist ☐: Final Report

Date/Time, File Return to?

2)

Report Format: MER-TP

Lump Sum 4.45 3350

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐: Site Insp (\$ \_\_\_\_\_)  
☐: Interview (\$ \_\_\_\_\_)  
☐: Tech. Invs (\$ \_\_\_\_\_)  
☐: Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

\$ + RS: \$ \_\_\_\_\_

Photos:

Others:

TOTAL

**TP INSURER:** Tokio Marine Insurance Singapore Ltd (HQ)  
**CTPL**

Singapore

Loke Wei Yang

### PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	17/02/2023
Vehicle Reg. No.:	SHA1197J	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	TOYOTA PRIUS, 1.5 HYBRID (A)	Vehicle Reg. Date:	07/01/2019
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	2ZR2B84578	Chassis No:	JTDKB3FU603077808
Odometer:	528493 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Remarks:	TEL: 62148355		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	3,261.16
Miscellaneous Items	11.00
Labour	2,220.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>5,492.16</b>
<b>+ GST 8.00% (S\$)</b>	<b>439.37</b>
<b>Nett Amount (S\$)</b>	<b>5,931.53</b>

This claim is handled by: MS. LOKE YY

Generated using Merimen e-Claims Internet Estimation & Adjusting System



# COMFORTDELGRO ENGINEERING

A member of COMFORTDELGRO

ComfortDelgro Engineering Pte Ltd

205 Bras Basah Road Singapore 179701

Mainline • 65 6383 6295 Faxline • 65 6383 9155

Workshops

59 Loyang Drive Singapore 508665

383 Sin Ming Drive Singapore 575717

45 Pandan Road Singapore 605285

322 Ulu Road Singapore 103841

24 Serangoon Road Singapore 758155

1 Sungei Kadut Way Singapore 728791

501 Yehin Industrial Park A Singapore 708332

Date/Time: 18.02.2023 11:24

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5886401

JC NO305546024

STOMER

/MS COMFORT TRANSPORTATION PTE LTD

STOMER NO. 7010045

DRESS 383 SIN MING DRIVE  
Singapore SINGAPORE 575717

.. (R) 65508755

(O)

(P)

COUNT CARD NO.

REGN NO.:

SHA1197J

MILEAGE

MAKE:

TOYOTA

FUEL

E.....1/2.....F

MODEL

PRIUS HYBRID(G4)18.02.2023 09:05

DATE/TIME IN

YR OF MANU.

07.01.2019

TARGET DATE

CHASSIS CODE

JTDKB3FU603077808

COMPLETION DATE/TIME

## JOB DESCRIPTION


Accident Date: 17.02.2023

NATURE: 3P 17.02.2023

3/NO

LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Wedge Slip

No.: SHA1197J

YY

Exit Pass

Vehicle No.:

SHA1197J

of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard