

ASS. REC. BY:

REF:

LPC/230018631K

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

PC 12905

Yr Regn:

02 12

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

NS Caravan

c.c.

2853

Colour

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

174092

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

CWGE25 140429

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NIT / S/Rim / STD A/Rim or

Tyre Size:

F: Blackarrow

195R15X8

R: Salin

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

J

mm

Rear

R/Bal.

9

mm

L/Bal.

J

mm

L/Bal.

S

mm

D.O.A.

13/2/23

D.O.I.

21/2/2023

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

Fnt NS

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Time, File Pass to?

☐

Prell. Report

☐

Final Report

Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

S - RS. SI

F. P. S.

Others

ort Format :

p Sum / I.B.I. (\$

TOTAL