

RECEIVED: TEWA

REF: CC3/41823001902/Tuy3

ASSIGNMENT

From: _____ Date: _____
Estimated cost: _____
☒ TP / ☐ VS / ☐ RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV
To inspect vehicle No: _____
Workshop ID: _____
Insured: _____
Policy No: SP2003181425-01
Claims No: 202332005505
Sum Insured: _____ Excess: 600 ~~100~~
(Officer's Record)
Make of Veh: _____

(Policy Condition)
Remark: The vehicle had commenced its repair at the time of inspection.
Est. or Market Value: 4150K.
DAG Accident Form: _____ Consistent? : Yes or No
DIA / PR Sheet: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Turn Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: S1808CD Yr Regn: 2021, Nov.
Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /
Truck / Trailer or _____
Make: Volkswagen Passat C.D. 1984
Colour: Black A/C: ☐ Insured / ☐ Std / ☐ NI / ☐ NA
Sp Reading: 5281 T/Radiat: ☐ Insured / ☐ Std / ☐ NI / ☐ NA
Eng/Mod: _____
C/No: WVWZZZ3CZME033567
Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt
Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or
Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or
Mod: ☐ Nil / ☐ STD / ☐ STD A/Rin or
Tyre Size: R 215/55 R17
R 2 2
SS / DUN / ZANNOVA / BY HS / LZA / WIC / DHTSU / PR / BURN /
TOYO / YOKO or Continental
Front: _____ Rear: _____
R/Bel: 6 mm R/Bel: 6 mm
L/Bel: 6 mm L/Bel: 6 mm
D.O.A. 18/2/2023 D.O.L. 21/2/23
Survey held at VW Tuan
Des. of Damages: ☒ Fr / ☒ Rear / ☒ L / ☒ R / ☒ U/C / ☐ Roof or
The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|-------------|---|
| 3/4/23 | Final fig \$23,925.43 confirmed by email (Red 7368.20, 23%) |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |

Date/Time, File Pass to? ☐ : Prel. Report
Date/Time, File Return to? ☐ : Final Report
3/4/23-typist
Days Of Repair: 13
Resurvey No. of Trip: 1
Add Fee: ☐ : Site Insp ☐ :
☐ : Interview ☐ :
☐ : Tech. ☐ :
Survey Fee: ☐
Transportation: ☐
Merimen
\$23,925.43

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 1/4

Company
ALLIANZ
INSURANCE SINGAPORE PTE. LTD.
79 ROBINSON ROAD
#09-01
SINGAPORE 068897

Customer Details:
Mr
JEAN-DOMINIQUE
IERACI
9 SWETTENHAM ROAD
SINGAPORE 248092

Document no.
Document date 21-02-2023
Customer no. 5211052769
Customer GST-ID 201903913C
Dealer 30001
Job order number 2023004881/ 1
Job order date 20-02-2023
Service Advisor SHU SHI TANG

| License plate | Model code | First registration | VIN | Model | Mileage |
|---------------|------------|--------------------|-------------------|-------------------------------------|---------|
| S1808CD | CB23HZB0 | 25-11-2021 | VWVZZZ3CZME033567 | Passat Business 2.0 I TSI 140kW DSG | 34,013 |

| Position no. | Description | Quantity | Unit | Unit price excl. GST | Tax code | Total amount excl. GST | Total amount incl. GST |
|----------------|---|----------|------|-------------------------|----------|---------------------------|---------------------------|
| 9801B004 | B&P CHECK SHORT CIRCUIT / HARNESS REPAIR | | | | #6 | ✓ 200.00 | 216.00 |
| 9801B005 | B&P DIAGNOSIS AND PROGRAMMING | | | | #6 | ✓ 360.00 | 388.80 |
| 9801B002 | B&P LEAKED CHECK, VACUUM & REGAS R1234YF | | | | #6 | ? 560.00 | 604.80 |
| 9801B001 | TO ALIGN LED HEADLIGHT | | | | #6 | ✓ 100.00 | 108.00 |
| 9801B003 | B&P WHEEL ALIGNMENT | | | | #6 | ✓ 300.00 | 324.00 |
| 9801B001 | R&R RIM & BALANCE | | | | #6 | ✓ 100.00 | 108.00 |
| 3G0823031C | Hood | 1 | pcs. | 1,817.01 | 28.00% | #6 1,308.25 | 1,412.91 |
| 3G0807217ALGRU | Cover For Bumper Primed | 1 | pcs. | 1,888.89 | 28.00% | #6 1,360.00 | 1,468.80 |
| 3G0805903J 9B9 | Spoiler Satin Black | 1 | pcs. | 363.72 | 28.00% | #6 261.88 | 282.83 |
| 3G0807287L 9B9 | License Plate Bracket Sat | 1 | pcs. | 121.03 | 28.00% | #6 87.14 | 94.11 |
| N 0385494 | Rivet | 4 | pcs. | 0.48 | 28.00% | #6 1.38 | 1.49 |
| 3G0807109AH | Impact Beam REINFORCEMENT | 1 | pcs. | 1,030.25 | 28.00% | #6 741.78 | 801.12 |
| 3G0807251D | Foam Insert | 1 | pcs. | 142.13 | 28.00% | #6 102.33 | 110.52 |
| 3G0807651D | Cross Member | 1 | pcs. | 247.68 | 28.00% | #6 178.33 | 192.60 |
| N 90812302 | Pop-Rivet | 4 | pcs. | 1.54 | 28.00% | #6 4.44 | 4.80 |
| 3G0807177D | Guide Piece | 1 | pcs. | 67.53 | 28.00% | #6 48.62 | 52.51 |
| 3G0807178D | BUMPER INNER BRACKET LH | | | | | | |
| | Guide Piece | 1 | pcs. | 67.53 | 28.00% | #6 48.62 | 52.51 |
| 3G0807049B | BUMPER INNER BRACKET RH | | | | | | |
| | Guide Piece | 1 | pcs. | 67.53 | 28.00% | #6 48.62 | 52.51 |
| 3G0807050B | BUMPER SIDE BRACKET LH | | | | | | |
| | Guide Piece | 1 | pcs. | 67.53 | 28.00% | #6 48.62 | 52.51 |
| 3G0807571 | BUMPER SIDE BRACKET RH | | | | | | |
| | Guide Piece | 1 | pcs. | 135.22 | 28.00% | #6 97.36 | 105.15 |
| 3G0998493A | BUMPER CTR BRACKET | | | | | | |
| | 1 Set Sensor Brackets | 1 | pcs. | 53.33 | 28.00% | #6 38.40 | 41.47 |
| 5Q0919275B GRU | Sensor Primed | 4 | pcs. | 194.63 | 28.00% | #6 560.53 | 605.37 |
| 5Q0919133 9B9 | Seal Ring Satin Black | 4 | pcs. | 1.53 | 28.00% | #6 4.41 | 4.76 |
| 3G0853651DJBKZ | Radiator Grille Satin Bla | 1 | pcs. | 687.72 | 28.00% | #6 495.16 | 534.77 |
| 5H0853601D DPJ | Vw Sign Black/Bright Chro | 1 | pcs. | 142.15 | 28.00% | #6 102.35 | 110.54 |
| 3G0853677AA9B9 | Cooling Air Grill Satin B | 1 | pcs. | 205.17 | 28.00% | #6 147.72 | 159.54 |
| 3G0853551B 2ZZ | BUMPER CTR LOWER GRILLE | | | | | | |
| | Decorative Moulding Brigh | 1 | pcs. | 217.09 | 28.00% | #6 156.30 | 168.80 |
| 3G0853666K 9B9 | BUMPER CTR LOWER GRILLE CHROM | | | | | | |
| | Cooling Air Grill Satin B | 1 | pcs. | 135.40 | 28.00% | #6 97.49 | 105.29 |
| 3G0854322A 9B9 | RHS FOG LAMP GRILLE | | | | | | |
| | Cover Strip Satin Black | 1 | pcs. | 103.71 | 28.00% | #6 74.67 | 80.64 |
| 3G0853665K 9B9 | RHS FOG LAMP GRILLE LOWER TRIM | | | | | | |
| | Cooling Air Grill Satin B | 1 | pcs. | 136.72 | 28.00% | #6 98.44 | 106.32 |
| 3G0854321A 9B9 | LHS FOG LAMP GRILLE | | | | | | |
| | Cover Strip Satin Black | 1 | pcs. | 103.71 | 28.00% | #6 74.67 | 80.64 |
| | LHS FOG LAMP GRILLE LOWER TRIM | | | | | | |

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



SKODA

Commercial Vehicles

Quotation

Non binding - Preview

Page

2/4

Company

ALLIANZ
INSURANCE SINGAPORE PTE. LTD.
79 ROBINSON ROAD
#09-01
SINGAPORE 068897

Customer Details:

Mr
JEAN-DOMINIQUE
IERACI
9 SWETTENHAM ROAD
SINGAPORE 248092

Document no.

Document date 21-02-2023
Customer no. 5211052769
Customer GST-ID 201903913C
Dealer 30001
Job order number 2023004881/ 1
Job order date 20-02-2023
Service Advisor SHU SHI TANG

| | | | | | | | |
|---------------|---|--------------------|-------------------|-------------------------------------|-----------|---------------------------|---------------------------|
| License plate | Model code | First registration | VIN | Model | Mileage | | |
| S1808CD | CB23HZB0 | 25-11-2021 | WVWZZZ3CZME033567 | Passat Business 2.0 I TSI 140kW DSG | 34,013 | | |
| Position no. | Description | Quantity | Unit | Unit price excl. GST | Tax code | Total amount excl. GST | Total amount incl. GST |
| 3G2941035Q | Led Headlight LHS H/LAMP | 1 | pcs. <i>ent</i> | 2,700.13 | 28.00% #6 | 1,944.09 | 2,099.62 |
| 3G2941036Q | Led Headlight RHS H/LAMP | 1 | pcs. <i>ent</i> | 2,700.13 | 28.00% #6 | 1,944.09 | 2,099.62 |
| 3G0941699 | Halogen Fog Lights With S LHS FOG LAMP | 1 | pcs. <i>mi</i> | 401.82 | 28.00% #6 | 289.31 | 312.45 |
| 3G0941700 | Halogen Fog Lights With S RHS FOG LAMP | 1 | pcs. <i>X</i> | 401.82 | 28.00% #6 | 289.31 | 312.45 |
| 8Z0820535B | TEMP.SENS. | 1 | pcs. <i>di</i> | 46.12 | 28.00% #6 | 33.21 | 35.87 |
| 1S0820536 | Holder For Temperature Se | 1 | pcs. <i>de</i> | 3.90 | 28.00% #6 | 2.81 | 3.03 |
| 3G0805588AC | Lock Carrier With Mountin | 1 | pcs. <i>?</i> | 1,566.47 | 28.00% #6 | 1,127.86 | 1,218.09 |
| 3G0805569B | Support For Lock Carrier | 1 | pcs. <i>?</i> | 40.84 | 28.00% #6 | 29.40 | 31.75 |
| 3G0121284AA | Air Duct | 1 | pcs. <i>?</i> | 30.93 | 28.00% #6 | 22.27 | 24.05 |
| 3G0121283AA | AIR GUIDE RH | 1 | pcs. <i>?</i> | 30.93 | 28.00% #6 | 22.27 | 24.05 |
| G 0525421G | R1234yf Coolant | 100 | pcs. <i>?</i> | 0.62 | 28.00% #6 | 44.64 | 48.21 |
| G 055535M2 | Oil For Refrigerant Compr | 0.1 | pcs. <i>?</i> | 394.77 | 28.00% #6 | 28.42 | 30.69 |
| 3D0260749C | A/C OIL | 1 | pcs. <i>?</i> | 7.75 | 28.00% #6 | 5.58 | 6.03 |
| 4D0260749B | Seal Ring | 1 | pcs. <i>?</i> | 8.23 | 28.00% #6 | 5.93 | 6.40 |
| G 12E050A2 | Coolant 1B | 2 | pcs. <i>?</i> | 25.14 | 28.00% #6 | 36.20 | 39.10 |
| 5G0955453J | Wash Water Reservoir | 1 | pcs. <i>de</i> | 133.82 | 28.00% #6 | 96.35 | 104.06 |
| 43955465 | WIPER TANK | 1 | pcs. <i>ne</i> | 2.36 | 28.00% #6 | 1.70 | 1.84 |
| M0919376 | Gasket | 1 | pcs. <i>ne</i> | 33.24 | 28.00% #6 | 23.93 | 25.84 |
| M0919382 | Water Level Switch | 1 | pcs. <i>ne</i> | 15.25 | 28.00% #6 | 10.98 | 11.86 |
| 052184A2 | Seal Ring | 1 | pcs. <i>ne</i> | 22.22 | 28.00% #6 | 16.00 | 17.28 |
| G0805911AC | Windshield Cleaner Concen | 1 | pcs. <i>fu</i> | 179.80 | 28.00% #6 | 129.46 | 139.82 |
| G0805912T | Wheelhouse Liner | 1 | pcs. <i>X</i> | 179.80 | 28.00% #6 | 129.46 | 139.82 |
| Q0825235A | LHS FENDER LINER LOWER | 1 | pcs. <i>fu</i> | 237.93 | 28.00% #6 | 171.31 | 185.01 |
| Q0825201L | Sound Baffle | 1 | pcs. <i>fu</i> | 161.98 | 28.00% #6 | 116.63 | 125.96 |
| Q0825202K | ENGINE LOWER COVER | 1 | pcs. <i>fu</i> | 147.17 | 28.00% #6 | 105.96 | 114.44 |
| 0407117B | Underbody Lining | 1 | pcs. <i>cur</i> | 13.24 | 28.00% #6 | 9.53 | 10.29 |
| 0825267 | LHS | 1 | pcs. <i>ne</i> | 0.44 | 28.00% #6 | 0.63 | 0.68 |
| 0854327D 5AP | Underbody Lining | 1 | pcs. <i>ent</i> | 52.79 | 28.00% #6 | 38.01 | 41.05 |
| 0854328D 5AP | Rear Transverse Trim | 1 | pcs. <i>ent</i> | 52.79 | 28.00% #6 | 38.01 | 41.05 |
| | LHS LOWER ARM COVER | 1 | pcs. <i>ent</i> | 52.79 | 28.00% #6 | 38.01 | 41.05 |
| | Rivet | 2 | pcs. <i>ne</i> | 0.44 | 28.00% #6 | 0.63 | 0.68 |
| | Water Deflector Strip Bla | 1 | pcs. <i>ent</i> | 52.79 | 28.00% #6 | 38.01 | 41.05 |
| | LHS FRT W/SCREEN SIDE MLDG | 1 | pcs. <i>ent</i> | 52.79 | 28.00% #6 | 38.01 | 41.05 |
| | Water Deflector Strip Bla | 1 | pcs. <i>ent</i> | 52.79 | 28.00% #6 | 38.01 | 41.05 |
| | RHS FRT W/SCREEN SIDE MLDG | 1 | pcs. <i>ent</i> | 52.79 | 28.00% #6 | 38.01 | 41.05 |

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 3/4

Company
ALLIANZ
INSURANCE SINGAPORE PTE. LTD.
79 ROBINSON ROAD
#09-01
SINGAPORE 068897

Customer Details:
Mr
JEAN-DOMINIQUE
IERACI
9 SWETTENHAM ROAD
SINGAPORE 248092

Document no.
Document date 21-02-2023
Customer no. 5211052769
Customer GST-ID 201903913C
Dealer 30001
Job order number 2023004881/ 1
Job order date 20-02-2023
Service Advisor SHU SHI TANG

| License plate | Model code | First registration | VIN | Model | Mileage |
|---------------|------------|--------------------|-------------------|-------------------------------------|---------|
| S1808CD | CB23HZB0 | 25-11-2021 | VWVZZZ3CZME033567 | Passat Business 2.0 I TSI 140kW DSG | 34,013 |

| Position no. | Description | Quantity | Unit | Unit price excl. GST | Tax code | Total amount excl. GST | Total amount incl. GST |
|----------------|--------------------------------|----------|------|-------------------------|-----------|---------------------------|---------------------------|
| 3G2857507FJ9B9 | Rear View Mirror Housing LH | 1 | pcs. | 640.05 | 28.00% #6 | ent 460.84 | 497.71 |
| 3G0857521B | Mirror Glass | 1 | pcs. | 199.16 | 28.00% #6 | ? 143.40 | 154.87 |
| 3G0857537J GRU | Mirror Cap Primed | 1 | pcs. | 177.89 | 28.00% #6 | Ry 128.08 | 138.33 |
| 3G0837643A Z7Z | Cover Strip Aluminium-Glo | 1 | pcs. | 200.72 | 28.00% #6 | X 144.52 | 156.08 |
| 3G0837901AB041 | LHS FRT DOOR TOP MLDG CHROM | | | | | | |
| | Trim For Pillar B Black | 1 | pcs. | 154.78 | 28.00% #6 | ent 111.44 | 120.36 |
| | LHS FRT DOOR TRIM (BLACK) | | | | | | |
| 3G0839901T 041 | Trim For Door Window Fram | 1 | pcs. | 114.89 | 28.00% #6 | ent 82.72 | 89.34 |
| | LHS REAR DOOR TRIM (BLACK) | | | | | | |
| 3G0853267 GRU | Cover For Door Primed | 1 | pcs. | 89.89 | 28.00% #6 | ? 64.72 | 69.90 |
| | LHS FRT DOOR LOWER MLDG | | | | | | |
| 3G0853331B GRU | Decorative Moulding Prime | 1 | pcs. | 137.46 | 28.00% #6 | ? 98.97 | 106.89 |
| | LHS FRT DOOR LOWER MLDG TRIM | | | | | | |
| WHT009252 | Clip | 7 | pcs. | 0.56 | 28.00% #6 | ent 2.82 | 3.05 |
| 3G2857508FS9B9 | Rear View Mirror Housing RH | 1 | pcs. | 640.05 | 28.00% #6 | ent 460.84 | 497.71 |
| 3G0857538J GRU | Mirror Cap Primed | 1 | pcs. | 177.89 | 28.00% #6 | Ry 128.08 | 138.33 |
| 3G0857522B | Mirror Glass | 1 | pcs. | 789.79 | 28.00% #6 | ? 568.65 | 614.14 |
| 3G0837902AB041 | Trim For Pillar B Black | 1 | pcs. | 154.78 | 28.00% #6 | ent 111.44 | 120.36 |
| | RHS FRT DOOR TRIM | | | | | | |
| 3G0839902T 041 | Trim For Door Window Fram | 1 | pcs. | 114.89 | 28.00% #6 | ent 82.72 | 89.34 |
| | RHS REAR DOOR TRIM | | | | | | |
| 3G0853268 GRU | Cover For Door Primed | 1 | pcs. | 89.89 | 28.00% #6 | ent 64.72 | 69.90 |
| | RHS FRT DOOR LOWER MLDG | | | | | | |
| 3G0853332B GRU | Decorative Moulding Prime | 1 | pcs. | 137.46 | 28.00% #6 | ent 98.97 | 106.89 |
| | RHS REAR DOOR LOWER MLDG TRIM | | | | | | |
| WHT009252 | Clip | 7 | pcs. | 0.56 | 28.00% #6 | ent 2.82 | 3.05 |
| WHT009252 | Clip | 24 | pcs. | 0.56 | 28.00% #6 | ent 9.68 | 10.45 |
| | SIDE SKIRT CLIP | | | | | | |
| 3G0601025F FZZ | Alloy Wheel Aluminium Shi | 1 | pcs. | 1,802.73 | 28.00% #6 | ent 1,297.97 | 1,401.81 |
| | LHS FRT RIM | | | | | | |
| 311601361 | Rubber Valve | 1 | pcs. | 3.99 | 28.00% #6 | ent 2.87 | 3.10 |
| 3G0601025F FZZ | Alloy Wheel Aluminium Shi | 1 | pcs. | 1,802.73 | 28.00% #6 | ent 1,297.97 | 1,401.81 |
| | RHS FRT RIM | | | | | | |
| 311601361 | Rubber Valve | 1 | pcs. | 3.99 | 28.00% #6 | ent 2.87 | 3.10 |
| | LABOUR | 8 | pcs. | 560.00 | 28.00% #6 | 2240 4,480.00 | 4,838.40 |
| | SPRAY PAINT | 10 | pcs. | 530.00 | 28.00% #6 | 4770 5,300.00 | 5,724.00 |
| | FRT NUMBER PLATE | 1 | pcs. | 80.00 | 28.00% #6 | bt 80.00 | 86.40 |
| | Tyre CONT 215/55/17 CPC5 SEAL | 2 | pcs. | 720.00 | 28.00% #6 | ent 1,440.00 | 1,555.20 |
| | ALLIANZ OD CLAIM | | | | | | |
| | DOA: 18/02/2023 | | | | | | |
| | EXCESS: | | | | | | |
| | SURVEY BY: | | | | | | |

Quotation valid till 27-02-2023

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Company
ALLIANZ
INSURANCE SINGAPORE PTE. LTD.
79 ROBINSON ROAD
#09-01
SINGAPORE 068897

Customer Details:
Mr
JEAN-DOMINIQUE
IERACI
9 SWETTENHAM ROAD
SINGAPORE 248092

Page 4/4
Document no.
Document date 21-02-2023
Customer no. 5211052769
Customer GST-ID 201903913C
Dealer 30001
Job order number 2023004881/ 1
Job order date 20-02-2023
Service Advisor SHU SHI TANG

| | | | | | |
|---------------|------------|--------------------|-------------------|-------------------------------------|---------|
| License plate | Model code | First registration | VIN | Model | Mileage |
| S1808CD | CB23HZB0 | 25-11-2021 | WVWZZZ3CZME033567 | Passat Business 2.0 I TSI 140kW DSG | 34,013 |

| | | | | | | | | |
|----------|----------|-----------|-------------------|-------|----------|----------------|------------------------|------------------------|
| Tax Code | Labour | Material | Material Discount | GST % | GST | Total Discount | Total amount excl. GST | Total amount incl. GST |
| #6 | 1,620.00 | 29,567.97 | 7,104.21 | 8% | 2,495.04 | 7,104.21 | 31,187.97 | 33,683.01 |

Customer

Service Advisor

—VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).—

All invoices are denominated in SGD, unless otherwise stated.

Tanfah 1741579
Not otherwise
Ex: H6a 21/2/23 0240pm
P/I Resurvey before paint
tanfah@khando.com
13 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: