

(08/11/13) wef

ASS. REC. BY: RAH

REF:

CS3/HSB23001925/Rvp3

ASSIGNMENT

From:

Date:

Estimated Cost:

Veh No:

FBT 987AT

Yr Regn:

2022

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

YAMAHA AEROX GDR155A CVT

c.c 155

Colour

MULTI

A/C: Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MH3SG731000001292

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

100/80-14

R:

110/80-14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

MAXXIS

Front

Rear

R/Bal.

4

mm

R/Bal.

4

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

25/01/23

D.O.I.

22/02/23

Survey held at

ROCKET REMM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$15K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Date / Time Action / Instruction

REPAIR LIM IT

13/7/23 Submit prs, repair range \$2,000-\$3,000

Date/Time, File Pass to?

☐

Prell. Report

1)

☐

Final Report

Date/Time, File Return to?

2) 13/7/23-typist

Days Of Repair: 4

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

S + RS \$

Photos

Others

Report Format :

Lump Sum / I.B.I. (\$