

(08/11/13) Wof

ASS. REC. BY: Pam

REF:

6326

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SJX 886Rat Workshop m/s MOTOR IMAGEof 25, LENA WEB RDInsured: PRHO

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 116K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SJX 886R Yr Regn: 2019 16CTType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: SUBARU FORESTER 2.0I EYS ^{SR} c.c. 1995Colour: BLACK

A/C: Insured / Std / NI / NA

Sp. Reading: _____

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JF 18K 7KLSK 9013708

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orMod: NII / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 09/02/23D.O.I. 16/02/23

Survey held at

MOTOR IMAGE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S REAR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPORT LIAISON - 74K

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$

) \$ + RS \$

☐ : Interview (\$

) Photos

☐ : Tech. Invs (\$

) Others

Report Format :

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO :
REFERENCE : INS/IC/CHI/0052/2023
DATE : 10-FEB-2023

ERGO INSURANCE PTE LTD
8 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER THREE
S(038988)
TEL : 6829 9199/200
FAX : 6829 9248/49
MOTOR CLAIM DEPT

OWNER'S NAME : LIM WEE CHYE
ADDRESS : APT BLK 16 JALAN TENTERAM
#19-110
S(321016)
TELEPHONE NO : 96835275

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1900232347-03 AIG
VEHICLE NO : SJX886R
MODEL CODE : SK7AKFL
MODEL/YEAR : FORESTER 2.0I-S EYESIGHT AWD CVT
ENGINE NO : FB20YG71660
CHASSIS NO : JF1SK7KL5KG013708
MILEAGE : 1 KM
DATE IN : 10/02/2023
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : DENNIS LEONG JIA HUI
ACCIDENT DATE : 10/02/2023

Print Date : 10/02/2023
Print Time : 17:26:10

Auto &
190 Clem

AGE ENTERPRISES PTE. LTD.

6 KEE ROAD

ORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SJX886R

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM) AGAINST ERGO INS-SMN2163Y		
2	ZZ/001	DOA:09/FEB/2023 TIME:0720 HRS LOCATION:BUKIT TIMAH, NEAR ACS BAKER		
3	ZZ/002	REPLACE REAR RH QUARTER FENDER, REAR BUMPER <i>2600 x 3</i>	2800.00	<i>1800</i>
4	ZZ/003	RESPRAY REAR RH QUARTER FENDER, REAR BUMPER, REAR RH QUARTER FENDER INNER <i>2520 x 2</i>	2800.00	<i>1040</i>
5	ZZ/004	REMOVE & REFIX REAR BOOT GARNISH & TRIM TO FACILITATE REPAIR	150.00	<i>/</i>
6	ZZ/005	REMOVE & INSTALL REAR RH QUARTER GLASS	180.00	<i>/ 145</i>
7	ZZ/006	TO SUPPLY AND INSTALL REAR RH QUARTER GLASS SOLAR FILM	145.00	<i>/</i>
8	ZZ/007	TO REMOVE & REFIX FUEL TANK	200.00	<i>/ 150</i>
9	ZZ/008	TRANSFER REVERSE SENSOR (OLD TO NEW)	80.00	<i>/</i>
10	ZZ/009	TO INSTALL REAR BUMPER CARGO STEP PANEL	80.00	<i>/ 60</i>
11	ZZ/011	TRANSFER/BALANCE TYRE/RIM	50.00	<i>/ 25</i>
12	ZZ/012	4 WHEEL ALIGNMENT	200.00	<i>/</i>
13	ZZ/013	SUNDRIES	100.00	<i>/ 20</i>
14	ZZ/10	FAULT DIAGNOSTIC (RESET)	280.00	<i>/</i>
TOTAL LABOUR CHARGES			7065.00	

SERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJX886R

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			
		NETT	LIST	S/NETT	S/LIST REMARKS
1 TYRE VALVE <i>nm</i> ✓	23142GA040	8.50			
2 DISC WHEEL <i>sea</i> ✓	28111SJ070	1500.00			
3 PNL SD OUT QTR RPRH <i>bm</i> ✓	51439SJ0009P	778.90			
4 BUMPER FACE R HG <i>de</i> ✓	57704SJ310	495.80			
5 BRKT SD R RH <i>n</i> ✓	57707SJ320	14.80			
6 BRKT SD R LH <i>X</i>	57707SJ330	14.80			
7 BEAM COMPL R EU <i>X</i>	57711SJ0309P	259.00			
8 COVER HOOK R <i>X</i>	57731SJ300	11.10			
9 COVER SD LWR RH <i>X</i>	57731SJ360	17.80			
10 BUMPER GUARD R SP <i>X</i>	57734SJ301	222.00			
11 WDW GL ASSY R QTRRH <i>nm</i> / <i>photo</i>	65209SJ040	551.30			
12 DAM RUBBER <i>n</i> / <i>det</i>	65245SJ000	8.90			
13 GARNISH AY R QTR RH <i>de</i> ✓	91112SJ340	102.00			
14 CARGO STEP PNL RESIN <i>n</i> ✓	E7710SJ010	360.00			
SUB TOTAL		4344.90	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)		868.98	0.00	0.00	0.00
GRAND TOTAL		3475.92	0.00	0.00	0.00
OVERALL TOTAL		3475.92			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SJX886R

TOTAL LABOUR CHARGES	7065.00
TOTAL SPARE PARTS CHARGES	3475.92

GRAND TOTAL	10540.92 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	Rgsur - Hp 90010068
SURVEYED DATE	:	16/02/23 @ 1030
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00 5 days
LIABILITY	:	0.00
REMARKS	:	Resin before paint

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

633G

Vehicle Details

Vehicle No.:

SJX886R

Vehicle to be Exported:

No

Intended Deregistration Date:

19 Feb 2023

Vehicle Make:

SUBARU

Vehicle Model:

FORESTER 2.0I-S EYESIGHT AWD CVT SR

Primary Colour:

Grey

Manufacturing Year:

2019

Engine No.:

FB20YG71660

Chassis No.:

JF1SK7KL5KG013708

Maximum Power Output:

115.0 kW (154 bhp)

Open Market Value:

\$18,058.00

Original Registration Date:

18 Oct 2019

First Registration Date:

18 Oct 2019

Transfer Count:

0

Actual ARF Paid:

\$18,058.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

17 Oct 2029

PARF Rebate Amount:

\$13,543.00

Intended COE Rebate Details

COE Expiry Date:

17 Oct 2029

COE Category:

B - Car above 1600cc or 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$41,361.00

COE Rebate Amount:

\$27,544.00

Total Rebate Amount:

\$41,087.00

Subaru Forester 2.0i-S EyeSight Sunroof

Overview

[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)

Price **\$116,800**

Depreciation ⓘ **\$16,160 /yr**
[View models with similar depre](#)

Reg Date **19-Oct-2019**
(6yrs 7mths 29days COE left)

Mileage **43,000 km (12.9k /yr)**

Manufactured ⓘ **2019**

Road Tax ⓘ **\$1,208 /yr**

Transmission **Auto**

Dereg Value ⓘ **\$41,168 as of today (change)**

OMV ⓘ **\$18,130**

COE ⓘ **\$41,361**

ARF ⓘ **\$18,130**

Engine Cap **1,995 cc**

Power **115.0 kW (154 bhp)**

Curb Weight ⓘ **1,591 kg**

No. of Owners ⓘ **1**

Type of Vehicle **SUV**