

ASS. REC. BY:

REF:

A/G/ 23002003/164

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.: Yes or No

Lum Sum:

1. B1

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

3/3 @ 4722.40 Center

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Report Format :

Lump Sum / I.B.I.: (\$

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S - RS. \$

Fees

Others

TOTAL

Veh No:

SDW 8288R

Yr Regn:

08, 20

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

M. C180

c.c

1487

Colour

M. Grd

A/C:

Insured / Std / NI / NA

Sp. Reading

44980

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WDD 2050 762R 564126

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

R:

225/50R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

8

mm

Rear

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

19/2/23

D.O.I.

1/3/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S body

The UIC / Chassis frame / Body Structure affected due to collision.

Tropical Tech Automobile Services

BLK 5032 ANG MO KIO AVENUE 3 #01-303 INDUSTRIAL PARK 2 SINGAPORE 569535

TEL : 6481 7773 / 6481 1403 FAX : 6484 4978

E-mail : tsac303@singnet.com.sg

M/s : **AIG Asia Pacific Insurance Pte. Ltd**
78, Shenton Way,
#11-16, Singapore 079120

Attn : Motor Claims Department
Tel : 64193000
Fax : 62256772

Estimate bill : TT 12 / 23 / TP / WT

Registration No : SDW8288R

Make / model : MB C180 (205)

Mileage :

Date : 28 / 02 / 2023

TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO: GBC889M AND SDW8288R ALONG 35 HOUGANG AVENUE 3 SINGAPORE 538840 (JUNCTION ROAD OF HOUGANG AVENUE 3 & BARTLEY ROAD EAST ON 19 FEBRUARY 2023 AT ABOUT 1400HRS.

1pc	Front left door	1809	\$	1,916.00	✓
1pc	Front left door outer handle with chrome trimming	579	\$	634.00	✓
1pc	Front left door glass outer chrome trimming		\$	255.00	✓
1pc	Front left door wing mirror frame	1148	\$	1,508.00	✓
1pc	Front left door wing mirror cover		\$	267.00	X
1pc	Front left door pillar outer garnish		\$	238.00	✓
1pc	Front left door pillar chrome trimming		\$	409.00	X
1pc	Front left door pillar weather strip		\$	279.00	X
1pc	Front left door weather strip	207	\$	351.00	✓
1pc	Front left door inner lock		\$	477.00	X
1pc	Front left door hinge (Top)		\$	182.00	X
1pc	Front left door hinge (Bottom)		\$	172.00	X
	Sub total :		\$	6,688.00	
	Less 10% discount :		\$	668.80	
	A total :		\$	6,019.20	
	Diagnostic & reset front left power window.		\$	100.00	801
	Remove and refit front left door, front left door outer handle with chrome trimming, front left door glass outer chrome trimming, front left door wing mirror frame, front left door wing mirror cover, front left door pillar outer garnish, front left door pillar chrome trimming, front left door pillar weather strip, front left door weather strip, front left door inner lock, front left door hinge (Top), front left door hinge (Bottom).		\$	500.00	3001
	Under coating on front left damaged portion.		\$	200.00	301
	Putty / primer application, spray painting front left door, front left door outer handle, front left door side mirror cover, front left door hinge (Top), front left door hinge (Bottom), rear left door.		\$	800.00	5001
	Grand final amount :		\$	7,619.20	

Tropical Tech Automobile Services

(Authorised Signature)
William Tan

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 464J

Vehicle Details

Vehicle No.: SDW8288R
Vehicle to be Exported: No
Intended Deregistration Date: 23 Feb 2023
Vehicle Make: MERCEDES BENZ
Vehicle Model: C180 SEDAN AVG (R17 LED)
Primary Colour: Silver
Manufacturing Year: 2019
Engine No.: 26491530207516
Chassis No.: WDD2050762R564126
Maximum Power Output: 115.0 kW (154 bhp)
Open Market Value: \$34,981.00
Original Registration Date: 05 Aug 2020
First Registration Date: 05 Aug 2020
Transfer Count: 0
Actual ARF Paid: \$40,974.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 04 Aug 2030
PARF Rebate Amount: \$30,730.00

Intended COE Rebate Details

COE Expiry Date: 04 Aug 2030
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$35,001.00
COE Rebate Amount: \$26,071.00
Total Rebate Amount: \$56,801.00

The information contained herein is correct as at 23 Feb 2023

OK