

Our Job Ref No : 305545720 ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969 Fax: 6546 8156 Date 20/02/23 **FINALIZATION FORM** LKK Fax: Attn : Mr____ Irfan Vehicle Reg No. : SHD7241J 13.02.2023 The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-1. The repair job shall bill to: INCOME SNC3938T 2. The finalized amount shall be: Spare Parts after List discount (a) Labour Charges (b) Total for Part-By-Part Repair Cost \$0.00 22/03/22 double check with Irfan (c.) Lumpsum Repair (if applicable) Total for Lumpsum repair cost after Less: 20% \$2,200.00 2400 \$2,200.00 Final Lumpsum Repair cost Estimated normal period for repairs: 2 working days. 3. 4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days 5. Thank you for your assistance. We confirm the estimates and finalized amount Signature ____ Signature : : Ms. Loke YY Name Name Tel 62148355 Date 65468156 Fax For Official Use Only Document Confirm By Item Amount Attached Remarks (Signature) Yes or No 1. Rental Rate P/Day YES

NO

\$26.75 / \$2.00

2. Loss of Income Paid

5. Medical Fees (on behalf of driver, if applicable)

3. Survey Fees 4. LTA Search Fee

6 Overrun

Remarks: