

(08/11/13) wef

ASS. REC. BY: PmmREF: CS/EG1.23002029/Rvy3

9630

ASSIGNMENT

From: _____ Date: _____


Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SMT 5280Rat Workshop m/s PERFORMANCEof ALXAMARAInsured: eh1Policy No. DMPG22007271Claims No. CDMPG23000412Sum Insured: _____ Excess: THA 800

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 130K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Date / Time Action / Instruction

REPAIR LIMIT 79KVeh No: SMT 5280R Yr Regn: 2020 / JunType: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: B.M.W 118I HATCHLED HL c.c. 1499Colour RED A/C: Insured / Std / NI / NASp. Reading 34578 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBA 7K 320107F86478Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: NII / S/Rim / STD A/Rim orTyre Size: F: 225/45R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 19/02/23

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 23/02/23PERFORMANCE

The U/C / Chassis frame / Body Structure affected due to collision.

31/5/23 Final fig \$5487.60 confirmed by email (Red 9243.25, 62%)

Date/Time, File Pass to?

☐

Preli. Report

☐

Final Report

1)

Date/Time, File Return to?

2) 8/6/23-typist

Days Of Repair: 5

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$Report Format: Merimen

Lump Sum / I.B.I.: (\$ 5487.60)

To: Rasu



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|---------------------------------|-------------------------------------|
| Date of Submission | 20/02/2023 11:09 (SGT) |
| Reported by | Both Policyholder and Actual Driver |
| Date of Accident | 19/02/2023 13:15 (SGT) |
| Exact Location of Accident | Bishan Street 13, Singapore |
| Additional Location Information | - |
| Country/State of Loss | Singapore |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|-----------------------|
| Vehicle Registration Number | SMT5280R |
| INSURED/POLICYHOLDER | |
| Is company? | No |
| Name Of Registered Owner | HO YING CI |
| NRIC No | SXXXX963D |
| Email Address | yingci11@yahoo.com.sg |
| Mobile Phone No | (Phone) +65-96713438 |
| Alternative Phone No | - |

VEHICLE PARTICULARS

| | |
|--|-------------|
| Manufacturer | BMW |
| Model | 118i |
| Variant | - |
| Exact purpose for which vehicle was being used at time of accident | Private use |
| Are you claiming under your own insurance policy for repair to your vehicle? | Yes |
| Vehicle Category | Private car |
| Transmission | Auto |
| CC | 1499 |

INSURANCE COMPANY

| | |
|-----------------------------------|--------------------------|
| Name of Insurance Company | ERGO Insurance Pte. Ltd. |
| Policy Number / Cover Note Number | DMPG22007271 |

DRIVER

| | |
|----------------|------------|
| Name of Driver | HO YING CI |
| NRIC No | SXXXX963D |
| Date Of Birth | 14/11/1985 |
| Occupation | Indoor |

| | |
|--|-----------------------------|
| Date Of Driving Pass | 19/08/2005 |
| Driving experience | 17 YEARS AND 6 MONTHS |
| Gender | Female |
| Mobile Number | (Phone) +65-96713438 |
| Alt. Phone Number | - |
| Email Address | yingci11@yahoo.com.sg |
| Address | 263 RIVERVALLEY ROAD #10-21 |
| Address complement | - |
| Postcode | 238309 |
| Is the driver the policyholder? | Yes |
| If No, Relationship of the Driver with the Insured | - |
| Does Driver Own Other Vehicles? | No |
| Vehicle Registration Number of Other Vehicle Owned by Driver | - |
| Insurance Company of Other Vehicle Owned by Driver | - |

GENERAL INFORMATION OF THE ACCIDENT

| | |
|--------------------|----------------------------|
| Type of Accident | Collision - Major/Minor Rd |
| Weather Conditions | Clear |
| Road Surface | Dry |

OTHER INFORMATION

| | |
|---|-----|
| Was any foreign vehicle involved in the accident? | No |
| Number of vehicles involved in the accident | 2 |
| Was anybody injured in the Accident? | No |
| Was any injured conveyed to hospital by ambulance? | - |
| Was any other vehicle or property damaged? | Yes |
| Number of Passengers (Including Driver) | 1 |
| Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? | No |
| Translator's name | - |
| Translator's ID | - |
| Translator's phone number | - |
| Translator's email | - |
| Original language used in the statement | - |

DETAILS OF POLICE ACTION

| | |
|---|----|
| Was the accident reported to the police? | No |
| Was notice of intended Prosecution given? | No |
| If yes, against whom? | - |

CIRCUMSTANCES OF ACCIDENT

ON 19 FEBRUARY 2023 AT ABOUT 1315HRS I WAS DRIVING VEHICLE A SMT5280R ALONG BISHAN STREET 13. I WAS AT RIGHT LANE AS I TRAVELLING STRAIGHT SUDDENLY MY VEHICLE FRONT COLLIDED ONTO VEHICLE B SLF3503Y WHICH TURN OUT FROM BISHAN PLACE (MINOR ROAD) RIGHT PORTION. EXCHANGED PARTICULAR AND NO INJURIES AT POINT OF TIME

ATTACHMENT(S)

| | |
|---|-----|
| Are accident photos available for attachment? | Yes |
| Was there any video captured by Car Camera? | No |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-----------------------------|--------------|
| Vehicle Registration Number | SLF3503Y |
| Vehicle Manufacturer | - |
| Vehicle Model | - |
| Vehicle Variant | - |
| Vehicle Colour | - |
| Vehicle Category | Private hire |

| | |
|---|----------------------|
| Name of Driver | ANG SIOK POH |
| NRIC No | SXXXX908F |
| Contact Number | (Phone) +65-92710713 |
| Address | - |
| Address complement | - |
| Postcode | - |
| Insurance Company Name | - |
| Nature Of Damage | - |
| Details of property damaged in accident | - |
| No. Of Passenger (Including Driver) | 4 |

SKETCH PLAN**IMPORTANT NOTICE**

1. Please correctly report the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the center and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims.
 - (ii) investigating the accident and/or my claims.
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me.
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (Collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Sketch Plan

Driver's Signature (If driver is not the policyholder) / Date & Time

1700hrs 19 FEB 2023

Witnessed by Reporting Centre Personnel

FLASH ACCIDENT
REPORTING OFFICER

FRO BALAJI

A. SMT5280R
B. SLF3503Y

BISHAN STREET 13




Describe Circumstances of the Accident

ON 19 FEBRUARY 2023 AT ABOUT 1315HRS I WAS DRIVING VEHICLE A SMT5280R ALONG BISHAN STREET 13. I WAS AT RIGHT LANE AS I TRAVELLING STRAIGHT SUDDENLY MY VEHICLE FRONT COLLIDED ONTO VEHICLE B SLF3503Y WHICH TURN OUT FROM BISHAN PLACE (MINOR ROAD) RIGHT PORTION. EXCHANGED PARTICULAR AND NO INJURIES AT POINT OF TIME

Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

1700hrs 19 FEB 2023

FLASH ACCIDENT
REPORTING OFFICER

FRO BALAJI



Witnessed by Reporting Centre Personnel

Vehicle grounded since
w/2 level 3-4 Ramp.

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 65092
Date Estimated : 21/02/2023
Prepared By : Yap Mee Key

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Ho Ying Ci
263 River Valley Road
#10-21

Singapore 238309

- ACCOUNT - 136

Ergo Insurance Pte Ltd
8 Temasek Boulevard
#04-01 Suntec Tower 3
Singapore 038988

| REGN. NO. | CHASSIS NO. | REGN. DATE | MODEL | MILEAGE |
|-----------|-------------------|------------|-------|---------|
| SMT5280R | WBA7K320107F86478 | 26/06/2020 | 118i | 29437 |

DESCRIPTION

To replace front wall, front bumper and attachments.

To respray front bumper and affected are

To remove old PDC assembly, replace damaged parts and
reconnect to new bumper including conduct check for
proper function.

To check electrical.

To replace left headlamp.

To supply front emboss number plate. b/c

Sundries.

| VALUE |
|-------------------|
| 1275 850 2,125.00 |
| 986 1,038.00 |
| 168 177.00 |
| 168 177.00 |
| Xm? 481.00 |
| 83.00 |
| 80, ? 150.00 |

Total Labour 1: 4,231.00

DESCRIPTION

| DESCRIPTION | QTY | PRIC | VALUE |
|---|-----|--------|--------|
| C CLIP FOR PLASTIC NUT ? Xan | 20 | 1.10 | 22.00 |
| RADIATOR ? Xan | 1 | 905.05 | 905.05 |
| CHARGE AIR COOLER ? Xan | 1 | 610.35 | 610.35 |
| FRT BUMPER PANEL PRIMED (LINES PDC) scd | 1 | 950.80 | 950.80 |
| LH SIDE TRIM GRILLE (LUXURY) ? Xan | 1 | 139.60 | 139.60 |
| RH TRIM SIDE GRILLE (LUXURY) ca | 1 | 139.60 | 139.60 |
| RH FOG LAMP SUPPORT ? Xan | 1 | 76.10 | 76.10 |
| LH FOG LAMP SUPPORT ? Xan | 1 | 69.15 | 69.15 |
| LH GRID LATERAL (LUXURY/SPORT) ? Xan | 1 | 111.50 | 111.50 |
| RH GRID LATERAL (LUXURY/SPORT) scd | 1 | 111.50 | 111.50 |
| LH FOG LAMP COVER ? Xan | 1 | 41.75 | 41.75 |
| FRT BUMPER TOP CARRIER ? Xan | 1 | 412.80 | 412.80 |
| GRATE CENTRE CLOSED (SPORT) ca | 1 | 143.40 | 143.40 |
| FRT BUMPER PROTECTIVE STRIP CENTRE ? ca | 1 | 65.10 | 65.10 |
| COVER SENSOR ? scd | 1 | 58.40 | 58.40 |
| FRT BUMPER BOTTOM CARRIER ? st | 1 | 160.70 | 160.70 |

Performance Motors Limited

A Sime Darby Motors Company

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 65092
Date Estimated : 21/02/2023
Prepared By : Yap Mee Key

Page No. : 2 of 5

| REGN. NO. | CHASSIS NO. | REGN. DATE | MODEL | MILEAGE |
|-----------|-------------------|------------|-------|---------|
| SMT5280R | WBA7K320107F86478 | 26/06/2020 | 118i | 29437 |

| DESCRIPTION | QTY | PRIC | VALUE |
|--|-----|----------|----------|
| FRONT TOWING HITCH COVER <i>see X n</i> | 1 | 45.25 | 45.25 |
| SET MOUNTING PMA SENSOR <i>? X n</i> | 1 | 73.75 | 73.75 |
| SET MOUNTS PDC SENSOR <i>? X n</i> | 1 | 64.55 | 64.55 |
| FRT LH MOULDING (LUXURY) <i>? X n</i> | 1 | 133.00 | 133.00 |
| FRT RH MOULDING (LUXURY) <i>see</i> | 1 | 133.00 | 133.00 |
| FRT SHOCK ABSORBER <i>? X n</i> | 1 | 86.10 | 86.10 |
| FRT GRILLE (LUXURY) <i>see</i> | 1 | 710.05 | 710.05 |
| COVER FOR AIR DUCT <i>? X n</i> | 1 | 290.50 | 290.50 |
| GROMMET <i>? X n</i> | 1 | 0.80 | 0.80 |
| PLAQUE 74MM <i>? X n</i> | 1 | 72.85 | 72.85 |
| AIR DUCT TOP <i>? X n</i> | 1 | 105.45 | 105.45 |
| AIR DUCT BOTTOM <i>? X n</i> | 1 | 105.45 | 105.45 |
| AIR DUCT FRAME <i>? X n</i> | 1 | 195.05 | 195.05 |
| LH HEADLIGHT BI LED <i>? X n</i> | 1 | 2,471.05 | 2,471.05 |
| CONDENSER AIR CONDITIONING WITH DRI <i>? X n</i> | 1 | 1,063.00 | 1,063.00 |
| DECOUPLING RING <i>see X n</i> | 2 | 5.30 | 10.60 |
| Ultrasonic sensor <i>see X n</i> | 1 | 386.00 | 772.00 |

Total Parts : 10,350.25

3rd Party Insured losses / Direct Settlement

Claim No. _____

Excess S\$ TBA

Sign _____

Authorised Yes / No Yes

Time _____

Surveyor's Name _____

Surveyor's Email _____

No. of Working Days Recommend 3 days + 2 = 5 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance

Acknowledged by Repairer

Signature:

Date:

| | | |
|----------------|---|-----------|
| Labour 1 | : | 4,231.00 |
| Parts | : | 10,350.25 |
| Labour 2 | : | 0.00 |
| Excess | : | 0.00 |
| Total GST @ 8% | : | 1,166.50 |
| Grand Total | : | 15,747.75 |

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors

BMW Dealer



Supplementary

Estimate No. : b1 65092
Date Estimated : 21/02/2023
Prepared By : Yap Mee Key

Page No. :

- ESTIMATE REPAIR FOR -

Ho Ying Ci
263 River Valley Road
#10-21

Singapore 238309

- ACCOUNT - 136

Ergo Insurance Pte Ltd
8 Temasek Boulevard
#04-01 Suntec Tower 3
Singapore 038988

| REGN. NO. | CHASSIS NO. | REGN. DATE | MODEL | M LEAGE |
|-----------|-------------------|------------|-------|---------|
| SMT5280R | WBA7K320107F86478 | 26/06/2020 | 118i | 29437 |

| DESCRIPTION | ORIGINAL PRICE | DISC. % | NETT |
|--|----------------|---------|----------|
| ** To replace front bumper and attachments, top air duct, front grille, front RH moulding, bottom carrier, grate centre closed, RH grid lateral, RH trim side grille include carrying out necessary repairs caused by the accident | 1,275.00 | 0.00 | 1,275.00 |

| DESCRIPTION | UNIT PRICE | QTY | DISC. % | NETT |
|------------------------------------|------------|------|---------|-------|
| # SUPPORT NUMBER PLATE ECE cracked | 76.75 | 1.00 | 0.00 | 76.75 |
| # PLAQUE 82MM nec | 72.85 | 1.00 | 0.00 | 72.85 |

SUPPLEMENTARY ITEMS

| | |
|-------------------------------------|----------|
| Total Labour : | 1,275.00 |
| Total Parts : | 149.60 |
| Total Labour & Parts (before GST) : | 1,424.60 |

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269

Co Reg No. 197401559W

A Motors Company