

(08/11/13) wef

ASS. REC. BY: Pom

REF:

CS/661.23002029/RVY3

9630

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMT 5280Rat Workshop m/s PERFORMANCEof ALCANTARAInsured: ehi

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: THA

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 130K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMT 5280R Yr Regn: 2020 / JunType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: B.M.W 118I HATCHLED HL c.c. 1499Colour: RED A/C: Insured / Std / NI / NASp. Reading: 34578 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBA 7K 320107F86478Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/45R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 19/02/23

Survey held at

Des. of Damages: FR / Rear / O/S / N/S / U/C / Rooftop or

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 23/02/23PERFORMANCE

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 79K

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

) \$ + RS, SI

) Photos

) Others

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 65092**
Date Estimated : **21/02/2023**
Prepared By : **Yap Mee Key**

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Ho Ying Ci
263 River Valley Road
#10-21

Singapore 238309

- ACCOUNT - 136

Ergo Insurance Pte Ltd
8 Temasek Boulevard
#04-01 Suntec Tower 3
Singapore 038988

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMT5280R	WBA7K320107F86478	26/06/2020	118i	29437

DESCRIPTION

To replace front wall, front bumper and attacehments.

850 ~~2,125.00~~

To respray front bumper and affecetd are

986 ~~1,038.00~~

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.

168 ~~177.00~~

To check electrical.

168 ~~177.00~~

To replace left headlamp.

? 481.00

To supply front emboss number plate. *bl*

83.00

Sundries.

? 150.00

Total Labour 1: **4,231.00**

DESCRIPTION	QTY	PRIC	VALUE
C CLIP FOR PLASTIC NUT ?	20	1.10	22.00
RADIATOR ?	1	905.05	905.05
CHARGE AIR COOLER ?	1	610.35	610.35
FRT BUMPER PANEL PRIMED (LINES PDC/ <i>sea</i>)	1	950.80	950.80
LH SIDE TRIM GRILLE (LUXURY) ?	1	139.60	139.60
RH TRIM SIDE GRILLE (LUXURY) <i>ca</i>	1	139.60	139.60
RH FOG LAMP SUPPORT ?	1	76.10	76.10
LH FOG LAMP SUPPORT ?	1	69.15	69.15
LH GRID LATERAL (LUXURY/SPORT) ?	1	111.50	111.50
RH GRID LATERAL (LUXURY/SPORT) <i>sea</i>	1	111.50	111.50
LH FOG LAMP COVER <i>2?</i>	1	41.75	41.75
FRT BUMPER TOP CARRIER ?	1	412.80	412.80
GRATE CENTRE CLOSED (SPORT) <i>ca</i>	1	143.40	143.40
FRT BUMPER PROTECTIVE STRIP CENTRE ?	1	65.10	65.10
COVER SENSOR ?	1	58.40	58.40
FRT BUMPER BOTTOM CARRIER ?	1	160.70	160.70

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 65092
Date Estimated : 21/02/2023
Prepared By : Yap Mee Key

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMT5280R	WBA7K320107F86478	26/06/2020	118i	29437

DESCRIPTION	QTY	PRIC	VALUE
FRONT TOWING HITCH COVER <i>SEA</i>	1	45.25	45.25
SET MOUNTING PMA SENSOR ?	1	73.75	73.75
SET MOUNTS PDC SENSOR FRT ?	1	64.55	64.55
FRT LH MOULDING (LUXURY) ?	1	133.00	133.00
FRT RH MOULDING (LUXURY) <i>SEA</i>	1	133.00	133.00
FRT SHOCK ABSORBER ?	1	86.10	86.10
FRT GRILLE (LUXURY) <i>SEA</i>	1	710.05	710.05
COVER FOR AIR DUCT ?	1	290.50	290.50
GROMMET ?	1	0.80	0.80
PLAQUE 74MM ?	1	72.85	72.85
AIR DUCT TOP ?	1	105.45	105.45
AIR DUCT BOTTOM ?	1	105.45	105.45
AIR DUCT FRAME ?	1	195.05	195.05
LH HEADLIGHT BI LED ?	1	2,471.05	2,471.05
CONDENSER AIR CONDITIONING WITH DRI ?	1	1,063.00	1,063.00
DECOUPLING RING <i>SEA</i>	2	5.30	10.60
Ultrasonic sensor <i>SEA</i>	1	386.00	772.00
Total Parts :			10,350.25

3m 3m 3m Uninsured losses / Direct Settlement

Rep. No. _____ Claim No. _____

Date of Claim 23/02/23 @ 1600 Excess S\$ TBA

Surveyor Name Rosal Sign _____

Surveyor No. 90010618 Authorised Yes / No ☒ No

Time _____

RESURVEYED BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail _____

No. of Working Days Recommend 3 days

Reg before part REVERSE



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance

Acknowledged by Repairer
Signature:
Date:

Labour 1	:	4,231.00
Parts	:	10,350.25
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 8%	:	1,166.50
Grand Total	:	15,747.75

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	963D
Vehicle No.:	SMT5280R
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Feb 2023
Vehicle Make:	B.M.W.
Vehicle Model:	118i HATCH LED HL
Primary Colour:	Red
Manufacturing Year:	2020
Engine No.:	42125985B38A15A
Chassis No.:	WBA7K320107F86478
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$33,311.00
Original Registration Date:	26 Jun 2020
First Registration Date:	26 Jun 2020
Transfer Count:	0
Actual ARF Paid:	\$38,636.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Jun 2030
PARF Rebate Amount:	\$28,977.00
COE Expiry Date:	25 Jun 2030
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$32,500.00
COE Rebate Amount:	\$22,017.00
Total Rebate Amount:	\$50,994.00

The Information contained herein is correct as at 24 Feb 2023

OK

BMW 1 Series 118i 5DR

Overview

[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)

Price **\$124,888** [Get Pre-approved Loan.](#)

Depreciation ⓘ **\$15,240 /yr**
[View models with similar depre](#)

Reg Date **31-Jan-2020**
(6yrs 11mths 6days COE left)

Mileage **18,000 km (5.9k /yr)**

Manufactured ⓘ **2019**

Road Tax ⓘ **\$684 /yr**

Transmission **Auto**

Dereg Value ⓘ **\$54,957 as of today (change)**

OMV ⓘ **\$33,143**

COE ⓘ **\$37,705**

ARF ⓘ **\$38,401**

Engine Cap **1,499 cc**

Power **103.0 kW (138 bhp)**

Curb Weight ⓘ **1,320 kg**

No. of Owners ⓘ **1**

Type of Vehicle **Hatchback**