

305545726 Our Job Ref No 🙏 ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969 Fax: 6546 8156 Date 20/02/23 **FINALIZATION FORM** LKK Fax: Attn : Mr\_\_\_ Irfan Vehicle Reg No. : SHC2526B 14.02.2023 The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-INCOME FT6595J 1. The repair job shall bill to: 2. The finalized amount shall be: Spare Parts after List discount Labour Charges (b) Total for Part-By-Part Repair Cost \$0.00 (c.) Lumpsum Repair (if applicable) Total for Lumpsum repair cost after Less: 20% \$1,000.00 Final Lumpsum Repair cost \$1,000.00 3. Estimated normal period for repairs: 3 working days. 4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days 5. Thank you for your assistance. We confirm the estimates and finalized amount Signature : Signature: Name : Ms. Loke YY Name Tel £ 62148355 Date : 65468156

## For Official Use Only

Fax

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$26.75 / \$2.00			
5. Medical Fees (on behalf				
of driver, if applicable)				
6 Overrun				

Remarks	s:					