

ASS. REC. BY:

REF:

TJ / 23002038/KW

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$12K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: 04/24 Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

24/3 @ 9000 Carh @ 10 days (Red \$9,827.00/52%)

Veh No: STQ 5153B Yr Regn: 05, 09

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai A1 Avante c.c. 1591

Colour: M. Maroon A/C: Insured / Std / NI / NA

Sp. Reading: 367740 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMH DU 41BR 9U 758308

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 16/2/23

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

: Prel. Report

: Final Report

Date/Time, File Return to?

Days Of Repair: 10

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS. SI

Fines

Others

Add Fee: Site Insp (\$)

Interview (\$)

Tech Invs (\$)

Weekend (\$)

Report Format: 00

Lump Sum / I.B.I. (\$ 1/5 \$9000)

Estimate

DING AUTO PTE LTD 176, Sin Ming Dr, #04-06 Sin Ming AutoCare, Singapore, Singapore, Singapore - 575721. Contact: +65 9231 3123 Email: desmond@insurlogic.co	Proforma Invoice No:	Date: Feb 21 2023
	Ticket No: DAP-J000005	Vehicle No: SJQ5153B
	Engine No: G4FC9U653224	
Customer Name: Bizcar Pte Ltd Mobile No: +65 83337878 Address: BLK 875 #03-14 Location: TAMPINES ST 84 City: SINGAPORE	Vehicle: HYUNDAI ACCENT EXE ALPHA 2009 Kilometer: 367740 Color: RED Fuel: PETROL PH: +65 83337878 Email: bizcarsg@gmail.com	

#	Part Name	Description	Quantity	Unit Price	Taxable	Parts Total
1	FRT BUMPER	Part	1.00	330.00	330.00	Bu 330.00 ✓
2	FRT BUMPER RETAINER RH	Part	1.00	27.50	27.50	Diy 27.50 ✓
3	FRT BUMPER RETAINER LH	Part	1.00	27.50	27.50	Sm 27.50 X
4	FRT BUMPER FOAM	Part	1.00	132.00	132.00	CM 132.00 ✓
5	FRT BUMPER LOWER GARNISH	Part	1.00	143.00	143.00	Diy 143.00 ✓
6	BONNET/HOOD ASSY	Part	1.00	638.00	638.00	Bu 638.00 ✓
7	HINGE, BONNET/HOOD (RH)	Part	1.00	49.50	49.50	Diy 49.50 ✓
8	HINGE, BONNET/HOOD (LH)	Part	1.00	49.50	49.50	Diy 49.50 ✓
9	BONNET LOCK	Part	1.00	93.50	93.50	Bu 93.50 ✓
10	BONNET INSULATOR	Part	1.00	121.00	121.00	CM 121.00 ✓
11	BONNET STAND	Part	1.00	44.00	44.00	R 44.00 A
12	FRT GRILLE CHROME MLDG	Part	1.00	220.00	220.00	CM 220.00 ✓
13	FRT GRILLE BASE	Part	1.00	154.00	154.00	CM 154.00 ✓
14	FRT LOWER GRILLE	Part	1.00	110.00	110.00	Diy 110.00 ✓
15	FRT GRILLE CTR BRACKET	Part	1.00	44.00	44.00	R 44.00 X
16	GRILLE BADGE	Part	1.00	44.00	44.00	Diy 44.00 ✓
17	FRT SUPPORT PANEL CPL	Part	1.00	330.00	330.00	CM 330.00 ✓
18	FRT PANEL UPPER GARNISH	Part	1.00	99.00	99.00	CM 99.00 ✓
19	FRT FENDER LH	Part	1.00	264.00	264.00	Bu 264.00 ✓
20	FRT FENDER INNER COVER RH	Part	1.00	77.00	77.00	Sm 77.00 X
21	FRT FENDER INNER COVER LH	Part	1.00	77.00	77.00	R 77.00 A
22	FRT FENDER RH	Part	1.00	264.00	264.00	Bu 264.00 ✓
23	FRT DOOR LH	Part	1.00	715.00	715.00	R 715.00 A
24	WIPER COWL PANEL	Part	1.00	495.00	495.00	Sm 495.00 X
25	WIPER PANEL END GARNISH RH	Part	1.00	66.00	66.00	R 66.00 X
26	WIPER PANEL END GARNISH LH	Part	1.00	66.00	66.00	Sm 66.00 X
27	HEADLAMP ASSY RH	Part	1.00	462.00	462.00	CM 462.00 ✓
28	HEADLAMP ASSY LH	Part	1.00	462.00	462.00	Mg Bu 462.00 ✓
29	HEADLAMP BRACKET RH	Part	1.00	55.00	55.00	CM 55.00 ✓
30	HEADLAMP BRACKET LH	Part	1.00	55.00	55.00	CM 55.00 ✓
31	FOG LAMP COVER RH	Part	1.00	44.00	44.00	Diy 44.00 ✓
32	FOG LAMP COVER LH	Part	1.00	44.00	44.00	Sm 44.00 X
33	RADIATOR ASSY	Part	1.00	528.00	528.00	Bu 528.00 ✓
34	RADIATOR AIR GUIDE RH	Part	1.00	49.50	49.50	R 49.50 X
35	RADIATOR AIR GUIDE LH	Part	1.00	49.50	49.50	R 49.50 X
36	CONDENSOR ASSY	Part	1.00	506.00	506.00	Bu 506.00 ✓
37	FAN SHOURD	Part	1.00	214.50	214.50	CM 214.50 ✓
38	FAN MOTOR ASSY	Part	1.00	203.50	203.50	Sm 203.50 X
39	FAN BLADE	Part	1.00	82.50	82.50	Sm 82.50 X
40	A/C SUCTION HOSE	Part	1.00	181.50	181.50	Sm 181.50 X

#	Part Name	Description	Quantity	Unit Price	Taxable	Parts Total
41	A/C DISCHARGE HOSE	Part	1.00	209.00	209.00	Pen 209.00
42	WASHER TANK	Part	1.00	99.00	99.00	Pen 99.00
43	EXPANSION TANK	Part	1.00	93.50	93.50	CM 93.50
44	AIR FILTER HOUSING	Part	1.00	319.00	319.00	Pen 319.00
45	AIR FILTER DUCT	Part	1.00	82.50	82.50	CM 82.50
46	AIR FILTER HOSE	Part	1.00	71.50	71.50	Pen 71.50
47	HORN - HIGH PITCH	Part	1.00	66.00	66.00	Pen 66.00
48	ENGINE LOWER COVER	Part	1.00	165.00	165.00	Pen 165.00
49	PANEL ASSY, INSTRUMENT/DASHBOARD	Part	1.00	1,045.00	1,045.00	Tn 1,045.00
50	DRIVER AIRBAG	Part	1.00	1,595.00	1,595.00	Ar 1,595.00
51	PASSENGER AIRBAG	Part	1.00	1,738.00	1,738.00	L 1,738.00
52	AIRBAG ECU	Part	1.00	748.00	748.00	Ne 748.00
53	SEAT BELT ASSY RH	Part	1.00	935.00	935.00	Tn 935.00
54	SEAT BELT ASSY LH	Part	1.00	935.00	935.00	Tn 935.00
55	STEERING - COLUMN SPRING	Part	1.00	198.00	198.00	Ne 198.00
56	BODY REPAIR, PANEL BEAT & STRAIGHTEN/ALIGN - ACCIDENT AREA	Part	1.00	1,200.00	1,200.00	Foot 1,200.00
57	SPRAY PAINT - FRT BUMPER, BONNET, FRT FENDER X2, FRT DOOR X2 & SUPPORT PANEL	Part	1.00	1,400.00	1,400.00	1000l 1,400.00
58	REMOVE & REFIT - FRT DOOR COMPONENTS	Part	1.00	150.00	150.00	nn 150.00
59	REFILL - RADIATOR COOLANT	Part	1.00	80.00	80.00	50l 80.00
60	REFILL - AIR COND GAS	Part	1.00	80.00	80.00	80.00
						Taxable Value 18,827.00 Discount Total 0.00 Grand Total 18,827.00

Parts Total	18,827.00
Labour Total	0.00
GST Total	0.00
Grand Total	18,827.00
Balance	18,827.00

Customer / Authorized Signatory

Service Advisor Signature

Cashier / Authorized Signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	17/02/2023 18:03 (SGT)
Reported by	Driver
Date of Accident	16/02/2023 18:20 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	ECP NEAR BEDOK EXIT 7B
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJQ5153B
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	BIZCAR PTE LTD
Company Reg No	2XXXXX991Z
Email Address	BIZCARSG@GMAIL.COM
Mobile Phone No	(Phone) +65-83337878
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Hyundai
Model	Avante
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private hire
Transmission	Auto
CC	1591

INSURANCE COMPANY

Name of Insurance Company	India International Insurance Pte Ltd
Policy Number / Cover Note Number	D22MFL0008446

DRIVER

Name of Driver	MOHAMMED SHUKON BIN OMAR
NRIC No	SXXXX672D
Date Of Birth	27/01/1983
Occupation	Indoor

Date Of Driving Pass	09/10/2006
Driving experience	16 YEARS AND 4 MONTHS
Gender	Male
Mobile Number	(Phone) +65-87427895
Alt. Phone Number	-
Email Address	BUPUTYIN1983@GMAIL.COM
Address	BLK 875 TAMPINES STREET 84 #03-14
Address complement	-
Postcode	S520875
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
Yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLQ4227E
Vehicle Manufacturer	Mazda
Vehicle Model	3
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	MABEL
Contact Number	(Phone) +65-96971747

Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKB7321L
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	ARON
Contact Number	(Phone) +65-96774934
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



Sketch Plan



Describe Circumstances of the Accident 16/02/23 around 1620hrs

I was travelling at ECP on the 1st lane. Weather was clear. I was checking my rear mirror of left side mirror when to do a lane change and as I turn to look at the front, vehicle B was already doing jam brake.

I tried to brake but the car didn't manage to stop in time and I collided with SLQ4227E.

Declaration

I/We declare the foregoing particulars are true in every respect.



17/02/23

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	991Z
Vehicle Details	
Vehicle No.:	SJQ5153B
Vehicle to be Exported:	Yes
Intended Deregistration Date:	24 Feb 2023
Vehicle Make:	HYUNDAI
Vehicle Model:	HD AVANTE 1.6 A
Primary Colour:	Red
Manufacturing Year:	2009
Engine No.:	G4FC9U653224
Chassis No.:	KMH DU41BR9U758308
Maximum Power Output:	89.7 kW (120 bhp)
Open Market Value:	\$11,465.00
Original Registration Date:	15 May 2009
First Registration Date:	15 May 2009
Transfer Count:	2
Actual ARF Paid:	\$11,465.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Apr 2024
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$13,088.00
COE Rebate Amount:	\$3,097.00
Total Rebate Amount:	\$3,097.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 21 Feb 2023

OK