ASS. REC. DT.	200 5473 Ruy3
<u>A</u> :	SSIGNMENT
From: Date:	Veh No: Smm 45585 Yr Regn: 2019 The
Estimated Cost:	Type M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No: SMM 45585	Make: Toyoto Corolla BLAS 16th c.c 1598
	Colour WHITE A/C: Insured / Std / NI / N.
of 160,54 much DR #07-18/19	Sp.Reading 256131 T/Radio: Insured / Std / NI / N
Insured: XB 8413U LPC	Eng/No:
Policy No.	CINO: MROS3 REH 604598029
Claims No. 21/22/22/VC00/025905	Gen. Cond: Good / Fair/ Poor / Burnt
Sum Insured: Excess:	Steering: Iporder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: norder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / STRim / STD A/Rim or
	Tyre Size: F: 215/45ZR17
(Policy Condition)	R: A*
	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or 766819
Bal. or Market Value: 94K	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 6 mm R/Bal. 6 mr
GIA / PR Seen: Consistent? : Yes or No	L/Bal. C mm L/Bal. C mr
Est. Repairs: days Res.: Yes or No	D.O.A. 07/06/22 D.O.I. 09/06/22
Lum Sum: % 3 Val.: Yes or No	Survey held at AT PERFORMANCE
	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS Vehicle: IN / O	
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision
Date / Time Action / Instruction	
REPAIR LIMIT- SEK	
Briman DONNE NE DERAM	AD STORMA-GU-QU-) INC DOLLA
Collegie Bross of restable	NO. OT DAYS-(8K-9K)/14 days
13/6/22 Submit PRS	
24/3/23 Submit LS \$9500 (red 3750, 28%)
Date/Time, File Pass to? : Prell. Report	
	Days Of Repair: 14
: Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
. 13/6/22-typiet	
1 3/6/22-typist Add F 24/3/23-typist	
1 3/6/22-typist Add F 24/3/23-typist Report Format :	Site Insp (\$)S+RSSI

SS0222670009 / S & H Motor Pte Ltd ENTRY DATE & TIME: 07/06/2022 17:04 (SGT) SUBMITTED BY: Cynthia Myint Myint Than VERSION: 1 (07/06/2022 17:04 (SGT))

G SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- IMPORTANT NOTICE

 1. Please report <u>correctly</u> the details of the accident to speed up the claims process.

 2. This Form must be <u>completed by the Policyholder and/or the Authorised Driver</u>

 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 5. Any false reporting may be referred to the Police for investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	07/06/2022 17:04 (SGT)
Date of Accident	07/06/2022 14:56 (SGT)
Exact Location of Accident	Sin Ming Ave, Singapore
Additional Location Information	Sin Ming Avenue slip road Marymount road
Country/State of Loss	Singapore

Date of Accident	07/06/2022 14:56 (SGT)
Additional Location Information	Sin Ming Ave, Singapore Sin Ming Avenue slip road Marymount road
Country/State of Loss	Singapore
DETAILS OF	F OWN VEHICLE
Vehicle Registration Number	SMM4558J
INSURED/POLICYROLDER	
Is company?	Yes
Name Of Registered Owner	AL Autorent Pte Ltd
Company Reg No	201832693N
Email Address	operations@alautocar.sg
Mobile Phone No	(Phone) +65-88115335
Alternative Phone No	(Home) +65-88115335
VEHICLE PARTICULARS	
Manufacturer	Toyota
Model	altis
/ariant	
exact purpose for which vehicle was being used at time of	

Manufacturer	Tovota
Model	altis
Variant	L
Exact purpose for which vehicle was being used at time of	
accident	Employment
Are you claiming under your own insurance policy for repair to	
your vehicle?	No - Claiming third party
Vehicle Category	Private hire
Transmission	Auto
CC	1600

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5111765135-02-000005
Cover Note Number	

Name of Driver	Wong Teck Wai
NRIC No	S1792926G

	01/08/1967
ing Pass	Outdoor
erience	19/01/1990
# T 10 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	32 YEARS AND 5 MONTHS
iher	Male
Jumber	(Phone) +65-98553316
ione Number	
,il Address	operations@alautocar.sg
dress	Blk 219D Bedok Central #11-106
ddress complement	-
Postcode	464219
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	,,,,
Insurance Company of Other Vehicle Owned by Driver	
insulation company of other vehicle owned by briver	-
GENERAL INFORMATION OF THE ACCIDENT	
5.50 C41 444 (4.44 2.50 (4. High) 1 4 V V	
Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry
A PROJECTION OF THE PROJECT OF THE PROJECT OF	
OTHER INFORMATION	New Land Control of the Control of t
Mos any faraign values invalved in the assidents	****
Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	•
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s)	
soliciting/offering accident claims assistance?	No
DETAILS OF POLICE ACTION	
A THREE STATE OF THE CONTRACT COLUMN SEC. SAFE THE STATE OF THE STATE	
Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	<u>2</u> 7
A STATE OF THE STA	
CIRCUMSTANCES OF ACCIDENT	
CIRCUMSTANCES OF ACCIDENT Refer attached report	
Refer attached report	
Refer attached report	
Refer attached report ATTACHMENT(S) Are accident photos available for attachment?	Yes
Refer attached report ATTACHMENT(S) Are accident photos available for attachment? Was there any video captured by Car Camera?	Yes No
Refer attached report ATTACHMENT(S) Are accident photos available for attachment?	Yes
Refer attached report ATTACHMENT(S) Are accident photos available for attachment? Was there any video captured by Car Camera? Was there any audio recorded?	Yes No
Refer attached report ATTACHMENT(S) Are accident photos available for attachment? Was there any video captured by Car Camera? Was there any audio recorded?	Yes No No
ATTACHMENT(S) Are accident photos available for attachment? Was there any video captured by Car Camera? Was there any audio recorded? DETAILS OF OTHER	Yes No No
Refer attached report ATTACHMENT(S) Are accident photos available for attachment? Was there any video captured by Car Camera? Was there any audio recorded? DETAILS OF OTHER	Yes No No R VEHICLE PROPERTY 1
ATTACHMENT(S) Are accident photos available for attachment? Was there any video captured by Car Camera? Was there any audio recorded? DETAILS OF OTHER	Yes No No R VEHICLE PROPERTY 1 XB8413U
Refer attached report ATTACHMENT(S) Are accident photos available for attachment? Was there any video captured by Car Camera? Was there any audio recorded? DETAILS OF OTHER Vehicle Registration Number	Yes No No R VEHICLE PROPERTY 1 XB8413U
Refer attached report ATTACHMENT(S) Are accident photos available for attachment? Was there any video captured by Car Camera? Was there any audio recorded? DETAILS OF OTHER Vehicle Registration Number Vehicle Manufacturer Vehicle Model Vehicle Variant	Yes No No R VEHICLE PROPERTY 1 XB8413U
Refer attached report ATTACHMENT(S) Are accident photos available for attachment? Was there any video captured by Car Camera? Was there any audio recorded? DETAILS OF OTHER Vehicle Registration Number Vehicle Manufacturer Vehicle Model Vehicle Variant Vehicle Colour	Yes No No R VEHICLE PROPERTY 1 XB8413U UDTrucks
Refer attached report ATTACHMENT(S) Are accident photos available for attachment? Was there any video captured by Car Camera? Was there any audio recorded? DETAILS OF OTHER Vehicle Registration Number Vehicle Manufacturer Vehicle Model Vehicle Variant Vehicle Colour Vehicle Category	Yes No No R VEHICLE PROPERTY 1 XB8413U
Refer attached report ATTACHMENT(S) Are accident photos available for attachment? Was there any video captured by Car Camera? Was there any audio recorded? DETAILS OF OTHER Vehicle Registration Number Vehicle Manufacturer Vehicle Model Vehicle Variant Vehicle Colour Vehicle Category Name of Driver	Yes No No R VEHICLE PROPERTY 1 XB8413U UDTrucks
Refer attached report ATTACHMENT(S) Are accident photos available for attachment? Was there any video captured by Car Camera? Was there any audio recorded? DETAILS OF OTHER Wehicle Registration Number Wehicle Manufacturer Wehicle Wariant Wehicle Variant Wehicle Colour Wehicle Category Name of Driver Contact Number	Yes No No R VEHICLE PROPERTY 1 XB8413U UDTrucks
Refer attached report ATTACHMENT(S) Are accident photos available for attachment? Was there any video captured by Car Camera? Was there any audio recorded? DETAILS OF OTHER Wehicle Registration Number Wehicle Manufacturer Wehicle Wariant Wehicle Colour Wehicle Category Jame of Driver Contact Number	Yes No No R VEHICLE PROPERTY 1 XB8413U UDTrucks
Refer attached report ATTACHMENT(S) Are accident photos available for attachment? Was there any video captured by Car Camera? Was there any audio recorded? DETAILS OF OTHER Wehicle Registration Number Wehicle Manufacturer Wehicle Wariant Wehicle Variant Wehicle Colour Wehicle Category Name of Driver Contact Number	Yes No No R VEHICLE PROPERTY 1 XB8413U UDTrucks

mage openly damaged in accident senger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report gorractly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3, Information provided must be as truthful and accurate as possible. Any watul misrepresentation or withholding of material facts may
- 4. The issue and acceptance of this Form by insurence companies is not an admission of policy liability on the part of the insurance
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association
- of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the ladgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

lunderstand, acknowledge, agree and consent that :

- (a) My insurer , my w orkshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (at insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government sgency/authority (such as the police), for the purpose(s) of :
- (i) processing, hendling and/or dealing with my claims including the settlement of the claims and any necessary investigations reletting to
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mes packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third perty service provious or agents (including their law yers flaw firms), which may be sted outside of Singapore, for one or more of the above Purposes.

	14				
oscyholder's Signature / Data &	Driver's Signature (#	f driver is not the polic		nessed by Reporting C	ada
ketch Plan	11	1-1	Hen	onnel	
	->				100
MARYA	HOUNT RO	7			
		←	(A) S	18224 MM	
_	100		- (B)	MM4558I XB8413M.	
	CC = KBI			* e	
	The state of the s				
	Aulm Tring				
	अंग्रिसाहर्	1 1			

WHS TRAIGHTALL I	HORY SIN MING AUE SLIP RD T GIVE WAY TO TRAFFIC FROM MI TRUCK XB84BIM CAIME FROM SECTION	
etch way can 7	CHAIN MING AUR SUP RD	TO MARY MOUNT RI
CWEGGE LATER	WILL THE TEMPTIC FROM MI	ARYMOUNT RD.
TO MY CAR REAR	TRUCK XESTIM CAINE FROM	BEHAD AND HIT
10 WY CAR PERAR	SECTION	
		· · · · · · · · · · · · · · · · · · ·

	The state of the s	
Declaration		
	No 119 process Standards	
We declare the foregoing particulars	are true in every respect.	Å
SOUTH A	1	\\ \\
Santa Contraction of the Contrac		11/
** ** ********************************	UA.	Υ
		Witnessed by Reporting Centre

Policyholder's Signature / Date & Time

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	893N
/ehicle No.:	SMM4558J
/ehicle to be Exported:	No Laboratoria de la companya de la
ntended Deregistration Date:	10 Jun 2022
/ehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 ELEGANCE (AUTO)
Primary Colour:	White
Manufacturing Year:	2019
Engine No.:	1ZROD95733
Chassis No.:	MR053REH604598029
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$20,881.00
Original Registration Date:	28 Jun 2019
First Registration Date:	28 Jun 2019
Transfer Count:	
Actual ARF Paid:	\$21,234.00
PARF Eligibility:	Yes I have been a first to be
PARF Eligibility Expiry Date:	27 Jun 2029
PARF Rebate Amount:	\$15,925.00
COE Expiry Date:	27 Jun 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$26,999.00
COE Rebate Amount:	\$19.026.00
Total Rebate Amount:	\$34,951.00

The information contained herein is correct as at 10 Jun 2022

Toyota Corolla Altis 1.6A Elegance

Overview Fin	ancial Accessories	Similar Research	Photos Map
Price	\$94,700		
Depreciation (*)	\$12,030 /yr View models with similar depr	Reg Date	06-Jun-2019 (6yrs 11mths 26days COE left)
Mileage	44,600 km (14.8k /yr)	Manufactured	2019
Road Tax	\$742 /yr	Transmission	Auto
Dereg Value	\$36,313 as of today (change)	ОМУ	\$20,881
COE	\$29,159	ARF	\$21,234
Engine Cap	1,598 cc	Power	96.0 kW (128 bhp)
Curb Weight	1,230 kg	No. of Owners	
Type of Vehicle	Mid-Sized Sedan		